

**CODE COMPRESSOR AND CONNECTOR FRAMES  
AND SUBSCRIBER SENDER RECYCLE FRAME  
6-DIGIT TRANSLATION  
EQUIPMENT DESIGN REQUIREMENTS  
NO. 1 CROSSBAR AND PANEL SYSTEMS**

**1. GENERAL**

*Under J95111A*

**1.001** The addendum supplements Sections 815-220-150 and 816-551-150, Issue 3.

*Add:*

**1.002** The addendum is issued to provide information for the Automatic Trouble Analysis feature in No. 1 crossbar offices in accordance with SD-96528-01, Issue 9B.

*List 10*—Wiring and apparatus per SD-96528-01, Fig. 3, option T only, required in addition to list 1 in No. 1 crossbar offices to provide for the automatic trouble analysis feature. (See Note E.)

E. A 329A plug is required when the frame is equipped for the automatic trouble analysis feature and shall be specified as directed by the telephone company.

**4. EQUIPMENT**

*Under J95111M*

The following changes apply to Part 4 of the section:

*Add:*

(a) J95111A, List 10 and Note E—added

(b) J95111M, List 4—added

*List 4*—Wiring and apparatus per SD-96528-01, Fig. 7, required in addition to list 1 in No. 1 crossbar offices to provide for the automatic trouble analysis feature.

Bell Telephone Laboratories, Incorporated

Dept 5245

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement  
Printed in U.S.A.