

CONTROLLER TROUBLE INDICATOR FRAME EQUIPMENT DESIGN REQUIREMENTS NO. 1 CROSSBAR SYSTEM

1. GENERAL

1.001 This addendum supplements Section 816-620-150, Issue 5.

1.002 This addendum is issued:

(a) To add reference to coin service improvements (dial-tone-first) in list 1 and 18.

(b) To remove list 20 under J23251B per SD-25452-01, Issue 16D.

◆ (c) To provide information for the automatic trouble analysis feature in accordance with SD-25452-01, Issue 17D. ◆

4. EQUIPMENT

The following changes apply to Part 4 of the section:

◆ (a) J23251B, List 1—revised

(b) J23251B, List 18—revised ◆

(c) J23251B, List 20—removed

◆ (d) J23251B, Lists 21 and 22—added ◆

(e) J23251B, Note I—revised

◆ **Under J23251B**

Change: List 1

To Read:

Bell Telephone Laboratories, Incorporated

Dept 5245

WIRE EQUIP NOTES

Lamp Relay and Lamp
for Indicating
Rotary or TOUCH-
TONE® Dialed and/or
Coin Service
Improvement (Dial-
Tone-First) Calls,
Fig. 19

2

0

◆

Change: List 18

To Read:

List 18—Equipment per SD-25452-01, Fig. 19, RD and TD relays and lamps, required in addition to list 1 when associated subscriber sender link and controller arranged for TOUCH-TONE calling and/or coin service improvements (dial-tone-first) operation in partially converted offices.

Remove: List 20

◆ **Add:**

List 21—Wiring and equipment per SD-25452-01, Fig. 20 required in addition to list 1 when the automatic trouble analysis feature is provided.

List 22—Wiring and equipment per SD-25452-01, option F required in addition to list 21 when the frame operates with two marker groups ◆

Change: Note I

To Read:

I. Wiring and equipment per SD-25452-01, option K, is required with the first list 19.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement
Printed in U.S.A.