

FIRST CLASS MAIL

Installation Engineering Handbook 9
Western Electric
Columbus Works

UIS Section 390.5
1-15-82

URGENT INFORMATION SUPPLEMENT

711 CONNECTORIZATION OF THE NO. 5 CROSSBAR
LINK FRAME HORIZONTAL MULTIPLES
SENDING END

1. GENERAL

1.1 This UIS is issued to revise Paragraph 3.112.

2. INSTRUCTIONS

2.1 Revise Paragraph 3.112 to read as follows:

3.112 Cut the mult cable stitches between the uprights and sufficient breakouts on either side of the "U" (if not provided), to provide the necessary fanning slack and to balloon the wire bundles.

Manager, Product Engineering
Control Center

Printed in U.S.A.

NOTICE - NOT FOR USE OR DISCLOSURE OUTSIDE THE
BELL SYSTEM EXCEPT UNDER WRITTEN AGREEMENT