

POSTION INDICATOR CIRCUIT  
NO. 1 OFFICE

1. GENERAL

- 1.01 This addendum, which should be inserted in the binder in front of Section A230.318, is issued in order to make corrections in the section.
- 1.02 Paragraph 3.7 should be changed to read as follows:

3. METHOD

- 3.7 **B End.** Remove the cord from the emergency listening jack and restore the emergency key. The guard lamp should light.  
**A End.** The lamp in the first sub-group should be lighted and the lamps in the other sub-groups should be extinguished.