

BELL SYSTEM PRACTICES
Station Installation and Maintenance

ADDENDUM C64.258
Issue 1, July, 1954
AT&T Co Standard

COIN COLLECTORS
MULTISLOT TYPES
TESTS ON ROUTINE MAINTENANCE VISITS

1. GENERAL

1.01 This addendum supplements Section C64.258, Issue 1.
It is issued to change a tool number in paragraph 2.12.

2. GENERAL TESTS

2.12 **Trap and Vane Release** (5.02, 5.03): 147A gauge and a
KS-14995 coin collector tool. Both sides of relay. If ←
mechanism does not restore, clear:

- (a) Vane binding on bearings or on hopper wall.
- (b) Trap catching on vane or roller.
- (c) Fork binding on vane stem. Replace trap, relay, or
coin collector as required.