

37

COMMON SYSTEMS
OUTPUT PULSER CIRCUIT
AUTOMATIC NUMBER
IDENTIFICATION-TYPE B
CROSSBAR NO. 1, PANEL OR STEP-BY-STEP OFFICE

CHANGES

D. Description of Changes

D.1 A change is made to ensure that a CLI major alarm is brought in at the trouble ticketer only when the identifier indicates that a line identification has been made. Connections at contacts 7 and 7B of the IRL relay are reversed so that the make portion of the transfer may be used to ground the CLI alarm lead at contact 9(CLI). The former wiring is shown as option ZP which is replaced by option 19 when the CLI feature is provided. Direct ground which was shown at 9(CLI) is removed.

D.2 The above change is made without record per agreement with WE and applies only where Fig. 19 is provided.

BELL TELEPHONE LABORATORIES, INCORPORATED

DEPT 5223-JLB-MR