

CABLE SPLICING - GENERAL  
GENERAL RULES FOR MAKING A SPLICE

NOTES CONCERNING THIS ADDENDUM

This Addendum supplements Section G50.646.1 with additional information for inspection of the completed job.

The cross-reference "See Addendum" should be marked in Section G50.646.1 following Paragraph 7.01 to indicate the addition of new information.

8. COMPLETION OF WORK

8.01 Upon completion of the work inspect the job before leaving it to make sure that it has been done properly and that it is left in a neat and workmanlike condition. In the case of an underground job, inspect all existing cables in the manhole after completing the splicing work. Pay particular attention to the following:

- (a) Broken wiped joints
- (b) Cracked cable sheaths
- (c) Cable racking
- (d) Tagging
- (e) Bonding
- (f) Conditions which might result in future cable trouble

Repair all breaks found in the sheaths of cables in the manhole and make any other necessary repairs not requiring much additional time. Make a report to the supervisor of the repairs made and state whether any further work is necessary to put the cables in good condition. Leave the job in an orderly condition. Remove all wire clippings, pieces of paper and other scrap material.