

**BELL SYSTEM PRACTICES**  
**Outside Plant Construction**  
**and Maintenance**

**ERRATA SHEET**  
**G50.653.3**

## **CABLE SPLICING**

The following correction should be made in

**Section G50.653.3**, Issue 3, dated November 1950.

On page 5 in the first drawing, change 1½ in. scotch electric tape to read ½ in. scotch electrical tape.