

PRESSURE TESTING
RESIN PLUGS - SLEEVE INJECTION
LEAD CABLES OVER 5/8-INCH DIAMETER

NOTES CONCERNING THIS ADDENDUM

This addendum supplements Section G73.157.4 with additional instructions on locating plugs and correcting faulty plugs.

The following paragraphs should be marked "See Addendum" and treated as indicated.

Paragraph 2.05 - Supplemented
Paragraph 6.02 - Added

2. LOCATION OF PLUG

2.05 Due to possible future requirements for insulating joints in many central office vaults, plugs should not be located in the first two splicing bays from the duct entrance to these vaults.

6. CORRECTING FAULTY PLUGS

6.02 If after several attempts, it is found that the resistance of the original plugging compound makes repair of the plug impossible, a new plug may be constructed about 30 inches from the first plug or at another suitable location.