



REVISION	1	10-1-57
DATE	2	



NOTES:
 1. CSI & 2 CARD SUPPORT MAGNETS ARE ENERGIZED AT THIS TIME BUT DO NOT FUNCTION UNTIL THE FLUX OF THE LIFT MAGNETS HAS DECREASED.
 2. ONLY CODE BARS HAVE CODE BAR CATCHES
 3. ONLY ONE OF THE 38 CODE BAR RELAYS & MAGNETS (AO) IS SHOWN.

SKETCH OF CARD TRANSLATOR OPERATION