









128B2 SET







BELL SYSTEM PRACTICES
Teletypewriter and Data Stations

SECTION P90.511
Issue 6, November, 1958
AT&TCo Standard

PLANS USED	




TEST EQPT. AT EMERGENCY TABLE
FIG. 2



REGULAR OR EMERGENCY TTY
FIG. 3

NOTES:

- SOME 128B2 SUBSCRIBER SETS ARE NOT EQUIPPED WITH THE (AT) RESISTANCE, AND WHEN A POWER CORD IS CONNECTED TO TERMINAL 12, A CHECK SHOULD BE MADE TO INSURE THAT RESISTANCE (AT) IS PRESENT.



STATION IDENTIFICATION

15 TTY — 15N TABLE
TWP SERVICE — 128B2 TTY SUB SET
TWO LOOP OPERATION — MAGNET RECEIVING

FIG. J

NO EMERGENCY IS USED
FIG. 5