7 1/8

10 1/4



NOTES:

1. ALL KS-19594 DIALERS REPAIRED PER BSRS 451.919 SHALL CONFORM TO THIS DRAWING.
2. SOME RELAYS MANUFACTURED BY GRIGSBY-BARTON, INC. HAVE K501 AND K502 CONTACTS CONNECTED INTERNALLY (ONLY HAVE A SINGLE RED AND A SINGLE GREEN EXTERNAL LEAD). REPLACE THESE RELAYS WITH A TYPE WHICH HAS INDIVIDUAL CONTACT LEADS AS SHOWN ABOVE

ENGR HWE 8/2/68	ISSUE 1	ADDED NOTES #1 & #2.	OLS 12-17-68 ISSUE 2
DRAWN OLS 8/2/68			

DWG: KS-19594 DIALER ADDITION OF CURRENT LIMITING RESISTOR

SCALE

WESTERN ELECTRIC COMPANY, INC.
ENGINEER OF MANUFACTURE

BELL TELEPHONE LABORATORIES
INCORPORATED

USED ON

CDS L-107098 A-

SHEET 1

NO. OF SHEETS PER SET SEE SHEET 1

59617

MD 604-A (12-64) PRINTED IN U.S.A.

1S