Viking Subscriber Software 20.1 Point 2 Release

Release: August 4, 2020

FSN-0820-VIKING-16

This Field Software Notice (FSN) announces the KENWOOD Viking® subscriber software version 20.1 Point 2 release.   This release is a minor Armada update to resolve limited scope issues.

Software Versions

The following table capture the Viking Software items and corresponding versions included in this release.

Item	Version
Armada	1.30.11

This release of Armada corrects two minor issues.

1. When attempting to apply a filter to the codeplug list on the label column, an error may pop-up. Version 1.30.11 of Armada corrects this error.

2. If Keypad Lockout is programmed to a toggle on a portable with Lock Toggle Control under the Keypad Lockout settings, Armada may show the configuration as un-writeable. Version 1.30.11 of Armada corrects this error and now provides additional clarity on allowable programming.

If you are experiencing either of these issues, we recommend upgrading your Armada client to this latest release.

For questions regarding this Field Service Bulletin, please contact the KENWOOD Viking team at 1.800.328.3911, option 3.

EF Johnson Technologies, Inc. | a JVCKENWOOD Company
1440 Corporate Drive, Irving, TX 75038