CLPe CPS RELEASE NOTES

SOFTWARE
NA CPS_R09.07
EMEA CPS_R07.04

Model Number
CLP1080e, CLP446e

CPS Release
1. To address factory (BG Tech) wrong serial number issue by using invalid 'O' serial number SOP, causing customers not able to read CLPe radio configurations with the CPS due to the invalid serial number.