Professional Series
Mobile Firmware UpgradeKit R05.08.05
Customer Release Notes

NOTE: Professional CPS R06.11.05 or later is recommended to be used with this firmware.

This release of radio firmware supports ALL models/bands of the Professional Series Mobile Radios. For any questions, please contact Customer Resources at 1-800-927-2744.

I.   Enhancements

> **None**

II.   Corrections

Item #1: Voice Storage Fails to Record in Silent Answer Mode

While in Silent Answer Mode the voice storage feature will stop recording after carrier is dropped even if the carrier reappears within the VS Debounce Timer.

Item #2: MDC ID of Radio Not Displayed When Using a Repeater

While using MDC Post PTT ID in conjunction with a repeater, the first keying radio's MDC ID is not displayed when a second radio keys during the repeater hang time.

III.   Known Issues

> **None**