Motorola Solutions, Inc.

Commercial VX-2200
Global Release Notes

Issue Date: 24 Sep 2018

What's new in the Release

This release notes is to address the fix of an issue impacting VX-2200 radio.

Theres is no firmware or customer programing software (CPS) change, the fix is implemented to factory programming software tool that flash codeplug to the radio. New radios produced after 13 July 2018 has the fix.

Product Version

Listed below is Product type with a reference to the released version of software:

Product	Version Supported in Release
Firmware VX-2200	V2.14 (no change)
CPS CE82 (VX-2200)	5.01 (no change)

Resolved issue

 Product: VX-2200

Description: VX-2200 switches to "set scan". When you press the "scan" button that is programmed. The radio displays "SCAN". If you press it again the radio displays "DELETE".

Root cause: Incorrect tag is set in the initial data used at the factory.

Resolution: Provide update tool to update the fixed tag data. Tool can be found on Motorola Online Using the following path: **Resource Center>Software> Two-Way >VX/EVX Series Portables & Mobiles >VX-2100/2200**