EQUIPMENT TEST LIST

B.S.P.	ISS	TEST OR REQT.	EQUIPMENT AND WORK DESCRIPTION	CLASS	FREQ.	JOB NO.
226-588-500	3		TRK TRMSN TSTS — WITHOUT MAN. OGT TST FRAME			
(Page 3)	*A*		*One-Way 1000-Hz Loss to 102 Type Test Line*	*MW*	*	
	B		*Message Cct Noise Meas to 100 Type Test Line*	*MW*	*	
	C		*Impulse Noise Meas to 100-Type Test Line*	*MW*	*	
	D		*Two-Way 1000-Hz & Noise Tst to 104 Test Line*	*MW*	*	
	E		*Two-Way 1000-Hz Loss Meas to Lp-Around Tst Line*	*MW*	*	
	AA		*Two-Way 1000-Hz Loss to 101 Test Line — Orig End*	*MW*	*	
	AB		*Two-Way Freq Response to 101 Test Line — Orig End*	*MW*	*	
	AC		*Message Cct Noise Meas to 101 Test Line — Orig End*	*MW*	*	
	AD		*Impulse Noise Meas to 101 Test Line — Orig End*	*MW*	*	
	AE		*Two-Way PAR Meas to 101 Test Line — Orig End*	*MW*	*	

Instructions: See Section 226-001-011, Par. 3.02 and 3.03