LINE INSULATION TEST CIRCUIT (SD-2H142)

TESTS AND ADJUSTMENTS

NO. 2 AND NO. 2B ELECTRONIC SWITCHING SYSTEMS

1. GENERAL

1.001 This addendum supplements Section 232-138-501, Issue 4. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum does not affect the Equipment Test List.

2.001 On page 1, add paragraph 1.03.1 as follows:

1.03.1 New (conventional) service order codes were adopted for use with the EF-2 and 2B-EF-2 generic programs. However, the translations can be configured with the old (No. 2 ESS unique) service order codes as an option. These old codes are common to all previous No. 2 and No. 2B ESS generic programs. The EF-2 and 2B-EF-2 generic programs can be arranged to recognize either option. In this section the term "conventional (new)" or "No. 2 ESS unique (old)" is used to identify the service order code for the keywords in each TTY input message given.

2.002 On page 2, paragraph 3.04, delete the system response and replace with the following:

The system response for offices using No. 2 ESS unique (old) code is as follows:

```
AR VY TRK aaa bbb
TEN nn gcsl
```

```
.
.
.
DSP ss rrbb
.
.
.
END
```

The system response for offices using conventional (new) code is as follows:

```
AR VY TRK aaa bbb
OE nn gcsl
.
.
.
DSP ss rrbb
.
.
.
END
```

2.003 On page 11, Step 7, for No. 2B ESS offices, change ss = Number of trunk scanner in decimal (0-11) to:

ss = Number of trunk scanner in decimal (00-11 for the 2B-EF-1 generic program) or (00-30 for the 2B-EF-2 generic program)