EQUIPMENT TEST LIST

B.S.P.	ISS	TEST OR REQT.	EQUIPMENT AND WORK DESCRIPTION	CLASS	FREQ.	JOB NO.
			SUPL 1			
			DELETIONS			
402-400			Return Loss Measurements			
402-400-503	1		TH SYSTEM			
(Page 2)		2	*Measure Return Loss of Each Transmitter and*	*MW*	*12M*	
			Receiver Antenna System Using One Channel			

Printed in U.S.A.