NOTES:

1. ALL SOLDERING SHALL BE IN ACCORDANCE WITH 50016, METHOD C.

2. SEE STOCKLIST OF ASSEMBLY DRAWING P-13E620, SHOWN ON A-579573, (612A) AND P-13E976, SHOWN ON A-579613 (615A), FOR INFORMATION CONCERNING ITEM NUMBERS AND REFERENCE DESIGNATIONS.



FIG. 2
TOP VIEW OF SPRING PILE-UP ASSEMBLY



FIG. 1
BOTTOM VIEW OF BLOCK

Item	IDENTIFICATION NO.	DESCRIPTION	REF DESIG	NOTE	Item
		STOCK LIST			

SUPPLEMENTARY DRAWINGS

SIGNIFICANCE OF SYMBOLS AND ITEM NUMBER SUFFIXES

S—PARTIAL ASSEMBLIES ON OTHER DRAWINGS WITH STOCK PARTS
D—PARTS SHIPPED LOOSE
ITEMS NOT SPECIFIED AS "S" OR "D" PARTS IN ITEM COLUMN ARE INDIVIDUAL ("A") PARTS

WHERE ITEMS HAVE REFERENCE DESIGNATIONS, THEY MAY BE USED IN LIEU OF ITEM NUMBERS ON THE DELINEATION.
✓ IN "REQ" COLUMN OF STOCK LIST—QUANTITY AS REQUIRED
✓ IN "DWG" COLUMN OF SUPPLEMENTARY DWG LIST—DRAWING REQUIRED
● DENOTES MANUFACTURE DISCONTINUED
▲ DENOTES MANUFACTURE LIMITED
AB—DENOTES APPARATUS BOOK DRAWINGS

UNLESS OTHERWISE SPECIFIED, ALL DIMENSIONS ARE IN INCHES. NONLIMITED DIMENSIONS OTHER THAN SIZE OF RAW MATERIAL SHALL BE HELD AS FOLLOWS WHEN EXPRESSED:
TO 2 DECIMAL PLACES ±
TO 3 DECIMAL PLACES ±
AS ANGLES ±
FOR GENERAL INFORMATION ON SYMBOLS AND NOTES REFER TO MANUFACTURING STANDARD 16.003, PART 2, SECTION 227.

DWG. SIZE 6S

REF FIELD CONSTRUCT	P-13E474
CONTROL DWG	A-579610
SUPPLEMENTARY DWG	A-579566
USED ON	DWG
(CO-590522-A1)	

WIRING DIAGRAM

SCALE

WESTERN ELECTRIC CO. INC.
ENGINEER OF MANUFACTURE

CDS

A-350045

A-350045

A-350045

ISSUE-1 7-10-61

REMOVED: P1 & WAS CONNECTED FROM PIN 1 TO PIN 6 OF ITEM 32 (TO AGREE WITH A-579573, (55A) (590612-A1))

ISSUE-2 9-14-61