BURIED CABLE MARKERS

NOTES CONCERNING THIS ADDENDUM:

This addendum has been issued to correct the wording and telephone number on the underground cable warning sign.

The following paragraph should be marked "See Addendum" and treated as indicated:

Paragraph 5.01 - Drawing on Page 5 replaced

5. UG CABLE WARNING SIGNS

5.01