PLANS USED	

TTY 67 Lin 5+16 REC 2+9



NOTE:
1. SOME 128B2 SUBSCRIBER SETS DO NOT INCLUDE THE (AT) RESISTANCE, AND WHEN THE KS-5663, L4 OR L7 RECT. IS USED A CHECK SHOULD BE MADE TO INSURE THAT THE (AT) RESISTANCE IS PRESENT.

15 TTY-15N TABLE
TWP SERVICE-128B2 TTY SUB SET
SINGLE LOOP OPERATION
WITH EMERGENCY TTY

BELL TELEPHONE LABORATORIES, INC.
PRINTED IN U.S.A.

COPYRIGHT, 1954, BY AMERICAN TELEPHONE AND TELEGRAPH COMPANY