Acer Aspire V5-572, V5-572G CMOS Battery Replacement

Acer Aspire V5-572,V5-572G CMOS Battery Replacement

Written By: ZFix

www.iFixit.com

INTRODUCTION

Acer Aspire - V5-572, V5-572G

If the Laptop shows sometimes error messages related to time and date options or CMOS checksum error, you must to change the battery of the motherboard.

This guide will show you how to do this.

### TOOLS:

- Phillips #0 Screwdriver (1)
- iFixit Opening Tools (1)
- iFixit Opening Picks set of 6 (1)

PARTS:

- CR2032 Lithium Battery (1)

This document was generated on 2019-09-22 10:19:05 PM (MST).

## Step 1 — Bottom Cover

- ⓘ Switch-off the Laptop.

- Remove the seventeen Philips #0 screws.

Step 2

- If there is a plastic storage tray in the laptop, remove it.

This document was generated on 2019-09-22 10:19:05 PM (MST).

Step 3

- Starting from the SD Memory Card hole, start prying between the top and bottom cases.

⚠️ Use plastic tools to avoid damaging the cover.

- Remove the bottom case.

Step 4

⚠️ Disconnect the battery immediately for a safer repair.

- Pull the battery connector away from the hard drive to disconnect it.

Step 5 — CMOS BIOS Battery

- Lithium Battery tape CR 2032, 3V

To reassemble your device, follow these instructions in reverse order.