# Dell Inspiron 14 3459 Display Assembly Replacement

Written By: Terrence15

INTRODUCTION

In this guide, we will be showing you how to remove and replace the Display Assembly.

🔧 TOOLS:

- Phillips #0 Screwdriver (1)

This document was generated on 2019-10-07 10:36:01 PM (MST).

Step 1 — Sliding the Antenna Cables

⚠ WARNING: Before working inside your computer, read the safety information that shipped with your computer and follow the steps in Before Working Inside Your Computer. After working inside your computer, follow the instructions in After Working Inside Your Computer.

- Close the display and turn the computer over.

- Slide the antenna cables into the slot on the computer base.

## Step 2 — Disconnecting the I/O Board Cable

- Turn the computer over and open the display.

- Open the latch and disconnect the I/O-board cable from the I/O board.

This document was generated on 2019-10-07 10:36:01 PM (MST).

Step 3 — Removing the Board Cable

- Remove the I/O-board cable from the computer base.

Step 4 — Remove the Antenna Cables

- Note the antenna cable routing and remove the antenna cables from the routing guides on the computer base.

This document was generated on 2019-10-07 10:36:01 PM (MST).

Step 5 — Note the Routing

- Note the display cable routing and remove the cable from its routing guides on the computer base.

Step 6 — Remove the Screws

- Remove the screws that secure the display hinges to the computer base.

This document was generated on 2019-10-07 10:36:01 PM (MST).

Step 7 — Lift the Display Assembly

- Lift the display assembly off the computer base.

Step 8 — Align the Screw Holes

- Align the screw holes on the display hinges with the screw holes on the computer base.

Step 9 — Replace the Screws

- Replace the screws that secure the display hinges to the computer base.

Step 10 — Route the Display Cable

- Route the display cable through the routing guides on the computer base.

This document was generated on 2019-10-07 10:36:01 PM (MST).

Step 11 — Route the Antenna Cables

- Route the antenna cables through the routing guides on the computer base and slide the antenna cables through the slot on the computer base.

Step 12 — Sliding the I/O Board Cable

- Slide the I/O-board cable into the I/O board and close the latch to secure the cable.

This document was generated on 2019-10-07 10:36:01 PM (MST).