# DigiTech RP70 Input/Output ¼" Ports Replacement

This is the guide to replace any of the three input/output jacks on the RP70.

Written By: Elijah Smith

INTRODUCTION

If the input/output port is broken this guide will teach you how to remove the broken component for replacement.

🔧 TOOLS:

- Phillips #0 Screwdriver (1)
- Soldering Iron (1)

This document was generated on 2019-09-22 10:40:43 AM (MST).

Step 1 — Motherboard

⚠ Unplug the device from its AC power adapter; unplug anything connected to the input/output jacks.

● Remove the four 8mm Phillips #0 screws located on the back panel.

Step 2

● Remove the back panel to expose the motherboard.

This document was generated on 2019-09-22 10:40:43 AM (MST).

Step 3

- Remove the two 11mm #0 Phillips screws located at the bottom of the motherboard.

Step 4

- Lift the indented end of the motherboard opposite the input/output jacks. Then, pull away from the input/output jacks to slide the motherboard out of the casing.

Step 5 — Input/Output ¼" Ports

- [Desolder](#) the back of the motherboard where the damaged input/output port is located.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2019-09-22 10:40:43 AM (MST).