HP Pavilion x360 15t-br000 Keyboard Replacement

Use this guide to replace the keyboard in your HP Pavilion x360 15t-br000.

Written By: xi yang

This document was generated on 2020-01-27 10:01:25 PM (MST).

INTRODUCTION

Use this guide to replace the keyboard in your HP Pavilion x360 15t-br000 laptop.

If your keyboard is damaged, you can not type text into the laptop.Thus, you can not operate normally on your laptop with a damaged keyboard.

Remember to shut down the laptop when doing the replacement.

🔧 TOOLS:

- Phillips #0 Screwdriver (1)
- Metal Spudger (1)

This document was generated on 2020-01-27 10:01:25 PM (MST).

　　　　　www.iFixit.com

Step 1 — Keyboard Panel

- Remove the covers to access the screws attached to the back cover of the device.

- Remove six 3mm screws using the Phillips #0 screwdriver.

Step 2

- Use a metal spudger to loose the four corners of the keyboard panel. The corner is circled red shown in the first image.

- Disconnect the keyboard panel cables under the upper case.

- Remove the keyboard panel from the device.

       www.iFixit.com

Step 3 — Keyboard

- Remove the two tapes of connected with the track board and the keyboard panel.

- Remove the seven 2mm screws using the Phillips #0 screwdriver.

- Remove the trackpad from the device.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-01-27 10:01:25 PM (MST).