Hot Tools HPK12 Cord Replacement

This guide will show you how to replace the Cord on your Hot Tools HPK12 Titanium Flat Iron.

Written By: Ben Miller

INTRODUCTION

This guide will show you how to replace the Cord on your Hot Tools HPK12 Titanium Flat Iron.

⚒ TOOLS:

- Metal Spudger Set (1)
- Phillips #2 Screwdriver (1)

Step 1 — Cord

- Remove the two black 6mm screws.

Step 2

- Slide the black O-ring out of its channel and pull it off the end of the flat iron.

Step 3

- Separate the top and bottom pieces of the shell. It may require some force to break the seal.

Step 4

- Remove the cord by pulling up and away from the bracket. You are now ready to replace the cord.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2020-03-05 08:04:10 PM (MST).