# Palm Treo 680 Microphone Replacement

Written By: Maiya123

www.iFixit.com

INTRODUCTION

This is a guide that indicates how to replace a faulty microphone for the Palm Treo 680.

🔧 TOOLS:

- Metal Spudger (1)
- Phillips #00 Screwdriver (1)
- Tweezers (1)

Step 1 — Battery

- Remove the battery cover by pressing on the small rectangular button located on the back of the phone.

Step 2

- Remove the battery by pulling it out towards you.

This document was generated on 2020-02-27 06:00:45 AM (MST).

© iFixit — CC BY-NC-SA   www.iFixit.com   Page 3 of 7

Step 3 — Back Panel

- Remove the stylus in order to access the screw.

- Remove the 27mm top-left screw using a T6 Torx screwdriver.

Step 4

- Using the spudger, remove the rubber rectangular cover located in the upper rear, right-hand corner.

- Remove the 27mm screw using the T6 Torx screwdriver.

 - (i) If there is a red Palm sticker covering this screw, puncture it to access the screw.

Step 5

- Remove the remaining two 27mm screws from the bottom using the T6 screwdriver.

This document was generated on 2020-02-27 06:00:45 AM (MST).

Step 6

- Turn the phone so the screen is facing the right side.

- Use a spudger to carefully separate the back panel from the front panel to access components inside the phone.

- Separate the covers from the left side of the device as indicated in the picture.

  ⚠️ The right side contains orange ribbons that are easily damaged.

Step 7 — Microphone

- Using a pair of tweezers, grasp the blue rubber microphone.

- Pull the rubber microphone up and back to remove it.

- Now you have successfully removed the microphone.

To reassemble your device, follow these instructions in reverse order.