# Roku 3 A/C Power Port Replacement

A guide to replacing your Roku 3's power jack.

Written By: Andy Hak

INTRODUCTION

Replace a broken or faulty power jack for your Roku 3. The Roku 3 cannot power on without a functioning power jack.

🔧 TOOLS:

- Screwdriver Hex 1.3 Head (1)
- Soldering Iron (1)

This document was generated on 2019-10-30 02:52:23 PM (MST).

Step 1 — Motherboard

- Place the Roku 3 on the table face down and orient it so you can correctly read the writing.

Step 2

- Pull back the rubber protection in the top right corner to locate the screw.

- Repeat with the bottom right corner and bottom left corner.

Step 3

- Remove the 9 mm screws from the three corners with a Hex 1.3 Screwdriver.

Step 4

- Open the device by gently lifting the bottom half away from the top half of the device.

Step 5

- Use your fingers to carefully lift the motherboard from the top half of the device.

## Step 6

- Pull away the IO shield from the motherboard using your hands.

| www.iFixit.com |

Step 7 — A/C Power Port

- Turn over the motherboard so the back is face up and almost all large silver components are resting facedown on the table.

- Orient it such that the backside of the HDMI port is in your upper right corner.

Step 8

- Desolder the connections of the A/C Power Port on the motherboard.

- Remove the port.

- (i) For more information on soldering, check out iFixit's Soldering Guide.

This document was generated on 2019-10-30 02:52:23 PM (MST).

To reassemble your device, follow these instructions in reverse order.