Samsung Galaxy Tab A 7.0" Headphone Jack Replacement

Replace faulty headphone jack to your Samsung Galaxy Tab A 7.0"

Written By: Bradley Watson

This document was generated on 2019-10-04 09:40:15 AM (MST).

TOOLS:

- iFixit Opening Tools (1)
- Tweezers (1)
- Phillips #0 Screwdriver (1)

PARTS:

- Galaxy Tab A 7.0 Headphone Jack Assembly (1)

This document was generated on 2019-10-04 09:40:15 AM (MST).

Step 1 — Headphone Jack

- Using the plastic opening tool, starting at any corner on the tablet, insert the tool between the back panel and the front panel.

- Slide tool around the tablet to unlock the panels from one another.

Step 2

- Carefully remove the back panel from the front panel.

- The inner components of the tablet will now be exposed.

This document was generated on 2019-10-04 09:40:15 AM (MST).

Step 3

- Remove the two Phillips head screws attaching the auxiliary port to the plastic frame using a P000 screwdriver.

- Remove the four Phillips head screws attaching the motherboard to the plastic case using a P000 screwdriver.

Step 4

- Using tweezers disconnect the headphone jack connector from the motherboard.

Step 5

- Using tweezers, carefully lift up the motherboard.

- Using tweezers, remove the metal jacket holding the headphone jack in place by grabbing the left corner where there is a recess to grab it.

- (i) There is a light adhesive holding the metal jacket down. You may have to pull slightly harder to get this off.

Step 6

- Remove the auxiliary port from the case.

To reassemble your device, follow these instructions in reverse order.

This document was generated on 2019-10-04 09:40:15 AM (MST).

This document was generated on 2019-10-04 09:40:15 AM (MST).