ZTE Grand X Max Plus Battery Replacement

This guide will show you the steps to remove the battery from your ZTE Grand X Max Plus.

Written By: Jordano Baer

INTRODUCTION

If you have a dead battery and want to replace it, you can use this guide.

The guide will show you how to remove the back cover of the ZTE Grand X Max Plus and how to remove the battery.

⚲ TOOLS:

- Hair Dryer (1)
- iFixit Opening Tools (1)
- Suction Handle (1)

This document was generated on 2019-09-20 02:20:33 PM (MST).

Step 1 — Back Cover

⚠️ Make sure you turn off your phone before starting.

● Heat the phone using a heating pad, heat gun, or hair dryer to loosen the glue. You just need to heat the back of the phone.

ⓘ You can also use a hair dryer or a heating gun for this step.

This document was generated on 2019-09-20 02:20:33 PM (MST).

© iFixit — CC BY-NC-SA | www.iFixit.com | Page 3 of 6

Step 2

- After the phone is heated, use the blue plastic opening tool on both sides of the phone.

⚠ Don't apply too much pressure because the cover can crack easily.

ⓘ To avoid that your cover cracks, you can add tape to back cover.

ⓘ You can use a suction cup to help remove the battery.

This document was generated on 2019-09-20 02:20:33 PM (MST).

© iFixit — CC BY-NC-SA   www.iFixit.com   Page 4 of 6

Step 3

- Carefully remove the cover from the phone.

Step 4 — Battery

- Use a plastic opening tool to pry the battery off.

- ⓘ The battery will be held down securely by glue, so it'll take quite a bit of sliding underneath to separate it from the compartment.

This document was generated on 2019-09-20 02:20:33 PM (MST).

Step 5

- Pull up the piece that is connected to the motherboard. You can pull it using your nails.

Step 6

- Remove the battery.

To reassemble your device, follow these instructions in reverse order.