# **Fixed Anomalies for Site Manager 15.5.0.0**

#### Q00517502-03: FT1

Need the ability to turn off Facilities Data Link (FDL) functionality on an FT1 interface. To do this, set the FDL parameter to None.

### Q00687120-01: Radius

Cannot configure a Radius client on a specific slot on a System 5000.

## Q00726531: Trap Manager

Cannot configure traps on a slot that contains a FREx processor board but not a link module. Note that this will only be allowed in Dynamic mode.

### Q00740507-01: MCE1

Cannot add or modify a circuit on an MCE1 module after the initial circuit is created.

#### Q00746359-01: ATM

Deleting a service record from an ATM circuit that contains more then one service record results in the removal of all protocols from the circuit.