

Cisco Unified CallManager Release 4.1(3) Service Release 8a

Release Notes Version 1
November 3, 2008

Table of Contents

[Introduction:](#)

[System Requirements:](#)

[Version and Description:](#)

[Important Notes:](#)

[Installation Instructions:](#)

[Installation Procedure](#)

[Uninstallation Procedure](#)

[Known Caveats for Cisco Unified CallManager 4.1\(3\)SR8a](#)

[Resolved Caveats for Cisco Unified CallManager 4.1\(3\)SR8a](#)

[Resolved Caveats for Cisco Unified CallManager 4.1\(3\)SR8](#)

[Resolved Caveats for 4.1\(3\)es144 - Base ES for 4.1\(3\)SR8](#)

[Resolved Caveats for 4.1\(3\)es135 - Base ES for 4.1\(3\)SR7](#)

[Resolved Caveats for 4.1\(3\)es126 - Base ES for 4.1\(3\)SR6](#)

[Resolved Caveats for 4.1\(3\)es106 - Base ES for 4.1\(3\)sr5, sr5a & sr5b](#)

[Resolved Caveats for 4.1\(3\)es72 - Base ES for 4.1\(3\)sr4d & sr4b](#)

[Resolved Caveats for 4.1\(3\)es40 - Base ES for 4.1\(3\)sr3c, sr3b, & sr3a](#)

[Resolved Caveats for 4.1\(3\)es25 \(Base for 4.1\(3\)sr2\)](#)

[Resolved Caveats for 4.1\(3\)es06 - Base ES for 4.1\(3\)sr1](#)

[File Versions included in 4.1\(3\)SR8a](#)

[Firmware Versions included in 4.1\(3\)SR8a](#)

[Determining the Software Version](#)

[Compatibility Matrix and Supported Upgrades](#)

[Locale Installer for Cisco Unified CallManager](#)

[Related Documentation](#)

[Release Notes for Cisco Unified CallManager Release 4.1\(3\)](#)

[Cisco Unified CallManager Document Guide](#)

[Obtaining Documentation, Obtaining Support, and Security Guidelines](#)

[Cisco.com](#)

[Documentation DVD](#)

[Cisco Ordering tool:](#)

[Cisco Marketplace:](#)

[Ordering Documentation](#)

[Reporting Security Problems in Cisco Products](#)

[Obtaining Technical Assistance](#)

[Definitions of Service Request Severity](#)

Introduction:

These Service Release (SR) release notes contain important information about installation procedures and resolved caveats for Cisco Unified CallManager release 4.1(3)SR8a. Updates for these release notes occur with every Cisco Unified CallManager SR.

Note: Please review all sections in this document pertaining to installation before you install this Service Release. Failure to install this Service Release as described may result in inconsistent Cisco Unified CallManager behavior.

System Requirements:

Make sure that you install and configure this release of Cisco Unified CallManager on a Cisco Media Convergence Server (MCS). You must install Cisco Unified CallManager on a Cisco-approved HP server configuration or on a Cisco-approved IBM server configuration, as indicated here:

http://www.cisco.com/en/US/products/hw/voiceapp/ps378/prod_brochure_list.html

Version and Description:

This Service Release is a cumulative update that incorporates all of the fixes and changes from Cisco Unified CallManager 4.1(3) ES144, along with additional changes that are specific to this Service Release.

Note: If you are running Cisco Unified CallManager 4.1(3) ES145 or higher, you must uninstall the Engineering Special (ES) before you can install this Service Release. (You may lose fixes that were added in 4.1(3) ES145 and above.)

Important Notes:

Service Releases do not impact system compatibility unless specifically stated.

Cisco provides the following guidance to help you successfully install and/or upgrade Cisco Unified CallManager software:

- Terminal Services/Remote Desktop Connection is not supported to perform this upgrade. For remote installation use VNC.

- Always log in with Administrator privileges before you begin the SR installation or uninstallation process.

- Exit all other applications and close all Terminal Services sessions before you begin the upgrade process.

- To minimize call-processing interruptions during the upgrade process, register all devices to servers that are running the same version of Cisco Unified CallManager software. Make sure that you register all devices to the backup Cisco Unified CallManager server or to the primary Cisco Unified CallManager server, but not to both the backup and primary servers.

- Upgrade all servers to Cisco Unified CallManager 4.1(3) and make sure that the servers are online before you begin this SR installation; otherwise, pre-upgrade checks may fail or return faulty information. This SR is based on Engineering Special 144. For this Service Release, Cisco supports upgrades from any Cisco Unified CallManager 4.1(3) release up to 4.1(3)ES144.

- If you are using Cisco Security Agent or a supported antivirus agent, you must DISABLE this software and then restart your system before you proceed with this installation. You must manually re-enable these services after the installation is complete.

- Make sure that you disable the following Cisco-verified platform agents and applications; these products may interfere with the Cisco Unified CallManager installation:

 - Server management agents

 - VOIP monitoring/performance monitoring

 - Remote access/remote management agents

- For a list of supported platform agents (i.e. Antivirus Products, etc.), review the following:

 - http://www.cisco.com/en/US/products/sw/voicesw/ps556/prod_bulletin0900aecd800f8572.html

- For optimum performance, apply the most current OS upgrade and SR before you install the Cisco Unified CallManager SR. For more information, refer to *Cisco IP Telephony Operating System, SQL*

Server, Security Updates at

http://www.cisco.com/en/US/docs/voice_ip_comm/cucm/win_os/os_srv_sec/osbios.htm

Service Releases contain firmware loads that are current as of posting, however, Cisco recommends that you always download the latest firmware load from the Voice Software Download Center at <http://www.cisco.com/kobayashi/sw-center/sw-voice.shtml>

All nodes in the cluster run through a database replication health check during the upgrade process as an extra measure, even though the publisher's database replication check should catch any replication errors clusterwide. If you encounter a warning message on any node during this check, make sure that you stop the installation process and check the log files. Follow the recommendations listed below if the log file displays any of the following messages:

All agent-implementing jobs are waiting to start

At least one agent-implementing job is attempting to execute after a previous failure

At least one agent-implementing job has failed to execute successfully

Installation Instructions:

The following procedure provides details about how to install Cisco Unified CallManager 4.1(3)SR8a.

Note: Cisco recommends that you apply this Service Release during a maintenance window.

Note: It is very important to disable platform agents and services, such as NetIQ and Prognosis performance monitoring, antivirus (such as Cisco-verified McAfee services or other Cisco-verified AV products) and intrusion detection software, remote management services, and any other monitoring applications that automatically restart services; this action ensures that your system does not encounter issues that are associated with these services.

This Service Release upgrades the affected services and files and then it restarts the server when the upgrade has completed successfully.

Apply this Service Release to all of your Cisco Unified CallManager servers, beginning with the publisher server and TFTP server.

Installation Procedure

Note: To verify that the installation completed successfully, follow the instructions in Step 6 below.

Perform the following procedure to install Cisco Unified CallManager 4.1(3)SR8a:

1. From the Voice Software Download Center, navigate to Cisco Unified CallManager version 4.1 and locate the **ciscocm.4-1-3-SR8a.exe** file; then, follow the instructions to download the file.
2. Transfer the file to each CallManager node in the cluster.
3. Double-click the **ciscocm.4-1-3-SR8a.exe** executable file to begin the installation as noted below:
4. Cisco recommends that you upgrade all servers in the cluster sequentially, to the same version of Cisco Unified CallManager software; otherwise call-processing interruptions may occur:
 - a. Begin with the publisher server
 - b. Followed by the TFTP server
 - c. Followed by the sequential upgrade of the backup servers
 - d. Finally, the sequential upgrade of the primary servers
5. Click **Next** when the installation process displays a message that asks if you want to install this SR. The remainder of the installation process continues without any additional user input. The system displays a message when the installation is complete.

6. Verify that the installation completed successfully by taking the following actions:
 - a. Click **Yes** when the system prompts you to view the log file.
 - b. Scroll down to the end of the log file; if errors occurred during the installation, the errors section at the bottom of the log file will be updated with a corresponding severity.
7. If any of the Client Plugins have a lower version than those included in this SR, perform the following:

After you have rebooted the server and completed the upgrade on all servers in the cluster, go to Cisco Unified CallManager Administration on any client machines (i.e. JTAPI, RTMT Client, etc.), navigate to the **Application > Install Plugins** menu. Choose the applicable plug-in, run the program from its current location, and follow the installation instructions that the system displays.

8. The system may create or edit the following log files during the installation or uninstallation process:
 - c:\program files\common files\cisco\logs\CCMPatch\Cisco CallManager 4.1(3)SR8a Installation YYYY-MM-DD HH.mm.log (this file is also accessible by navigating to the Start menu shortcut "Cisco Install Logs" under the CCMPatch folder)
 - c:\install\dbinstall\dbinstallXXX.txt
 - c:\program files\common files\cisco\logs\CCMPatch\sqlX.txt
 - c:\program files\common files\cisco\logs\history.log

Note: This Service Release can take up to 20 minutes to complete the installation.

Uninstallation Procedure

The following procedure provides details about how to uninstall Cisco Unified CallManager 4.1(3)SR8a. (The SR uninstallation process does not change the device defaults to the version that was installed before the SR.)

Note: Uninstall the SR on all servers in the cluster in the same order in which you performed the installation.

Perform the following procedure to uninstall Cisco Unified CallManager 4.1(3)SR8a:

1. Navigate to **Start > Settings > Control Panel > Add/Remove Programs > Cisco Unified CallManager 4.1(3)SR8a Uninstall**.

A dialog box displays to confirm that you want to uninstall this SR.
2. Click **Next** and then **Yes** to continue.
3. Verify that the uninstallation process completed successfully by taking the following actions:
 - a. Click **Yes** when the system prompts you to view the log file.
 - b. Scroll down to the end of the log file; if errors occurred during the uninstallation, the errors section at the bottom of the log file will be updated with a corresponding severity.
4. After you have rebooted the server and completed the uninstall on all servers in the cluster, you need to revert to the prior version of the plug-in after the uninstallation is complete, navigate to the **Application > Install Plugins** menu from Cisco Unified CallManager Administration.
5. Choose the applicable plug-in on the client machine, run the program from its current location, and follow the uninstallation instructions that the system displays.
6. The system may create or edit the following log files during the installation or uninstallation process:

c:\program files\common files\cisco\logs\CCMPatch\Cisco CallManager 4.1(3)SR8a
 Installation YYYY-MM-DD HH.mm.log (this file is also accessible by navigating to the Start
 menu shortcut "Cisco Install Logs" under the CCMPatch folder)
 c:\install\dbinstall\dbinstallXXX.txt
 c:\program files\common files\cisco\logs\CCMPatch\sqlX.txt
 c:\program files\common files\cisco\logs\history.log

Known Caveats for Cisco Unified CallManager 4.1(3)SR8a

CSCsi68438	The installshield engine (ikernel.exe) could not be launched
CSCsj13112	The Latest Installed Version isn't updating
CSCsj18916	IpVms.sys isn't in the fileversions.ini
CSCsj18970	Aupairps.dll\DBConvert2to3.exe need to be removed from fileversions.ini

Resolved Caveats for Cisco Unified CallManager 4.1(3)SR8a

4.1(3)SR8a Devpack Fixes	
CSCsv43502	After install of sr8 6608 GW not receiving new code version
CSCsv40311	Adding 8.4(1)SR2 to CUCM
CSCsu42322	Adding Display Refresh Flicker Correction feature
CSCsu83049	Update 7925 CSV & XML files for FCS
7906G,7911,7941,7941GE,7961,7961GE,7970,7971	
CSCsu93940	phone failed to register to Windows CUCM working in mixed mode
CSCsm65836	7961G-GE Multicast Slow Throughput - disable flow control on BCM phones
CSCsr55945	Phone query's 12x Primary TFTP server before failing over to Secondary
CSCsr96183	Phone stops receiving mulitcast audio after few times
CSCsu23948	Assistant Phone gets hanged while making intercom call to two different.
CSCsu38132	CTI controlled phone generates incorrect DTMF
CSCsu43219	en-bloc feature causes non-dialable characters to be dialed
CSCsu47079	CP7931/CP7911 may unregister due to CDP hold timer expiry
CSCsv04751	DTMF is not squelched on third gen phones causing duplicate DTMF

Resolved Caveats for Cisco Unified CallManager 4.1(3)SR8

CSCsu38644	Valid SIP message can cause CCM process to crash
CSCsq35211	Hold/Resume issue between 4.3(2) and 7.0
CSCsb10401	CTI reports failure response when call is initiated on line with a call
CSCsr17872	Alerting Part name no presented to calling phone over SIP trunk
CSCsq52480	Rare Race Condition in Callmanager
CSCsr04662	CM Group Change Does Not Take Affect
CSCsq70952	TAPI does not always indicate correct CFA status on phones
4.1(3)SR8 Devpack Fixes	

CSCsu58187	SCCPxx.8-4-1ES2 should be SCCPxx.8-4-1SR1S
CSCsr78825	Font file in CUCM default US-english locale corrupted
CSCso68961	No "AAR Calling serach space" Field available for 7937 on CUCM
CSCsu42286	Adding 3rd Gen firmware 8.4(1)SR1 to CUCM
CSCsr96709	Adding 8.4(1) to CUCM
CSCsr99715	Wrong load name for H/W CFB in the device default page
CSCsr78254	Check-in Cisco 7921 firmware version 1.2(1) to CUCM
CSCsr74486	Update 7921 support files for Release 1.2
CSCso60580	7937 1.2(1) CUCM vob check in defect
CSCso45110	Locale not displayed properly after changing from Japanese to English
CSCsm72777	Announcement identified: 53 not found.
CSCsr54047	3.3(16) and 3.2(19) CCM vob commit
CSCsq01290	Adding 8.3(5) phone firmware to CUCM
CSCso60580	7937 1.2(1) CUCM vob check in defect
CSCsr54047	3.3(16) and 3.2(19) CCM vob commi
6608/6624	
CSCsh87381	6608Fix help file URL for CCM 6.0
7925	
CSCsq71668	Add 7925 support files (CSV, XML, GIF) to CUCM
7940/7960	
CSCsc81912	Pressing Cancel while Requesting RingList File displays two Ring Type
CSCsj46864	7960 shows 1 packet RXLost at start of every call
CSCsj56967	Firm 8.0.5 , Delay in accessing corporate directory on 7940/7960 Phones.
CSCsk01740	Secure ephone configured with octal Dn for more than 3 button reload
CSCsk02810	7940 Russian Phones show garbage characters in Calls History
CSCsk60865	7960 is not doing HTTP redirects properly when connected to Phone Proxy
CSCsl48111	7960/40 EAPOL-Logoff functionality
CSCsm03233	SCCP phone being told to play DTMF * but playing DTMF C
CSCsm85006	After a callback warning pressing dial plays dial tone and no ring back
7985	
CSCsf30989	CCMUser page has no user guide for 7985
CSCsm34227	7985 phones reply with ResponseItem Status="OK" instead of "0"
CSCse99403	Some of the fields on the phone's XML web pages have wrong information
CSCsd98103	SSH password field is only 7 characters wide
CSCsg45402	Unable to register 7985 to TFTP server which is not default

CSCsf12862	7985 fails to pickup parked call/initiate adhoc hardware conference
CSCsk00550	CfwdAll Display message is not getting refreshed.
CSCsh94592	7985 Changing the CCM version doesnt change the background image.
CSCsm68209	7985 need to support non-overlapping preference for video codecs
CSCsf11074	Phone ignores CDP when using Admin VLAN with PC Voice VLAN Disabled
CSCsg57377	7985 not displaying status correctly if MeetMe conference creator .
CSCsa83591	Operational impacting debug commands should not been available by telnet
CSCsd18615	when incoming call from IPVC, 7985 does not display correct video rate
CSCso11148	7985 "Download User Guide" link does not link directly to User Guide
CSCsi03313	7985Unable to make call from directory, from 2nd/other lines.
CSCsl43133	7985If DNS resolution failed to CCM1, CCM1 doesnt appear in CM list.
CSCsc84359	CCM4.2 - Cisco 7985 No Red Pickup Light Notification
CSCsc84373	Visual Pickup Notification sometimes does not overwrite status line
CSCsc68270	Network statistics stop refreshing when switching screens
CSCsh92840	7985 video-disabled & background image changed, new image seen other end
CSCsi18517	7985Phone displays "Rejected by CM "%S"" when autoreg disabled. .
CSCsh89214	7985Instance of call on phone not visible in a scenario. .
CSCsl43219	7985When all CUCMs service stopped, 7985 should display Registering.
CSCsd96689	Phone service input fields don't display pop-up box showing char choices
CSCsl29490	7985- 20ms packetization and phone still gets stuck intermittently
CSCse65798	Need to remove RFC2833 Disabled parameter for 7985 phone in CCM Admin
CSCsj32986	7985Status Not Updated Until OffHook/OnHook

Resolved Caveats for 4.1(3)es144 - Base ES for 4.1(3)SR8

CSCsm55846	BAT 5.1.4d - MLPP Domain Automatically Popoulates with 000NAN
CSCsj50653	Softkey template is set to none on new Device Profile
CSCsq35151	RISDC Authentication Bypass
CSCsq21662	CDR record error when call invalid number and blind transfer to client
CSCsm55007	Collation Difference Change in CDR Search
CSCso13172	DST- RTMT update needed for 2008 Iraq Daylight Time removal
CSCso12889	DST- Comm Manager ToD update needed for 2008 Iraq Daylight Time removal
CSCso78628	SIP trunk accepts unregistered and unauthorised INVITES
CSCsq01290	Adding 8.3(5) phone firmware to CUCM
CSCso12910	DSTES/SR JRE update needed for 2008 Iraq Daylight Time removal
CSCso90706	CallManager 6.1.1.3102-2 Cored
CSCse58233	Call pickup group not seen in select item combo box in F\L phone page
CSCse68351	Softkey is none if generate UDP Based on devices controlled by user

CSCso54978	Wrong load name for MTP in the device default page
CSCso28885	cannot initiate cBarge after call held and resumed on another device
CSCsj18891	CcmServRtmtPlugin.exe is not in fileversions.ini
CSCsa85396	CCMPWDCHANGER Next button greyed out
CSCsb45883	Callmanger Failed on backup Subscriber
CSCsd11122	Clean up pendingRequests due to request timeout (related to CSCsc79231)
CSCso45110	Locale not displayed properly after changing from Japanese to English
CSCsk84209	IPMA Assistant Console plugin to be uploded for 4.1(3)SR6
CSCsk30281	AC displays wrong error message in this scenario
CSCso19279	Incorrect error message when invalid entry is made to UserID Edit Box
CSCsl18244	AC not showing a headline for the first column in its windows
CSCsi92728	AC-Display changes to "to unknown" when parked call is held and resumed
CSCso02434	CM 4.2(3)es54.1 IPMA Client auto update fails - missing assistantconsole
CSCsk83084	Need parameter to allow updated OCN for each call
CSCsj54590	JTAPI changes termconn to active/talking for RIU line in progressing st.
CSCsk82007	Terminal.removeCallObserver() does not remove observation on calls
CSCso02197	JTAPI using invalid lineid for setForward
CSCsm72277	Announcement identified- 53 not found.
CSCsm78496	high cpu from java.exe during CAR load
CSCsk10239	New CDP.sys driver is only copied to C:\Program Files\Cisco\Bin"
CSCsm37416	MLA not allowing access to RouteList
CSCso09806	MGCP QSIG Interop issue
CSCsm95252	CUCM TFTP reaches max serving count with off-cluster connection timeouts
CSCso07015	DirUser java api causes cpu spike when car loader starts
CSCsl49298	Call drops if second H.245 MSD received from CVP
CSCso05118	Adding 8.3(4)SR1 phone firmware to CUCM
6608/6624	
CSCsh87381	6608Fix help file URL for CCM 6.0
7925	
CSCsq71668	Add 7925 support files (CSV, XML, GIF) to CUCM
7940/7960	
CSCsc81912	Pressing Cancel while Requesting RingList File displays two Ring Type
CSCsj46864	7960 shows 1 packet RXLost at start of every call
CSCsj56967	Firm 8.0.5 , Delay in accessing corporate directory on 7940/7960 Phones.
CSCsk01740	Secure ephone configured with octal Dn for more than 3 button reload
CSCsk02810	7940 Russian Phones show garbage characters in Calls History

CSCsk60865	7960 is not doing HTTP redirects properly when connected to Phone Proxy
CSCsl48111	7960/40 EAPOL-Logoff functionality
CSCsm03233	SCCP phone being told to play DTMF * but playing DTMF C
CSCsm85006	After a callback warning pressing dial plays dial tone and no ring back
7985	
CSCsf30989	CCMUser page has no user guide for 7985
CSCsm34227	7985 phones reply with ResponseItem Status="OK" instead of "0"
CSCse99403	Some of the fields on the phone's XML web pages have wrong information
CSCsd98103	SSH password field is only 7 characters wide
CSCsg45402	Unable to register 7985 to TFTP server which is not default
CSCsf12862	7985 fails to pickup parked call/initiate adhoc hardware conference
CSCsk00550	CfwdAll Display message is not getting refreshed.
CSCsh94592	7985- Changing the CCM version doesnt change the background image.
CSCsm68209	7985 need to support non-overlapping preference for video codecs
CSCsf11074	Phone ignores CDP when using Admin VLAN with PC Voice VLAN Disabled
CSCsg57377	7985 not displaying status correctly if MeetMe conference creater .
CSCsa83591	Operational impacting debug commands should not been available by telnet
CSCsd18615	when incoming call from IPVC, 7985 does not display correct video rate
CSCso11148	7985 "Download User Guide" link does not link directly to User Guide
CSCsi03313	7985- Unable to make call from directory, from 2nd/other lines.
CSCsl43133	7985- If DNS resolution failed to CCM1, CCM1 doesnt appear in CM list.
CSCsc84359	CCM4.2 - Cisco 7985 No Red Pickup Light Notification
CSCsc84373	Visual Pickup Notification sometimes does not overwrite status line
CSCsc68270	Network statistics stop refreshing when switching screens
CSCsh92840	7985-video-disabled & background image changed, new image seen other end
CSCsi18517	7985- Phone displays "Rejected by CM "%S"" when autoreg disabled. .
CSCsh89214	7985- Instance of call on phone not visible in a scenario. .
CSCsl43219	7985- When all CUCMs service stopped, 7985 should display Registering.
CSCsd96689	Phone service input fields don't display pop-up box showing char choices
CSCsl29490	7985- 20ms packetization and phone still gets stuck intermittently
CSCse65798	Need to remove RFC2833 Disabled parameter for 7985 phone in CCM Admin
CSCsj32986	7985- Status Not Updated Until OffHook/OnHook

Resolved Caveats for 4.1(3)es135 - Base ES for 4.1(3)SR7

CSCsa85518	Phones handset lamp not flashing if Service param "Hold Type" is true
CSCsl55631	No conference model established on CTI port in Offering
CSCsm31029	Need support for multiple progress indicators in PROGRESS message

CSCsm91430	7937 1.1(1) CUCM vob check in defect
CSCsm42626	Different conferences are joined together.
CSCsm55689	Device in registered state but not issuing Dial Tone on offhook
CSCsm12047	Maximum Counters Per Session i.e. 1000 on WIN CCM(4.1) does not work
CSCsm46064	Problem when CUCM sending out an invite with tel uri
CSCsm46027	Link 'View the User Guide for your phone' not available for 7911/7970
CSCsj18895	PLKs on 8.3 phones have "???" labels when talking to pre-6.0 CCM
CSCsm21224	Pickup failure - Pickup table entry remains as it is not removed
CSCsl94948	CCM release calls on receipt of status message for FAC IE.
CSCsm20067	CM doesn't process new call attempt from 79xx with 7914 -79xx seems hung
CSCsm12573	IPVMSApp TFTP Client appends extra byte to end of RRQ packet
CSCsk85086	Communications Manager RTMT update needed for Venezuela TZ change
CSCsl18846	DST- Comm Manager RTMT update needed for 2008 Brazil Summertime change
CSCsl90896	DST- Comm Mgr RTMT update needed for 2007-2008 Argentina Summertime chg
CSCsk17777	DST- RTMT JVM needs new timezone data to support 2007 NZ DST changes
CSCsj54590	JTAPI changes termconn to active/talking for RIU line in progressing st.
CSCsm03185	DST JRE ES/SR update needed for 2007-2008 Argentina Summertime change
CSCsl10157	Reason code wrong for Media Device unregistrations (CFB, MTP, MOH, etc)
CSCsl16491	DST Comm Manager ToD upd needed for 2008 Australia Summertime change
CSCsl90873	DST Comm Mgr ToD update needed for 2007-2008 Argentina Summertime chg
CSCsl53864	IP Phone keeps ringing even after CFNA is done
CSCsl51895	MOH locks up when using MOH with Full duplex streaming True
CSCsl04641	DST Comm Manager update needed for 2008 Australia Summertime change
CSCsc99257	Thread leak with IPMA activated but not configured (CTI disabled, users.
CSCsm13605	Update 7921 CSV and XML files for Release 1.1 FCS
CSCsl89165	CUCM Should Reset Incoming H.245 OLC LCN To 0 When OLC Is Rejected
CSCsc62073	Locations Out of Bandwidth causes unexpected Unity Failover
CSCsl53017	Pickup group configuration changes to none on shared line
CSCsi97709	Hear clicking when headset is attached and display is on
CSCsj19212	No audio if source reset RTP timestamp in the middle of a call
CSCsk21821	GUI process can lock up when receiving XML messages
CSCsk27161	phone unregisters when making toll free and long distance calls
CSCsl18853	DST- JRE update needed for 2008 Brazil Summertime change
CSCsk80526	ES/SR can abend during StopServices
CSCsi97912	JTAPI problem during conference calls.
CSCsl18846	DST- Comm Manager RTMT update needed for 2008 Brazil Summertime change
CSCsk85086	Communications Manager RTMT update needed for Venezuela TZ change
CSCsk17777	DST- RTMT JVM needs new timezone data to support 2007 NZ DST changes
CSCsk40662	Backporting IPMA Assistant Console plugin to 4.x for SR,ES,mainline

CSCsk80416	CCMUser login takes 12 Seconds to login.
CSCsl48004	Browser back button in Device Association page removes all device associ
CSCsl48329	Global Directory errors nonintuitive
CSCsl02367	receiving mac address is not unique error message when updating 6608
CSCsk20791	CallManager limits unity 5 voicemail port integration to less than 96
CSCsk17414	7911 LCD glimmer / flicker when florescent light is on
CSCsj77506	Intermittent Location CAC Bandwidth Leak
CSCsk78860	Meet-Me # Becomes Unusable After Parking It Twice
CSCsl18843	DST- Comm Manager ToD update needed for 2008 Brazil Summertime change
CSCsf01412	CCM does not mark b-chan as idle after sending release-complete.
CSCsh41460	busy hunt group return incorrect release cause
CSCsl22355	Char *s_strncpy doesn't check input parameters for NULL pointers
CSCsb05760	StartMulticastMediaReception in CCM trace must display multicast IP
CSCsi96814	Ringng condition with CCM and BA Dailer version 7.1.3
CSCef90503	Option for- Stop Extending Call On Q.931 Disconnect Causes
CSCse70721	Need ability to delay media until alerting, progress, connect, or PI
CSCsk46729	FS- CCM doesn't send CLC after CTI call hold request
CSCsj48672	WebKnight triggered when string 'code=' is encountered
CSCsl16535	DST- Comm Manager update needed for 2008 Brazil Summertime change
CSCsj04779	JTAPI stopped delivering events
CSCsk31196	Platform excetion when adding Terminal Observer
CSCsl37601	Adding 8.3(3)Sr2 to all CUCM builds .
CSCsl35182	Ehook- CCM Feature Description uses "Ehook" term .
CSCsl30824	Removing eHook feature from 11/06, 31, 41/61 and 70/71 phone models
CSCsl22167	Update Load_ID.prm for 7937 phone
CSCsl03211	Adding TNP 8.3(3) and 7937 1.0(1) to CUCM
CSCsl03191	Adding 8.3(3) features
CSCsk62795	CCM is not porting the OCN in Qsig ICT setup to oCdpnVM
CSCsl03211	Adding TNP 8.3(3) and 7937 1.0(1) to CUCM
CSCsl03191	Adding 8.3(3) features
CSCsk80351	Forwarded inbound QSIG calls sometimes presented as direct call to Unity
CSCsj92043	Connected INFO fail to update orig side when PBX Blind Xfer by Reroute
CSCsk70885	Faststart used with CTI RP can cause mediaexchange to fail.
CSCsk17284	Callmanager needs to pass multiple PI in Alerting message
CSCsk67620	CCM crash caused by StationD LineStruct array resize
CSCse21449	Calls from Boulder G729 communicator get fast busy due to MSD issue
CSCsk84868	Null pointer exception in JTAPI receive thread
CSCsh34550	PlatformExceptionImpl Error randomly occurs for redirect request
CSCsg67552	External caller DN was same as agent DN causes JTAPI to create EXT type

CSCsi96604	7985 Can not disable advertisement of g.722 codec
6608	
CSCsi65408	E1 Port on WS-6608 5.4(2) not replying to external ping (ICMP) packets.
CSCsi11805	ICMP is disable for 6608 Device
7921	
CSCsm49041	Check-in Cisco 7921 firmware version 1.1(1) to CallManager
CSCsk29789	7921 Reboots with race condition between HTTP and SCCP
CSCsk35364	7921 queues SCCP reset when not in main idle screen
CSCsk35382	7921 sends SCCP Unregister message unexpectedly
CSCsk37014	Corporate Directory blanket search does not display all results
CSCsk45135	7921 sources RTP from random port rather than port specified in olc
CSCsk65362	7921G phone cannot access Corporate Directory
CSCsk67080	7921 roaming improvements
CSCsk68437	7921 does not place the softkeys in the specified order
CSCsk73151	7921 does not dial * or the # before the dial strings
CSCsk81509	7921 does not dial out on available line if shared line 1 is in use
CSCsk84950	Ver 1.0(4) incorrectly display softkey Login, Flash, Acct used by CME
CSCsl06935	7921 phones will register max 2 lines when in srst mode
CSCsl14865	7921G error on activating SSID with 20+ chars
CSCsl22248	Speaker Phone Activates when Phone Answered
CSCsl29672	7921 fallback failure from SRST to CUCM .
CSCsl33154	7921 only roams on max TX retries with APs not supporting QBSS
CSCsl53949	7921 loses localized tones after reset
7940/7960	
CSCsk21863	DNS Response Parsing Stack Overflow
7985	
CSCeh05812	When registering to TFTP server the Call Manager Config is incorrect
CSCsd23422	Toggle Alpha Transparency of Menus using full screen key with 3 states
CSCsf13963	On CME, 7985 took ~7 sec to close video chann if CUTA press Hold
CSCsh04586	Mobility cell pickup feature is not supported on 7985
CSCsh77948	Status line is not updated when Call Forward All is performed
CSCsh87471	Unable to activate callback from 1st line to 2nd line which is shared DN
CSCsh87489	7985- Hit redial after call from 2nd line & CB, call goes out of 1st lin
CSCsh90893	7985- Phone restarts during active call if nw settings changed & saved.
CSCsh91214	7985- Transfer from Line1 to Line2 on 7985 doesnt work.

CSCsh94705	7985- ringer stops when callback hit in a scenario.
CSCsh94811	7985 phone doesnt display meetme number in a meetme conference.
CSCsh98317	Services button not working when DNS returns wrong address for CM5.x
CSCsi03370	7985- Displays "From Unknown Number" on shared line, when call placed.
CSCsi11684	7985 - dialled digits are dropped, dialing from Directory in a scenario
CSCsi11755	7985- Dialling from directory doesnt initiate newcall in a scenario.
CSCsi11847	7985- nw config locked, still erase button accessible in a scenario.
CSCsi20257	7985- gap before first speed dial
CSCsi20273	7985- Wrong softkey template is retained
CSCsi32450	7985- G729 codec time lag is too long.
CSCsi43569	7985-No PC port connectivity when phone is in voice vlan
CSCsi68045	7985 does not acknowledge reset message
CSCsi68103	7985 does not failback when secondary CME is not available
CSCsi88218	7985 does not support video bit rates of less than 64kbps
CSCsi96604	7985 Can not disable advertisement of g.722 codec
CSCsj16414	7985- should be able to handle audio only conference (testing only)
CSCsk46491	7985- changes to reflect Cisco Callmanager product name change
CSCsk86556	Phone uses old Alt tftp ip instead of existing.
CSCsk86579	7985- **#** to unlock needs to key-in very fast.
CSCsl22095	7985- Phone reboots on invoking graphicMenuBoundary test. .

Resolved Caveats for 4.1(3)es126 - Base ES for 4.1(3)SR6

CSCsk61898	No counters in traces to indicate available resources for MTP/Xcoder
CSCsj35169	CallPark Reversion text not displayed when device controlled by CTI
CSCsk76659	correct DST settings for Newfoundland and London
CSCsb99648	Button Disappears from IPMA ToolBar
CSCsk74433	correct DST settings for Newfoundland and London
CSCsk48211	Extra button templates are displayed for 7937
CSCsk60093	Update the QED setting for the 7937 phone guide
CSCsk66315	User Guide added for new IP Phone 7937
CSCsk04754	CiscoAddress.setForwarding reports invalid state 1 (= IN_SERVICE)
CSCsk44375	MTP port not closed when h323 call finishes before media creates MXs
CSCsk43187	CTI Route Points stuck in state=WaitforRegister after ccm.exe crashes
CSCsk18542	H245 Process leak when not getting SDLListenRes from SDL TCP layer
CSCsk37562	IPVMS crash - race condition or memory shortage
CSCsj88596	CM strips first digit of PRI DMS Original Called Party Number
CSCsk46944	CCM service restarts on receiving a valid SIP Packet
CSCsk28463	Changing User Profile information deletes 'ciscoatuserprofile' in AD

CSCsk52155	Update English locale Files into the CCM branches for 8.3.3 release
CSCsh84539	Locale Changes
CSCsk47048	7940 - 7960 Do not upgrade to P00308000700
CSCsj84028	CCM 4.1 No ACK to mid-call INVITE response
CSCsj72525	Transfer failure when operator transfers caller to ICM route point
CSCsj88994	CTI Loop causing CM CPU Spike
CSCsg54933	No CallAttributeInfoEvent after LineEventFilterChange
CSCsd85136	Call disappears from the CTIOS client on cycling CTIOS server.
CSCsj09354	Phones stuck at requesting template
CSCsk12127	CM fails to start if not in CM grp- ERROR readStationRegistrationProfile
CSCsj14493	IPMA Callback feature causes ccm.exe crash
CSCsj99679	Transfers-fast go/stop with network delay causes fast busy
CSCsh74963	JATPI does not provide Network Reached event when IVR transfers
CSCsk21909	re-tag XML file for guinness QED
CSCsf31842	CDBLException Dump adding FXO ports into Route group
CSCed51968	EM login/logout causes errors in event log
CSCsj82133	Enter number message keep displaying for a long time after Gpickup
CSCse75188	CCM Does Not Populate Correct IP-Port For IRR - Cannot Send IRR Out
CSCsj51987	reason=unavailable is converted to originalCdpnRedirectReason=0
CSCsj78145	An AXL issue when the same parameter is being modified for the multiple
CSCsj64364	SIP diversion header with reason=unavailable is not handled properly.
CSCsj37299	Can't add phone template via BAT
CSCse48117	Prefix not prepended on the caller info after a call pickup.
CSCse87777	Called party number contains number prefix in a scenario
CSCsj54547	Call is not cleared properly
CSCsj86355	Add Russian time zones (with DST) for GMT+4 and GMT+5 timezones
CSCsi96736	SR install reports error "2" when 2nd JRE is installed
CSCsj56299	CDR Analysis and Reporting does not reflect DST changes for New Zealand
CSCsj67111	Enable Guinness Model phones to appear in CUCM Admin Pages
CSCsj56236	Call Manager Update needed for New Zealand DST changes in 2007 CSCsc29848call processing failures due to partial table loads
CSCsc29848	call processing failures due to partial table loads
CSCsj61353	CCM Shows Conf resources allocated when CFB shows no sessions active
CSCsj61773	queued MSD from previous transfer causes later MSD failure
CSCsj72508	ccm 4.1.3 sr5b Outgoing Calls Fail throw DBL exception
CSCsh44003	CCM-DST change does not take effect for Timezone Atlantic Time (Canada)
CSCsj58771	Callmanger TOD Routing Update needed for New Zealand DST changes in 2007
CSCsj37081	CDP.sys causing nonpaged pool memory leak identified by Mdl tag
CSCsj49480	CTI error in event log when logging out of Ext Mob

CSCsj30852	Inactive or Unassigned DN with CFA still forwards calls
CSCsi53674	Phone does not display full status message when registration fails
CSCsj30844	7906/11 display square symbol when the Caller ID too long.
CSCsj59428	Update Device Support
CSCsj09650	CM is not forwarding the Notification Ind from QSig Facility Messages
CSCsf23007	Presentation Indicator is not set correctly in H225 Notify messages
CSCsd81015	CCM uses internal msec packet size, ignoring size proposed by caller.
CSCsj22605	Call Manager CTLProvider Heap Overflow Vulnerability
CSCsj33336	Adding 8.3(1) Display instances to all released CCM branches
CSCsi42951	If CDR database is offline/suspect InsertCDR service leak memory
CSCsa72958	IPMA could not read directory users
CSCsi97599	TSP crash at ASB bank in New Zealand related to EM
CSCsj14217	IPMA Assistant Console Install throws warning message after Aug 20
CSCsj10750	compatibility issue between IPMA and SMS
CSCsj29258	Locale file - target-dictionary.utf8.xml needs to be updated
CSCsi09197	7940/7960 SIP Phone Won't Display CGPN (Caller ID) - 8.5(0) (POS3-08-5)
CSCsj08607	TopN by Number of Calls - By Extension Reports in CAR are missing users
CSCsj09134	JTAPI function getType() for calling party returns farEndType = 0
CSCsj09236	Unable to clear CFA from IP phone
CSCsa70364	InsertCDR service should handle character '
CSCsi98510	Need a way to control SSH access to phone from CM
CSCsj06799	Check-in Cisco 7921 firmware version 1.0(3) to CallManager
CSCsh86221	Special number call is cancelled after 1 ring when keypad is locked
CSCsh86894	Phone on Antiope vibrates if headset attached when set vibrate alert
CSCsi16085	User can not do factory reset if setting access is disabled
CSCsi22784	High multicast can degrade unicast RTP voice quality
CSCsi26846	75% battery icon appears with full battery
CSCsi44504	7921 doesn't work with CME unicast paging
CSCsi86567	Power consumption high after roaming during a call with tspec enabled.
CSCsi63235	AXL-SOAP fails to update services on CallManager 4.1(3)
CSCsi78367	Pickup should not fail the action when receiving SsSplitInd with ss2=0
CSCse70772	DA entries get corrupted due to out of order change notification for DN
CSCsi98337	ccm tftp stops building new config files
CSCsh37992	SOAP requests return 999 HTTP Response Code
CSCsj01083	Webknight Firewall in CCM 4.2.3SR2 stops AXL requests
CSCsj01914	CallManager 4.2(3) ES 31 Web Knight POP up seen
CSCsj02768	WebKnight blocks 'style=', a valid input from CUOM to CUCM
CSCsi48096	MTP resource leak if no response are recived to BYE message.
CSCsi78363	Forwarding should stop CFNA timer and remove the call from PickupTable

CSCsi72404	Monitor table leak due to Q.SIG APDU in setup then Call immediate split
CSCsi63301	Pickup fails when call is transferred between interclusters.
CSCsg57283	Call Fails When PBX Attendant Console performs Blind xfr back to CCM
CSCsh96614	ST-Cause code 47 Resource Unavailable generated for SCCP to H.323 1CPS
CSCsh46915	Call over ICT fails when h245 OLCack is sent with wrong LCN number
CSCsi63412	Faulty Hi-Res CPU timer affects IPVMS driver on DL 380 G4 3.8Ghz CPU
CSCsi36083	Phone not able to place outbound calls
CSCsh36048	CCM sends an extra ORC
CSCse41788	Change Notification Fails - DBLCNQueue Counts Rise - DBL Ptr Corruption
CSCsi60627	15 sec delay due to missing MWI retError APDU
CSCsi12859	Callback fails if IPMA proxy line has PickupGroup or CFNA configured
CSCsi42635	For signaling only call, CCM should not request bandwidth reservation
CSCsc95859	After implementing CSCsb42763, can't view or delete hunt pilot.
CSCsh86496	CM 4.3- Attendant Console Pilot Point returning busy after CM restart
CSCsi40809	MGCPQsigCdpc process leak for signalling only call
CSCsd99590	MLA- ASP file is not found in the when accessing VG224 gateway
CSCsg15510	MTP not invoked for G711Alaw call
CM-6608 CFB/MTP	
CSCsk15356	KeepAlive interval with CM-6608 CFB/MTP resources
6608	
CSCsf01303	6608 T1 resets due to bugtrap
7905/7912	
CSCsi03943	CP7912-UK Locale files are downloaded every time the phone reboots
CSCsi32679	7912 increase number of digits displayed for external phone number mask
CSCsg67466	DTMF Tx failing 7912G
CSCsh21722	7912G IP PhoneCannot access corporate directory with French locale
CSCsb76616	CP7905/7912 phoneDN returned Under DeviceInformationX is Incorrect
CSCsg33911	7912G does not boot up after firmware upgrade
CSCsg48291	CP7912G-The behavior after the recovery from the DHCP issue
CSCsi33314	Incorrect chunk size in http encoding for StreamingStatisticsX
CSCsh97445	HTTP URL requested by 7912 misses variable name
CSCsg21329	7912-Calling number is missing from received call history
CSCsi40995	The memory space of version string is smaller than the macro definition
CSCsh31976	7912 should retry after HTTP refresh failed
CSCsi22118	7912 8.0(2) SCCP - phone resets when accessing Corp Dir or other XML

7914	
CSCef20398	Check in 7914 loads
CSCse94977	Add new icons for sidecar to support Muster release
7920	
CSCsi98997	7920 Firmware 3.0.2 Check-in
7921	
CSCsi68185	High multicast can impact battery life
CSCsi95386	Proxy URL is not supported
CSCsj06189	Can not reset phone when idle url is active
CSCsj08685	7921 cannot resume shared line hold calls beyond the first
CSCsj17853	7921 doesn't show missed calls when keypad is locked and LCD went off
CSCsj19212	No audio if source reset RTP timestamp in the middle of a call
CSCsj20985	7921 enters speakerphone mode after call park retrieval with CME
CSCsj24173	Current volume can get impacted while configuring other volumes
CSCsj24757	7921 with CME speed dial can corrupt system message display
CSCsj26459	headset mic audio may distort if in noisy environment
CSCsj31395	DnD does not work with CME on 7921
CSCsj40917	Get a 10 second audio gap after receiving deauth with static WEP128
CSCsj60989	Alert tone does not always play when pushed via Play URI
7935,7936	
CSCsb67361	Phonebook doesn't display numeric number by default in Web interface
CSCsd62614	Second phone in a shared line hangs in a failback and failover scenario
CSCsd70946	Phones hangs while using restore default from UI in this scenario
CSCsd70988	Phone UI displays error when Restore Factory default in a active call
CSCse89223	Fields in "Add New Phone Book entry" in 7936 GUI do not get refreshed
CSCse89250	"Server error-413 N/A" appears when wrong input given in phone book
CSCse90611	Phone book entries duplicate
CSCse93370	No validation for "upload logs" under Diagnostics in phone menu
CSCse93388	Ping page in GUI does not get refreshed
CSCse93398	No. of characetr as password input inconsistent in GUI and phone menu
CSCse94529	Call Park Reversion message not displayed
CSCse94545	Ping input in GUI gets truncated
CSCse94582	Network settings dont work when 2 phones are in a call
CSCsf10268	Phone Book does not accept 24 digits as DN
CSCsf10303	Only 23 digits displayed of a 24 digit DN though lot of space available

CSCsf18999	Softkey templates working improperly
CSCsf20893	CFwdAll in an active call breaks the voice path
CSCsg03371	CP-7936 v3.3.11 can continually reboot after a few weeks on HP switch
CSCsg06252	7936 may not dial the * character when using Phone Book
CSCsg68705	Softkeys missing(7936) ,when hunt pilot call is answered with callfwdall
CSCsg72715	Phone plays ringback tone if destination phone has CFA set to unknown.
CSCsg72841	Deleting the DN freezes the phone
CSCsg76020	"Http Server" label in place of Http client
CSCsg76026	DN does not display completely
CSCsg76032	Reboot does not work
CSCsg76088	Pressing menu-> phone button in active call phone in a wierd state
CSCsg76262	c in click should be capital on "Passwords/HTTP Port Change" webpage
CSCsg76410	Help page does not show hostname
CSCsg85470	Changing the ringer during an active call puts the phone on hold
CSCsg85473	Help page of time and date does not list all the date options
CSCsg85482	Help Page of Network Setup incomplete
CSCsg87187	Softkey templates incorrect in case of Shared line
CSCsg95361	7936 phones intermittently fails to upgrade to new load
CSCsg96610	Icelandic characters not shown on 7936 IP conference phone
CSCsh15304	Spelling of transfer softkey in case of new call
CSCsh20499	CFwdAll softkey is absent when initiating a new call during active call
CSCsh66397	7936 DN display only displays 11 digits of a 12 digit DN
CSCsh69839	7936 - tone49(zipzip) has beep beep then sounds like long euro ringback
CSCsh71499	CP7936 Experiencing Possible ARP Cache Corruption
CSCsh74682	7936- conference soft keys becomes inactive after a few calls
CSCsi17642	Need support for GetElementManagementFromManagedElementOid
CSCsi18606	7935 & 7936 stops after 8dhcp discoveries w/no response
CSCsi95304	DHCP changes can cause phone to reset while on a call
CSCsi34558	7936 resets or one-way audio due to exceptions caused by DHCP renewal
7937	
CSCsg18362	7937-Device Definition Files Need to be Checked In
7940/7960	
CSCsh71110	7940 / 7960 reboots when receiving IP fragmented packet
CSCsh83337	7940/7960 phones fail to upgrade LSC with CME secure authentication
CSCsh89961	Choppy audio/jitter in incoming RTP to 7960 causes one way audio
CSCsh85947	no audio after high delay or jitter on network with g.729
CSCsi50585	hook switch debounce timer too short on 7940 IP phone

CSCsi18540	In speakerphone disabled state, 'Dial' softkey active in a scenario
CSCsi55407	when callwaiting tone is invoked, calls stop getting ringback
CSCsi59551	7960(sccp) resets under Codenomicon HTTP test suite running
CSCsi63845	7960/SCCP resets under two cases of Codenomicon TCP Test suites
CSCsj16673	7960/40 ignores StartTone Messages when in connected state
CSCsj09232	Phone struck in a loop inside the personal address book
CSCsj12968	Migrate to use new load authentication key
CSCsj84236	multiple issue after upgrade to 3.3.5sr2b
CSCsj39564	Hold call is disconnected when primary CallManager gets back
7906G,7911,7941,7941GE,7961,7961GE,7970,7971	
CSCsh71451	NullPointerException on AutoCallAgentImpl.inFocusItemChanged() events
CSCsg61032	DSP Configuration Files are not Correct
CSCsg34158	7911 DEV load contains incorrect jar file
CSCsh91671	Third-Gen SCCP Retries Registration 20K+ Times/Day On Phone-Reg-Rej
CSCsi00668	R2D- mapPixelCoordinatesToWindow always returns NULL.
CSCsg09017	Pressing New Call should let user "Enter Number"
CSCsg69809	M&R- new M&R tone command should override playing tone of same type
CSCsg49400	Tone not suppose to send to supervisor when selected remote only
CSCsh58346	Phone does not show complete information for show inventory command
CSCsh05253	Change the immDiv softkey name to Redirect - Update SIP dictionary files
CSCse49854	Need Automation API to get status of headset, mute and speaker lights
CSCeg36199	Commit of CSCef34402 broke c6slc, other? pikespeak images
CSCsg16790	make 'DEBUG' trace anticipated for a 1-way audio problem as NOTICE trace
CSCsg45815	Phone doesn't calculate SRTP auth tag correct for certain RTP payload
CSCsi26607	DC bias introduced by noise reduction
CSCsh51849	Play URI doesn't play ring file after first time push
CSCsh48277	Guinness- Continuous unicast traffic resets the phone
CSCsg40569	C-P-7941 Changes on the Ring Tone go back to Default after a soft reset
CSCsi69085	Update memory timings for Goped boot loader
CSCsg15653	SIP phone failed to clear Held call when CCM restarted
CSCsd18550	TNP- keyboard I/O errors on reset
CSCsh21082	No spkrphone dialtone when Trans/Conf button hit on TNP SCCP 8.3.0.9S
CSCsg15118	ppid found file system issue with unmount beneath stdio file access
CSCsh29774	Re-partition MIPS memory allocated for ZSP
CSCsg23326	Call duration timer window on ph display cycles between multiple calls
CSCsg96535	7971-ringer volume is too high
CSCsg73772	7971 unable to come up while detecting Supplicant on both switch port
CSCsh66544	Guinness- Beamish models should not have touchscreen enable/disable

CSCsh50494	7942/7962- pressing "Cancel" key does not discard change to contrast
CSCsg52254	797X- Phone DHCP config data got corrupted during firmware upgarde
CSCsh57927	Phone UI locked up when remaining in fail over mode
CSCse67832	minimum send gain not consistent
CSCsh16054	Static analysis on debug shell
CSCsi58584	Broadcom phones unable to determine source port of unicast 802.1x EAPOL
CSCsh27031	Add wideband PLC to codec G.722 and L16K pcm
CSCsh75383	7975 Gigabit is sensitive to CM signal, and loose many packets
CSCsh62325	Show wrong time when using the Singapore date time group selection
CSCsg94978	Change dsp cost table for iLBC
CSCsh69952	Noise reduction causes highband rolloff on handset
CSCse86158	7931- Overview not in home position at initial bootup
CSCsi44101	Speed Dials not working on SIP Phones in a specific scenario
CSCsh99568	DSP resets when Noise Reduction is enabled and spike in audio signal
CSCsh96583	keypad tones not played on speakerphone when transferring a call
CSCsg21884	RTCP socket open error may cause audioserver to spin
CSCsg98214	Fix Static Analysis warnings from TNP security code
CSCsg20534	GoPed- Auto Line Select does not work as expected
CSCsh90574	Phone hangs if it stays on placed calls when the peer ends the call
CSCse30736	Third gen phone may behave wrong under stress registration test
CSCsh21201	Guinness- PC port does not forward egress packets
CSCsg31390	SIP Phone core dumped after failover
CSCsh69414	Disable Speaker/Handset for TNP SIP doesn't disable Meet me Softkey.
CSCsh61440	echo on guinness speakerphone
CSCsi50696	7970 with firmware 8.2.2sr1 speaker not working correctly
CSCsh94809	Unusable G711 calls (loud noise)
CSCsc42101	Automation- Need enhancement to AutoStream for SRTP or RTP
CSCsg61595	Automation does not work on 7911
CSCse09805	need interface getLineButtonPosition() to AutoCallAgentIf
CSCse71098	Phone- Dial softkey should not be available for PRIVATE numbers
CSCsh84369	CallHistory Menu- line key, speaker key, no longer work
CSCsg79786	Remove tftp command from Mirzam ROMMON
CSCsf07505	7971/7941 re-append parameters with a redirected authentication
CSCse87192	CDP can alter statically assigned VLAN
CSCsh76479	R2d code doesn't return null reference for corrupted PNG file
CSCsh02936	TNP SCCP phone displays "???" for DND linekey
CSCsg57105	Remove I-Hold changes for Enterprise phones
CSCse47164	3g-phones -- pick up Sun Java patch to address 2007 DST changes
CSCsh30041	TNP SIP phone needs to be power reset to re-register in a scenario

CSCsh45424	slower error propagation causing ph to become leaf of grand child phone
CSCsh20650	7971 Shows NPE when rebooted during inactive time
CSCsh52394	7911/7931/7962- DSP process memory leak
CSCsg34789	Filesystem Privilege Escalation
CSCsi64737	Volume Control on Group Listen is Broken
CSCsh66612	When zrun exec VM, it returns immediately& unmount takes causing Ph loop
CSCsg69169	ppid display notification icon addition
CSCsg88076	Psylocke code review
CSCsg82637	SCCP70.MU-1-0-19S advertises iLBC and causes the call drop
CSCsg65141	7931- Softkeys not Updated in Alerting State
CSCsh38895	PPID- sunvm should not be trying to come up while /dnld is occupied
CSCsg20828	Noise Reduction voice metric has erroneous value
CSCsh27001	Guinness- Update LCD device driver for 7975 (Murphys) model
CSCsh97248	supposed lock issue on CNU rebooting contention problem with init
CSCsh77943	SA errors for activate() methods
CSCsh66788	AutoStream getRemotePort returns neg value for ports in 60000 range
CSCsh15247	Guinness- Psylocke SOC SA/Cleanup
CSCsh05337	Inconsistent display of DND Feature (in line button) on SIP & SCCP Phone
CSCsh21992	KA timer still alive on child phone; phone creating new tranfer process
CSCsg08791	Audible MWI support
CSCsh97116	authentication fail on parent, but child authenticates OK
CSCsh28594	Guinness- keypad device driver for 7945 / 7965 models (Beamish)
CSCsg03189	SA baselining for TNP
CSCsg94655	7931-Resume SK does not resume call after scrolling to another line
CSCsg47862	Merge from DSP Version 4.2
CSCsh16244	Phone goes out of memory after upgrade/downgrade due to OutOfMemoryError
CSCsh79504	Hearing Aid Compatibility tests failed on Guinness/Wideworld TNP
CSCsi42294	Hebrew chars position too high in softkeys
CSCse50960	Comfort Noise needs to be tuned for Wideband codecs
CSCsh74616	8.3(1) SCCP Phone resets during video setup with non-CM6.0 Endpoint
CSCsg60921	Display scr. is dark & won't accept input while phone upgarde downgarde
CSCsh06243	phone as root and leaf for the same file; two roots for the same file
CSCsg40375	Phone with network plugged into PC port can get stuck if link drops
CSCsg21513	Osage- Phone drops incoming unicast EAPOL when VVLAN is present
CSCsg38776	Customer cannot use Codec of their choice after 8.2 phone load install
CSCsh06278	Parent not sending KA to leaf; leaf reroot; end up with TLOAD
CSCsd99957	Phones failover to secondary node with wrong cause code
CSCsh29250	PAE can't exit due to a file lock during shutdown, phone hangs
CSCsi40683	Cannot answer call by going off-hook

CSCsg15386	TNP phones on CME can't resume call with Line button
CSCsg50665	Focus does not shift to off-hook line while another call is incoming
CSCsg07708	PPID FOUND CORNER CASE- init never reimages in certain instance
CSCsh04378	Focus should remain on oldest ringing call with mulitple incoming calls
CSCsh84246	set ringtone after preview ringtone can crash a 3rd gen phone
CSCsf05653	NAK SMT/ORC
CSCsh37244	7975 Network Stats page displays the wrong NW port info
CSCsg96816	Guinness- move interrupt learning code to a helper function
CSCsh73366	MenuApp Application has wrong icon in title bar
CSCsh42049	Merge Noise Reduction improvements into Mainline branch
CSCsi29861	Phone Directory gives incorrect details after upgrade to 8.2.2
CSCsh95418	Muster- Phone Errors when pushing URL's with priority
CSCsg63862	offhook w/ handset for the first time after reboot, no dialtone is heard
CSCsi12885	7962/42 advertises PAUSE capable via Ethernet AUTO-NEG
CSCsg83617	PPID Unit Test Findings - TCP Communication Problem on Root Removal
CSCsh26780	SIP phones run out of memory in Java heap for every call
CSCsh79956	XML Parse error when phone is dialing
CSCsh48598	7911/7972- Add tool to dump DSP data structures, initially msg buffers
CSCsh27231	Remove redundant model specific dictionary entries
CSCsg98016	Update boot loader on Guinness phones
CSCsg40141	Replace TI assert function by dspfw define ASSERT
CSCsi09004	No dialtone with handset off-hook or using the Speaker button
CSCsh10877	Change text on Power Save Config menu of phone from Display to Backlight
CSCsh32248	Guinness- Update Touchscreen device driver for 7975 (Murphys) model
CSCsh27632	Guinness- update LED test app for 7975 model
CSCsh69955	SBB/SBCB & Barge/cBarge call instance focus incorrect after phone reset
CSCsg42971	OnHook Dialing from Line2 doesn't work if Line1 and Line2 have same DN
CSCsh67730	Not able to configure Directed Call park BLF in 7970/71 SIP phones.
CSCsg69313	GoPed- Add Help for Fixed Feature Keys, NavPad, and LocalFeature PLKs
CSCsh84510	Graphic Issues
CSCsh62009	guinness audio improvements
CSCsh22057	Guinness- use port index to update queue link speed
CSCsh80344	TNP phones fail to upgrade LSC with CME secure authentication
CSCsg12956	Enhance kernel memory utilities to report free blocks in the virtual mem
CSCsg71361	7970/71/41/61- DSPBOOTStart-Sync failure btw ZSP and MIPS-MBOX1=DEAD
CSCse96138	Need ability to send hook signal for onhook transfer feature
CSCsh95098	Phone does not come back up when the PC and sw cables are reversed and r
CSCsh50348	new threaded PPID algorithm with dual TX threads wont shutdown
CSCsh74277	"Update" softkey isn't displayed when focus is on LSC

CSCsh59997	Phones don't handle fatal Java exception properly
CSCsh95397	IP phone fails to parse the encrypted config file
CSCsh21659	SIP Tnp Phones display needs to be changed
CSCsh55163	bug trap 91 on system reboot
CSCsg15319	Don't write cdp.conf file everytime we recieve packet if not necessary
CSCsh79579	Changes per UI Evaluation
CSCsi04474	clean up syslogs in PPID remote and console logging
CSCsh21291	differentiate illegalStateException in getNodeId()
CSCsg78661	No help information avail for NAV Left NAV Right button in 797X phones
CSCse43654	IDLE Phone with Open detailview screen cause inconsistant DTMF behaviour
CSCsh98758	CallHistory Menu- Going offhook dials wrong number in special case
CSCsh07117	With Setting Access to restricted can access Network Config
CSCsh57968	Phone gets stuck while resetting
CSCsg10154	SIP 7970 phones showing RemoteHeld state while it has to be in HELD stat
CSCsg41181	/usr/cache out of space - can't create a new file
CSCsg73386	7961 phone not show Help info for privacy button
CSCsg64398	Large increase in PNG graphic processing time
CSCsg50737	Focus should remain on oldest ringing call with mulitple incoming calls
CSCsf99230	Handset adaptive gain control needs to match the 7940/7960
CSCsc12073	Automation- Need isSelected method in autoobjinfofocus
CSCsh38083	Display Timer on TNP Phones wrong, Meet Me initiated with Trans Pattern.
CSCsh30199	Shared memory access collision between dspfw and driver
CSCsh24257	JPN- Cannot Display Kanji via UserToDeviceData
CSCsg87192	79x1 phone delay to display system message after deactivate DND
CSCsh04310	Leave space between display of Internal caller ID and Line Text Label
CSCsg91609	Guinness- create unique queue for reserved mcast
CSCsg92844	turn on WB handset feature bit in mfgInfo for guinness phones
CSCsh73072	Background Image list item irregularities
CSCsh84815	Intercom- 7931 phone cannot complete onhook dialing with incoming interc
CSCsg33312	Takes long time to receive error from phone
CSCsg26548	SIP phone stop registering to CCM w/ 50% packets loss
CSCsg13871	Unknown name displayed if special characters are in display name
CSCsg83553	dtmf issue in CME software conference
CSCsg75502	7911 Ph unregister flood console logs with Supplicant logged off message
CSCsh95281	Top of Softkey Graphics Disappears When Slider Bar is Shown
CSCsh16283	Add debugging info-- add broadcast TX/RX count to call trace
CSCsh38542	phones should keep the latest Kfactor value in the phone stats
CSCsf20589	7914 configured over 15 digit in line number behaves very strange
CSCsh83469	Guinness 7945s got stuck during ppid upgrade

CSCsg91498	some SCCP phone types does not play call alert or reminder tone for DND
CSCsf96921	CallInfo page displays wrong status for the idle lines
CSCsf08041	convert "Can Not" to "Cannot" in all SCCP english dictionary phrases
CSCsh62801	SIP7911 stuck during automated upgrade/downgrade
CSCsh38661	Guinness- Update BN2 to latest diagnostics version 13.2.0.33
CSCsh66934	AutoFeatureIf invokeDirect returns success when softkey press failed
CSCsh70002	Headset LED in wrong state after power cycle
CSCsh98744	CallHistory Menu- Can't dial with line key speaker in special cases
CSCsh11245	Guinness- update to latest diags for all guinness phone models
CSCsg40909	Privileged Shell Commands available to unprivileged user
CSCsh14066	Handle REG ALL FAILED differently to allow LSC installation
CSCsg90047	Root phone not offerring new leaf when its children are gone
CSCsh27914	7975/45/65- Gig E speed option unavailable Switch port or PC Port settin
CSCsg20573	Guinness bugtrap- SY MSG- Kernel Shu= 0x6666
CSCsg87829	Call Preservation- sccp to sccp intercom call clearing issues
CSCsg39381	mislist processing removes critical files on upgrade [stale file problem
CSCse84617	Need to be able to get the versionStamp for the config
CSCsh59952	Intercom- phone does not do talkback if onhook dialing is in progress
CSCsg46339	ESP debug message add (passau)
CSCsh32344	Guinness- Implement Psylocke programming restrictions
CSCsh79786	on speaker, noise or mute tone heard when pressing Mute button
CSCsg51963	Factory Reset require for secure phone to move to another CCM
CSCsi47072	3rd phones break 802.1x auth when span to pc enabled
CSCsg10985	Bugtrap 0x91 phones (during fsck)
CSCsh53315	phone load need to support new timezones
CSCsh43529	Guinness- provide register access for gig testing
CSCsg51275	2nd iLBC channel can't be opened as full-duplex to do barge-in
CSCsg83593	Collapse muster into tnp_main branch
CSCsf33010	third gen phones power is initially set high power at boot w/line powered
CSCsg50951	Phone web page http-//Phone IP Add shows ??? character for parameter nam
CSCsg93125	Update 7975 / 7965 / 7945 bootloader for LED changes in new HW
CSCsh53200	Pre-dial list shows DN followed by conference after a conference.
CSCsg16614	flash/buffer comparison failing
CSCsi06502	Repeated Dialing from Call History Menus causes OutOfMemoryError
CSCsh70082	CallInfo URL missing VisibleFeatureList tag when application pane open
CSCsh84385	Secure conference need support for getting icons from confList
CSCsh86324	7975- Add touch panel calibration defaults
CSCsg89875	Phone declared as a child twice by same parent due to keep alives TO
CSCsg60966	SIP Intercom - enable redial feature

CSCsh78055	Audible MWI (Stutter Tone) is not sounds correct
CSCsh12444	Time zone rules do not update correctly on 3rd-gen phones
CSCsh21063	7911 phone advertise 2 iLBC codec on its capability message
CSCsh29270	dhcp memory leak
CSCsg97287	Change dsp cost table for G.722
CSCsi09102	7941/61 TNP time displays 1 hour early if power cycle
CSCsh48406	802.1x packets are not forwarded
CSCsi24166	Need a smaller font for the call reference for Makaha and Caffreys.
CSCsh58009	Private RIU calls show up in the callinfo list
CSCsg34758	IP Phone SSH Vulnerability
CSCsg93122	Read linenumbr from the config file
CSCsg20806	Noise Reduction total energy parameter rests at 28 instead of 0
CSCsd62804	7970 phone in low power mode consumes more power than CDP advertisement
CSCsi30040	Bogus load name in Phone load element value cause TNP phone to hang
CSCsh38263	Phone TFTP request packet for a background image is Malformed Packet
CSCsh18483	guinness- code cleanup in dsp device driver
CSCsh05966	Guinness- Update diags for Murphys to 13.2.0.23
CSCsh79629	TNP Phone SSH Vulnerability
CSCsh93038	Update diagnostics / BN2 for guinness phones
CSCsg92754	XML parsing error on LineInfo to turbo phones w/ speed dial configured
CSCsh73391	MenuApp Application has wrong icon in title bar
CSCsi42424	7970- Malformed UDP packet DOS attack causes phone to freeze
CSCsg71854	SIP shows incorrect info for placed intercom call in IntercomHistory log
CSCsg88111	SIP phone should disable Callback and DND for intercom call
CSCsh18467	port "reset on sleep mode" ddts to guinness code base
CSCsh61578	Modify assembly to address Titan Advisory R5691 and c55 Advisory CPU_116
CSCsh67900	Multiple softkeys on the phones are "bleached" on touchscreen drag
CSCse49845	Need automation API to get tthe time/date from the phone
CSCsg94679	Update cpk files for Beamish model 7965 phone
CSCsg33063	Need to Press Right button twice on Nav Pad to close Line Detail
CSCsi22566	Guinness- nmap TCP connect scan crashes 7945 and 7975
CSCsg13753	Composed IPPM messages display + instead of space
CSCsi05317	Update power requirements for 7945, 7965, and 7975 phones
CSCsh31900	Guinness- Update BN2 to latest diagnostics version 13.2.0.31
CSCsh98695	75 phone call numbers over flows the spaces assigned for it
CSCsh96691	Recording tone plays abnormally during a call
CSCsi41081	DSP process dies while running the call features automation script
CSCsh69745	LCD for Guinness 7975 need color register adjustment
CSCsg89210	SIP 7911 and 7961- Erase config from Settings menu does not reset phone

CSCsh76569	Font kerning issue on 7970
CSCsf96907	Missing Pixels on the left side of UI displays on Turbo phones
CSCsh29152	Guinness phones need different EQ based on Handset Hookswitch
CSCsh45237	Phone does not get registered when daisy-chained with 7961 phone
CSCsg17063	Customer is experiencing one way audio calls
CSCsb58751	TNP improvements- /bin/sh should always be a POSIX-compliant shell
CSCsg99046	7971GE- Sleep Mode issue
CSCsg46354	7941 - BLF speed-dial status LED does not work
CSCsf99285	PNG Broken- Phone fails HTTP GET if earlier HTTP request is not finished
CSCsi59185	wrongly uses tftp server as log server
CSCsi52430	Rings shouldn't be configured for intercom lines
CSCsh33442	SIP phone does not answer by lifting handset
CSCsh61505	LCD for Guinness 7975 phone displaying inaccurate color balance
CSCsi52234	Phone sends different help ID for intercom line
CSCsd65625	TNP semaphore traverse
CSCsf15839	Shared line display & going offhook while in active call distort display
CSCsd86563	command parse error and command search fail on 7970
CSCsh95139	JAL doesn't work as per requirement with c-Barge Conference
CSCsh79370	Frequency Value for Steady Dial Tone After Stutter is Wrong
CSCsg83632	PPID Unit Test Findings hash test ugliness
CSCsf29477	Jphone and init.tab and sleep interaction
CSCsh54326	Update diagnostics for Guinness phones to version 13.2.0.36
CSCsg87760	Phone does not get registered when daisy chained
CSCsh17747	pressline 2 not working for 2nd line of 7941
CSCsg28219	SCCP phone does not register back to publisher after restart.
CSCsg20339	GUI stuck after changing contrast
CSCsh61113	SA for img_main (image daemon)
CSCsg12954	Enhancement- provide an indication of when flash was last formatted.
CSCsh27635	Guinness- Fix the printing of the Chip Version Register (CVR) values
CSCsh31849	Ph hits max file download timer of 60 min during firmware upgrade downgr
CSCsg56809	TNP Phone 7941 second line line button will light up for incoming call.
CSCsh88441	SIP phone init a new call when pressing the line that already has a call
CSCse77453-2	Hung RS-232 port causes phone upgrade failure
CSCsg30974	Response.Redirect fails
CSCsh31843	When ph is going to safe mode or TLOAD its background should be cleared
CSCsh29551	Ph stuck in IDLE state after Java Error without CallManager menu Entry
CSCsi32069	7945/65/75 Hardware version 6.0+ uses external gamma
CSCsi43427	7970- nmap TCP connect scan crashes 7945 and 7975
CSCsh40396	7975- PC port goes no link after reconfiguring to 1000F

CSCsh00225	G722 Monitoring call could not be setup for iLBC primary call
CSCsg05630	Memory Leak on phones with repeated calls with very short call hold time
CSCse84601	Event needed for reset
CSCsh33456	Change the CiscoError, CiscoStart and CiscoReboot png files for new logo
CSCsg30853	Phone core dump while running the call features automation script
CSCsh69293	7971 SIP/SCCP- PC port can be enabled after being disabled from CCM page
CSCsh78286	7975- Port 0 is not coming up while working with 100 Half Hub port
CSCsh77939	Erroneous Behavior when DialLine URI on Intercom Line that has call
CSCsh04896	Gross timeout for downloading file with DLOAD & TLOAD should be changed
CSCsi12211	when callwaiting tone is invoked, calls stop getting ringback
CSCsh51967	Host unicast traffic are not forwarded to the egress PC port
CSCsg43304	GoPed- localization work for Muster
CSCsf97297	Phone hangs while downloading PNG files
CSCsh35474	7970- implement ethARLCache functions
CSCsh31868	TLoad- timer_start fail - doGrossTimeout-serial issue seen on 16s load
CSCsi33781	831-Settings button access set to restricted disables directories/servic
CSCsh16102	Callback softkey is presented but it doesn't do anything.
CSCsj44202	New Default Background Image Required
CSCsi55967	Jake Featurette check-in
CSCsi22692	Cloudraker-XML Parser- xml parse error on event ID of Redirect Softkey
CSCsi22697	Cloudraker-SendDigits URI fails to send in-band dtmf
CSCsi28316	Wideband Handset available for config on 7931.
CSCsj29511	7945/65/75 bounce link on soft reset for both PC and network ports
CSCsi78172	disable audio output during bootup
CSCsi35093	Alien crosstalk is degraded after CSCsh75383 is fixed
CSCsk00535	7971 DHCP address from data vlan
CSCsj44208	New Default Background Image Required
CSCsi15620	Cloudraker- Missing support of IconIndex in Title element
CSCsi97524	Turbo/Goped sometimes experienced resets after power recycle
CSCsi68055	7945/65 becomes inactive after CCM down
CSCsj14730	7961 crashed when running Codenomicon https suite(Test #9)
CSCsi23806	call on sharedline lost on phone - both users hit endcall on other line
CSCsk03246	Update diagnostics in BN2 for 7931
CSCsi51381	Ph not register afte XML Parser Excep seen during config file parsing
CSCsi05693	Cloudraker-phone fails to come up if deleted and tries to Auto-reg SIP
CSCsi97537	Turbo Bootloader Changes
CSCsj14728-2	7962 does not come up with load 8-3-1-10
CSCsi91532	7911 phone crash when switching to Arabic locale
CSCsi29861	Phone Directory gives incorrect details after upgrade to 8.2.2

CSCsj58806	TNP Phone Update needed for New Zealand DST changes in 2007
CSCsj72109	CIA 1085- lower Voice Mail status line to below DND state.
CSCsj67955	TNP Phone use Narrowband Vol Table even for WB
CSCsj24151	CallBubbleSelected.png is one pixel too wide for beamish
CSCsj58596	Ph in stuck state after capfList config structure change in SEP MAC file
CSCsj29530	Ph got stuck in Settings screen when Settings is pressed while dialing
CSCsj96756	7970 RLR is softer
CSCsj24826	Phone API startMedia request, parameter "receiveVolume" not working.
CSCsj39444	7975G characters look fuzzy/not formed correctly
CSCsj82411	Pixels surrounding the active UI tab are not black
CSCsj30906	Callback Message screen mixed up with Placed call screen
CSCsj57357	Cloudraker- XML parser- Hardened Soft Key Files schema rules
CSCsj47675	Resource Image updates for FCS
CSCsj78781	Update Guinness BN2 for Memory Bist tests
CSCsj42478	Darker greyscale images cause unreadable display on 7961/41
CSCsj03654	Guinness handsfree mic signal can clip
CSCsj22658	Cloudraker- XML Parser- No Error when tag is duplicated
CSCsj76590	Update Guinness BN2 files with diags version 13.2.0.60
CSCsj22707	Guinness Phones do not respond to 802.1x Re-authentication Requests
CSCsj65563	Missed call history incorrect for forwarded calls
CSCsh27683	Underworld - XML Parser Code changes
CSCsj30200	Underworld- Phone does not shows "bad ring list" for erroneous ring file
CSCsj16916	Cloudraker- XSI- xml push onFocusGained to phone executes 3 times
CSCsh69955	SBB/SBCB & Barge/cBarge call instance focus incorrect after phone reset
CSCsj46912	Update Guinness mfg image to include new diagnostics ver 13.2.0.49
CSCsj86182	PS loads fails to switchover to Jap locale
CSCsj57687	Resource Image updates for FCS
CSCsj04679	Underworld- Config File schema errors and issues
CSCsj67508	XML Schema hardening prevent encrypted & non-encrypted config parsing
CSCsj50696	7970 with firmware 8.2.2sr1 speaker not working correctly
CSCsh66572	7962- packets egressing PC port should have PC vlan untagged.
CSCsj09081	New generation phone have lower volume then older phone types
CSCsj29636	Null pointer exception on XML Parsing for SIP phones
CSCsj14733	ESW clock not initialized properly by boot loader
CSCsj10776	7962 barge in no voice
CSCsj71455	XML data can't be rendered to IPphone
CSCsj42254	Guinness Handset RLR incorrect
CSCsj27425	AEC suppression can degrade voice quality scores on Guinness
CSCsj47653	Guinness- Color models are displaying visual noise on power cycle/reboot

CSCsi82422	Pixels surrounding the active tab are not black
CSCsi34192	Cloudraker- CFWDALL and MCID not working on SIP phones
CSCsi44038	TNP SIP phone can not failover to SRST due to wrong port
CSCsi51093	Start Media Response does not returns codec string correctly
CSCsi49954	Guinnes handset - "highs" are little too high
CSCsi40110	Goped Bootloader Changes
CSCsh95586	New XML parser unable to display another Ph web page in XML services
CSCsi67614	TNP phone corrupt background image causes blue image and crash
CSCsi42432	Turbo- Malformed UDP packet DOS attack causes phone to freeze
CSCsh89981	Broadcast Storm one way audio for 7961 SIP
CSCsj89943	Update diagnostics in BN2 for 7911 / 7906
CSCsi27816	Guinness- Malformed UDP packet DOS attack causes phone to freeze
CSCsi78863	Analog codec audio output enabled in early stage
CSCsh48406	802.1x packets are not forwarded
CSCsi28283	SBB feature does not work
CSCsi89583	Update Guinness BN2 mfg image to release signed
CSCsh86422	Calls transitioning to OFFHOOK state should take focus
CSCsj23245	send specific XMLObject code into 7970, phone cannt request EM service
CSCsj85491	Guinness- improve AEC doubletalk performance
CSCsi29572	TNP SCCP ph unable to come up and register with sidecar 7914 attached
CSCsi83328	Underworld - XSI Backward Compatibility Changes
CSCsj82106	SDK version updated to 6.0.2 for 8.3.1.release branch [8.3(2)]
CSCsi44676	support new Spansion flash part
CSCsi97536	OS PLL init setting unnecessary
CSCsj47660	Resource Image updates for FCS
CSCsh93292	3rd gen phone may loose personalization after rereg to another CCM
CSCsi07754	Phone will not load from case sensitive TFTP server
CSCsi62729	Bug in vFillShorts assembly source
7942/7945/7962/7965/7975	
CSCsk27574	Check in Guinness phone firmware to CallManager
7985	
CSCsd23559	7985 Screen Powersave LED indicator can't be distinguished from MWI
CSCsg81394	7985 sources from random port rather than from standard specified in olc
CSCsg87851	7985 should use symmetrical UDP port numbers
CSCsc84363	Visual call Pickup notification fails when line audio alert setting off
CSCsf32885	7985 phone not working with Mobile Connect service. (CMM/SNR)
CSCsd32569	7985 does not send out video packets w/ IPMA configured

CSCsf99294	Star50 feature is not working on 7985 video phone
CSCsh79376	7985 phone with no voice vlan configured fails DHCP/ip address.
CSCsh86331	7985 enters reboot loop on upgrade when using Alternate TFTP
CSCsh91159	7985- the ">>" and "delete" softkeys in edit dial screen arent working.
CSCsh98124	7985- restart loop if load is different between DHCP and alternate TFTP
CSCsi05160	7985- Phone crashes when long input is entered in inputboundary test.
CSCsh94603	7985- Ringer stops ringing when try to change ringer drg outgoing call
CSCsh80864	Ringer stops when 2 incoming calls on 7985 & 1 call ended.
CSCsi23692	7985- Phone dumps hex value on screen with imageboundary service test.
CSCsi32472	7985- IPMA - Manager screen goes off after every change
CSCsi36049	7985- Screensaver leaves chars all over screen
CSCsh84842	Ping replies from the phone are not recognized by the originating host

Resolved Caveats for 4.1(3)es106 - Base ES for 4.1(3)sr5, sr5a & sr5b

CSCsi18723	Call has a negative CI number
CSCsi39652	H225Cdpc Needs To Handle DstopReq In Paused State
CSCsh98793	Call Control To Address Missing ssRejectionInterceptInd Event
CSCsh68517	RTMT JVM needs new timezone data to support 2007 DST changes
CSCsh44945	Phone Service subscribed by Autogenerated Dvice Profile is set to default
CSCsh32382	Adding THX and Babylon5 features
CSCsg24875	CCM drops APDU's received in a Progress message while in Transit mode.
CSCse05539	Aupair service terminates within function CDBNotifyClient-isRunning.
CSCsd35843	Aupair unexpected shutdown On 51st NCS Connection Request.
CSCsf20938	Long delay when calling overlapping DN from Webdialer.
CSCsg09173	No web access cfg option for 7941/61 in CCM device donfiguration page
CSCsg19828	Unable to insert 7941 phone with Device Security Mode as Authentication
CSCse60875	QRT misreading First and last write in report file
CSCsg16444	CCM- GW is intermittently lost from route-group route-list
CSCse46846	6608 PRI Gateway stayed up even when CCM lost connection
CSCsc24499	MGCP backual message with length of 12 bytes
CSCsb86004	Router identify a very short DTMF as a valid DTMF
CSCsf28425	CTI is sending CtiDeviceCloseNotify during failover/failback scenario
CSCsf28510	Phantom call stuck in attendant console client servicing broadcast queue
CSCsf25340	ES/SR Stopservices logging to stopservices.txt instead of ES/SR logfile
CSCsf10966	OS 2000.4.3a Upgrade Shows 110% On Stopping Services
CSCsf26211	ES/SR Need to reboot twice after 3.3(5)ES50 Uninstallation
CSCsf26883	ES/SR Need additional debug for commands run during installation

CSCsf13296	Merging local dictionary in CCM
CSCse54360	CCM unexpectedly shutdown while running ctigw (CUPS) load testing
CSCse72192	IPMA-RTMT counters shows wrong value for IPMA services
CSCsb21755	SCCP analog GW Virtual endpoint registration is rejected by CCM 4.1(3)
CSCsd8380	called number display on calling phone across ICT shows only DN
CSCsb44459	add/updateTransPattern-provideOutsideDialTone element is not present
CSCse41096	ES/SR - Update uninstallation handling
CSCse45722	ES/SR Internal reboot function doesn't work when executed remotely
CSCsf09846	ES/SR Update Stopservices to stop all COM objects
6608	
CSCsh69135	6608 MTP port intermittently unregistered
CSCsg67510	6608 T1 CAS ports are getting marked as OOS
CSCsf10555	6608- Cleanup code to make room for few more fixes
CSCsf11865	6608- debug enhancements
CSCsh31698	6608 Gateway gets unregistered after resetting MGCP Backhaul port 2428
CSCsf21778	6608 shows wrong OID
CSCsb65151	COLP not present over SCCP -- H323 ICT -- SCCP
CSCsf32240	Overlap Sending broken when using redial function while phone is onhook
CSCsg06040	SDL version change for fix of CSCsf32240
CSCse63793	CCM reporting encodingStyle as ISO-8859-1 instead of an http URL
CSCsd96188	Dead air for calls that are not processed by application.
CSCsc28999	CCM service unexpectedly shutdown - access violation
CSCsf05606	CM 4.1(3) stops Multicast-MOH after receiving an ICMP Dest Unreachable
CSCsc78892	CCMSNMP does not start on subscriber when publisher is down
CSCsc95740	Add retry DB Sanity test logic in CCM SNMP agent during initialization
CSCse77644	JTAPI CiscoTransferStartEv anomaly when transferring a call to a CTIRout
CSCsf23515	Address type not updated when JTAPI receives CallPartyInfoChangedEvent
6608 E1/T1	
CSCsg27904	6608 T1 cas channel rejects outbound calls
CSCsc96457	ccm core when QSIG-tunneled ICT call is disconnected by remote side.
CSCsg43678	CCM4.1(3)ES. SQL error when inserting a 7961 phone
7902/7905/7912	
CSCse89135	Phone response status inconsistent between models
CSCsd23880	7912 phone should not send StationFeatureStatReq if feature is not confi
CSCsd77798	7905- Japanese characters are shown as ?s in EM screens
CSCsd87290	CP-7912 can not use 255 as last octet of SRST address.

CSCsd57828	IPICS Channel selection by select key does not work intermittently
CSCse89724	DnD fails on 7912s
CSCsd03642	7912 w/alt tftp disabled does not read TFTP server from DHCP
CSCsd29035	7912 can not resume multiple calls from hold
CSCsc59290	Connection Monitor Duration changes not applied to 7902
CSCsd42758	7912 cannot make new call after lifting handset
CSCse33953	Malformed XML Delieverd from 7912GA when using DeviceInformationX
CSCsd63376	No response to UserToDeviceData for Key-xxx URI passed from CTI
CSCsd95573	Init-CallHistory URI does not re-set status line on 7905
CSCsd82000	call waiting tone doesn't stop when the second call hangs up.
CSCsc51485	7912 prefixes fastdial with 'undefined'
CSCse17115	7912 affected by ARP storm
CSCsf01247	7912 authentication problem - password encoding
CSCse41834	IP Phone Service problem with 7912 http redirect v8.0
CSCsd02610	Able to Change Ring Volume Even when Setting Access set to Disable
CSCsd72524	7912G-A phone does not obtain address when voice vlan = access vlan
CSCsd48532	CIA 650- Randomize TimeDateReq's to Call Manager from 7905/7912
CSCsg12126	CCM drops APDU with multiple invokes received in Alert message.
CSCsg30550	H225Notify Connected number IE not handled in some states
7920	
CSCsg59616	7920 3.0.1 Firmware and XML Schema Check In
CSCsc06572	Full Access & Read Only Access users are denied to view some pages
CSCsc27174	MLA generates error when configuring CSS for DN
CSCsc61258	Error Message ASP file is not found in the mapping for ROUser
CSCsc63798	Full Access user Not able to Run IPMA Wizards.
CSCsc87464	FullAccess User Can't edit HL/P, RL/P, DP from Route Plan report.
CSCsd97640	Multiple change notifications received for Route filter clause update
CSCeg51615	getHuntList response with wrong name space
CSCsd60519	AXL removePhone API doesn't remove the autogenerated device profile
CSCsf06697	HuntList needs to be fixed
CSCsb44680	MediaManager is not releasing the pre-allocated MTP resource
CSCsd13088	H323 FastStartCCM Closes wrong forwardLogicalChannelNumber in CLC
CSCsd24796	CCM does not allow IPVC PSTN call to be setup with G722
CSCsd65745	Race ConditionStationOffHook at same time as CcSetupReq received
CSCsd72778	Perfmon of >1 CM Shows 6624 GW Port-1 Registered Simultaneously
CSCsd87256	No voice after Call forward in a scenario-Call Diversion by reroute
CSCsd99344	Clean up the huntlist trace for better trouble shooting
CSCse00015	hunt list incorrectly extends call to next line group on race condition

CSCse32138	CCM does not start media in some scenario involving IPVC GW and Tandberg
CSCse43044	media resource status is out of sync between MatrixControl/Call Control
CSCse69001	Redial not working in a scenario involving overlap sending
CSCsf00272	Allow VideoCFB to update itself's capabilities
CSCsq12377	No transfer start event sent when CTI app redirects call during a trans
CSCsq15105	H.323 phone calling 7960 legacy SIP over H.323 ICT fast start fails
CSCeq33875	Incorrect Missed Call Information when Call is routed via HL/LG
CSCsq41812	CTI Route point does not unregister when administratively reset
CSCsq51334	CallManager 4.2(1)sr1a -redirect and transfer occurring at the same time
CSCsc62073	Locations Out of Bandwidth causes unexpected Unity Failover
CSCse72474	TFTP unexpected shutdown When Length Of File Name Exceeds 256 Characters
CSCsf13392	TFTP stop rebuild cache for some specific events
CSCsf95957	When CCM 4.2 is Secure, HTTP will not serve Un-Signed files, like TFTP
CSCsb04265	callInfoDisplay -Case Sensitivity different in getPhone and updatePhone
CSCsd04356	Failure adding member to CiscoAdminRepToolAdminGroupUsers Group.
CSCsc72925	RTMT (RISDC) not showing true value of CTI items when threshold reached
CSCse45530	Cannot login into Tomcat Web Application Manager
CSCsf03985	User field "Department" - Extending beyond 30 characters to 40 or more
CSCsb68657	CallManager input validation needs improvement.
CSCsf25313	ScalabilityImprove WebDialer call rate on 7845 to 4 calls/sec
CSCsq19828	Unable to insert 7941 phone with Device Security Mode as Authentication
CSCsq43678	CCM4.1(3)ES. SQL error when inserting a 7961 phone
CSCsf19999	Add support for Security feature in Communicator
CSCsq54729	3.0.1 English Dictionary Check In
7921	
CSCsi02935	Check-in Cisco 7921 firmware version 1.0(2) to CallManager
CSCsh57674	Unknown DRQs CM to GK
CSCsh83800	Call Redirect and CcSetupConf at same time in CM Call Processing
CSCsh50321	TransferManager splits pair of SsInfoInds to 2 dif. Transferring process
CSCsh93529	Double TransferStart/TransferEnd caused by SsRedirectCallInd
CSCsh74289	Detailed RoutePlanServer Trace Results in CallManager Restart
CSCsh36571	Redial Onhook fails when Routelist contains QSIG+NON-QSIG Route Groups
CSCsh81747	Callmanager TOD routing not updated with DST patches
CSCsh60272	Need to change PTT URL to Application URL
CSCsh73858	CTI is not setting more flag correctly when more than 50 Park DN's
CSCsh77362	Fail recieving SIP message when there are a lot of SIP Trunk
CSCsd59949	Cisco VoiceMail Port Wizard freezes when attempting to add port DN's
CSCsh95531	Install of 4.1(3)esA0 fails

CSCsh66860	Forwarding Table incomplete after CCM loses connection to Publisher SQL
CSCsh69439	SIP Trunk sends 200 instead of 488 on reinvite with no voice caps
CSCsh54683	TSP - Update Unmodified Calling DN with Modified when call is Offnet
CSCee40177	Attendant Console returns error if dial busy station
CSCsh57956	Need to have 4 new Service Parameters to control the cgpn prefix.
CSCsh50402	Device/Line goes OOS when CCM receives LinkOOS from other node
CSCsc50536	H.323-NonDialable Redirected Number Causes Corrupted CDR
CSCsq31011	Need Connected Number IE support in H225 CONNECT message.
CSCsc50103	MGCP-Non-Dialable Redirected Number Causes Corrupted CDR.
CSCse82363	Phone hangs/freezes in a blind transferred scenario
CSCsh49627	Unable to update a time schedule which has over 22 time periods
CSCsh42654	When conferencing, "Invalid Conference participant" is shown on phone
CSCsh50283	Merging local dictionary in CCM
CSCsq70952	TAPI does not always indicate correct CFA status on phones
CSCsh45847	Check-in 7921 firmware to CallManager
CSCsh32287	Cannot manually update / change phone load in DEVICE DEFAULTs page
CSCsf97815	race condition leads to MTP leak
CSCsh14343	CM Cdcc / bandwidth leak - HuntList stuck in paused state
CSCsh14487	CCM fails to send DLCX when receives QSIG ReleaseComp before CRCX Ack
CSCsh31967	right click transfer in attendant console fails, receiver gets MOH
CSCsc61299	Create Voice Mail is not working When MLA is Enabled For FAUser.
CSCsd99590	MLA- ASP file is not found in the when accessing VG224 gateway
CSCsh37279	Unable to create new or modify VG224 ports.
CSCsq66339	Need update to "devicelistx.asp" to support new Cisco 7921 wireless phone
CSCsq65659	Redirect call across 3 ICT disconnected when multiple hold/resume
CSCsq05163	MGCP/Qsig User name not displaying , Alerting name with ACSE
CSCsf15403	H245Interface does not use received h245ta to start H245 Client Session
CSCsq27373	AXL getUser fails after AD plugin integration
CSCse74654	ST-TFTP service does not build device config files after upgrade
CSCse10763	The phone config files are missing in TFTP2 server
CSCsc14339	Callmanagers do not have all timezones included in Date/Time Group
CSCsq54074	Update 7921 CSV and XML files for FCS
7935/7936	
CSCsf19023	Phone Button does not work
CSCse52537	7936 with 4.2SR1 cannot dial digits when in call state 3 (Ring Out)
CSCse40618	Scrolling to the end of the line in EditDial causes 7935/7936 Reboot
CSCse38339	7936 not passing DTMF while in alerting state.
CSCsd97794	DTMF tone will not play for consecutive same digits with 7936

CSCsd51983	Display is not uniform when dialing an non existing number
CSCsd56760	Mute dosen't work with Ping when CCM fails over
CSCsd58102	Phone dosen't ring while viewing the MAC address details using **6
CSCsd29851	7935 and 7936 do not support 40, 50, and 60ms frame sizes
CSCsd43199	Phone displays In Use Remotely with out shared line in SRST mode
CSCsd43138	LED Status changes when the Transfer softkey is selected in SRST mode
CSCsc76303	7935/36 need to support the priority field in DisplayPriNotify message
CSCsb63454	Polycom 7936 doesn't refresh after saving the Alt TFTP address
CSCsb21162	Main/Secondary TFTP Address cannot be modified when DHCP is disabled
CSCsb21151	Conference not working on 7936 in SRST mode
CSCsb18858	7936 Phone does n't allow/display full domain name.
CSCef12306	7936/7935 does not support JOIN feature of CCM 4.0
CSCse34223	Renumber 7935 firmware load name to match the CCO versioning
CSCsq19032	7935/36 reboot using corporate directory search on 3'rd party LDAP server
CSCsq35991	7936 with CCM 5.0 displays Server Not Found when access Corporate Dir
CSCsq26788	7936- Can gain access to web interface w/o admin password
CSCse92668	7936 does not register G.729a capability along with G.729 capability
CSCsf12006	Selecting Tone Test and exiting hangs phone
CSCse94554	Setting up Admin VLAN id brings up the phone without a DN
CSCse92515	7936/35- Ignore CDP V1 message for VLAN configuration purposes
CSCsq18874	7936 phone hangs when pressing hold & resume
CSCse54751	7935 does not recover after power/network loss
CSCsd88016	7936 phone shouldn't release its VLAN until the TTL(CDP message) expired
CSCsd51965	UI displays Failed to set VLAN Idwhen changing n/w setup in activecall
CSCsd52101	When we dial the DN through web page ,message flashes for sec & proceeds
CSCse92656	7935 does not register G.729a capability along with G.729 capability
CSCsh02684	Change Notification fails to update Digit Analysis. CallForward fails
CSCsq87977	MGCP PRI should prevent repetitive datalink up and down
CSCsh07191	IdleCI not passed via NotifyReq when transfer fails
CSCsh14301	IdleCI not passed via NotifyReq when transfer fails
CSCsd07193	Provide a user identity for call
CSCse69050	TAPI Reports 7941 & 7961 Phones as Unknown Device Types
CSCsf01277	TSP unexpectedly shutdown on application server
CSCsh21570	missing 7906 default load 8.2(1)
7940/7960	
CSCse90516	Animated circle (reset icon) seen continuously in a scenario
CSCse94977	Add new cons for sidecar to support Muster release
CSCsf24624	7960 not allow to select 2nd call of a conference call on shared line

CSCsf23295	A call picked up is not recorded in 'Received calls'.
CSCsf15043	Upgrade LSC menu strings not flushed on moving out of tht menu.
CSCsd83498	7960 stops sending CDP packets - causes do1x error disable switch port
CSCsf03215	Phone remain in Configuring IP state even with proper DHCP response
CSCsf31131	Option 66 preferred over option 150 based on appearance in DHCP ack.
CSCsf31328	7960/40 skinny do not detect handset with failover to SRST
CSCsf98491	Unicode Special Characters blacked out on 7940 and 7960 SCCP phones
CSCsf99236	Several call progress tones need to be louder
CSCsq29621	Secure Conferencing Icons for Muster
CSCsq66095	7960 phone does not calculate srtp authentication tag correctly
CSCsq66121	Placed call list shows '*' for FAC enabled calls
CSCek53592	Secure SCCP Phone Conference Initiator unexpected shutdown on Hangup
CSCsh13470	7940 ph does not accept new req after rejecting invalid IP address req
CSCsq91727	7960 SCCP does not play beep tone when DND incoming alert is configured
CSCsq92860	Phone temporary rejects HTTP connection when its sockets are available
CSCsh31417	Static, white noise heard w/ 7960 7940 logging into unity with G729
CSCsh38467	Update Cisco Logo on phone web pages
CSCsh40436	Update the copyright year to 2007 on the boot display for the mid-range
CSCsh25423	7940/60 not streaming sometimes when using encryption
CSCsh61510	StreamingStatisticsX reports phone as idle when call is active
CSCsf03684	IP phone at remote offices stuck in opening.
CSCsi22745	Transfer call leg connects while held leading to call drop, media leak
CSCeq04628	Resolved the race condition caused by SsManager registration lost due to link issues.
CSCsi26345	Checking in latest tone file for third generation phones.
CSCeb70772	Build phone loads
CSCee71612	JPN-Cancel softkey not available for configuring 7960+7914
CSCsb25081	phone displays Select Ringer... for Invalid DistinctiveRing.xml
CSCsb56074	UI screen is grayed out when i-button is pressed
CSCsc80832	Autodial cancelled is shown for a Phone in RingIn state
CSCsc80901	Phone displays AutoDial Cancel in transfer scenario
CSCsc82124	7960 tries fallback to CCM that has CCM service shut but port 2000 open
CSCsd01460	Phone Softkey should be greyed out for Disable Speakerphone and Headset.
CSCsd58570	7960 produces garbled audio and repeated words for PA Help
CSCsd65718	Softkeys within various Settings submenu not responding if held
CSCsd80952	DN not displayed in a hold scenario after line button press.
CSCsd94166	Init-CallHistory URI does not re-set status line on 7960/7905
CSCsd97560	Phone displays Callmanager parameter as UNDEFINED to boot up process
CSCse02975	revertPriority = Even fails when Hold Reversion call is oldest
CSCse03934	Integrate DSP rev 4.0(2)

CSCse11517	parked calls get loud tone when picked up from 7960/40 on CME 4.0
CSCse29339	Callback can not be activated for a busy extension
CSCse40076	Abbreviate dialing should not be available if phone not able to call
CSCse53264	need to press line button twice to answer an incoming call
CSCse53471	Mute light stays on after audio broadcast is complete
CSCse57394	ST- 7960 secure phone got TLS error with SRST after CCM 4.2.2 upgrade
CSCse62416	one way voice when the timestamp field in the RTP packets rolls back
CSCse67529	RTP Tx URI request should be rejected when a call is active
CSCse71803	7960 does not differentiate local hold call and remote hold call
CSCse77759	40/60 - LA dev size grown above acceptable size limit
CSCse84352	7960 with voice vlan resets if IPC is connected to 3rd vendor switch
CSCsf05274	phone doesn't handle the DHCP next server field and option 66 correctly
CSCsf06674	7960 displays XML error on hitting directories button with French locale
CSCsf07908	Phone hangs with HIGH CPU detected- during EM logout & locales installed
7906/7911/7941/7961/7970/7971	
CSCsi29861	Phone Directory gives incorrect details after upgrade to 8.2.2
CSCsd18550	TNP- keyboard I/O errors on reset
CSCsd62804	7970 phone in low power mode consumes more power than CDP advertisement
CSCsd99957	Phones failover to secondary node with wrong cause code
CSCse28400	Network Locale Version backwards compatibility
CSCse30736	Third gen phone may behave wrong under stress registration test
CSCse47164	3g-phones -- pick up Sun Java patch to address 2007 DST changes
CSCse77453	Hung RS-232 port causes phone upgrade failure
CSCsf07505	7971/7941 re-append parameters with a redirected authentication
CSCsf20589	7914 configured over 15 digit in line number behaves very strange
CSCsf21480	phone UI Locks up when adjust Speaker Volume during registration w/ BLF
CSCsf33010	third gen phones power is initially set high power at boot w/line powered
CSCsf96872	3rd gen phones running 8.0(4)SR1 unable to adjust ringer after a call
CSCsf98288	u7961/41/70 stuck at requesting after phones inbound web access disabled
CSCsf99285	PNG Broken- Phone fails HTTP GET if earlier HTTP request is not finished
CSCsg00560	After flash reformat phone gets flash Programming failure errors
CSCsg05630	Memory Leak on phones with repeated calls with very short call hold time
CSCsg09017	Pressing New Call should let user Enter Number
CSCsg10985	Bugtrap 0x91 phones (during fsck)
CSCsg13753	Composed IPPM messages display + instead of space
CSCsg13871	Unknown name displayed if special characters are in display name
CSCsg15183	Exit softkey stops UI when in Security Configuraiton/CTL File submenu
CSCsg15386	TNP phones on CME can't resume call with Line button

CSCsq16790	make 'DEBUG' trace anticipated for a 1-way audio problem as NOTICE trace
CSCsq17063	Customer is experiencing one way audio calls
CSCsq17247	SenderJoins & Byes values were different regardless of call status
CSCsq20339	GUI stuck after changing contrast
CSCsq21513	Osage- Phone drops incoming unicast EAPOL when VVLAN is present
CSCsq23326	Call duration timer window on ph display cycles between multiple calls
CSCsq29562	Idle sftkeys displayed on new incoming call after transferw/rel image
CSCsq30155	AutoObjInFocusIf.getLabel returns incorrect information for a call item
CSCsq30974	Response.Redirect fails
CSCsq34758	IP Phone SSH Vulnerability
CSCsq36199	Internal calls are having one way audio
CSCsq42627	Filesystem Denial of Service
CSCsq45815	Phone doesn't calculate SRTP auth tag correct for certain RTP payload
CSCsq49636	Stutter Tone quality problem when using speaker / line button
CSCsq50737	Focus should remain on oldest ringing call with mulitple incoming calls
CSCsq63581	Phone displays CM down in a active call during failback
CSCsq73386	7961 phone not show Help info for privacy button
CSCsq83571	No dial tone is heard after togglling the hookswitch in ring out state
CSCsh04378	Focus should remain on oldest ringing call with mulitple incoming calls
CSCsh84369	CallHistory Menu- line key, speaker key, no longer work
CSCsf09122	SIP Phone goes for a reset when proxy address name starts with _
CSCsf32377	phone resets after warning out-of-chunks for memory tracking
CSCsq00140	Caller-id is not updated correctly for conference calls
CSCsq05342	Retrieving a parked conference call, disconnects the call
CSCsq15497	Phone unexpectedly shutdown running Codenomicon SIP test 4913
CSCsq15511	unable to do cfwdall if kpml is enabled in sip-srst mode
CSCsq15653	SIP phone failed to clear Held call when CCM restarted
CSCsq26731	call tranfer after cfw noan on tnp sip phone failed
CSCsq27644	Incorrect Date header value in SIP REGISTER request
CSCsq76651	SIP Phone needs to also detect non-localized Conference
CSCsq81670	Number stored in missed calls not updated upon receipt of SIP UPDATE
CSCsq81884	Not able to Set CallFwdAll on tnp sip phone in particular scenario
CSCsq97988	TNP SIP sometimes sending malformed to or from header
CSCsq98545	7970 sip sends invalid presence subscription causing high CPU
CSCsh12712	Failed on multipl forward from SIP phone to SCCP phones
CSCsh24076	tnpsip phone doesn't light up blflamp when destination press callfwdall
CSCsh41516	Phone unexpectedly shutdown when messages hard button is hit.
CSCsh42357	Call not forwarded after CTINewCallAcceptTimeOut on SIP TNP phone
CSCsh96543	Transcoder is not able to handle correctly locations

CSCec58464	Active Server Pages exception first time CCMUser page is loaded.
CSCsi13106	7936 Phone Displays Host not found when accessing corporate directory
CSCsh26767	Need ability to tag dashes on 12 digits calling party number
CSCsh89461	H225 / SETUP RedirectIE not populated when VMprofile is created w AXL
CSCsh95211	Callmanager Disconnects BRI call with Call State Mismatch
CSCsf17786	Added Prefix on calling num. for inbound calls removed from CDR records
CSCsh81417	CDR Analysis and Reporting does not reflect new DST changes
CSCsi05446	Time Schedules Limitation
CSCsf19873	Calls not transferred to always route member after hold timer expiry
CSCsg87252	WD logs ERROR-WDNotStarted - Failed to startup WebDialer application
CSCsh44003	CCM-DST change does not take effect for Timezone Atlantic Time (Canada)
CSCeh02765	DirectoryConnectionFailed alerts when DNS server unreachable
CSCsh79606	SIP does not return error when failed to open UDP port for SIP trunk
7911/7941/7961/7970/7971	
CSCsf15719	Beep tone max power is only -22dBmO
CSCsd67218	FSCK stuck in deadlock with syslogd
CSCse92116	Enumeration Pattern Code Updates
CSCsd89584	Phone sends corrupted RFC2833 packets when SRTP enabled for call
CSCsf29401	Dev Studio changes to make building Communicator easier
CSCsd91409	Secure phone does not retrieve the SEP file
CSCsc87057	7931- Call Plane Detail View is not open after On-Hook dialing
CSCse15702	CiscoIPPhoneStatusFile LocationX parm not used for small image size
CSCeq36199	Commit of CSCef34402 broke c6slc, other? pikespeak images
CSCsd63834	Titan dsp host could 32-bit read between dsp firmware two 16-bit writes
CSCse87239	Osage- Max Input Rxd msg displayed when 32 chars input to Shared Secret
CSCsd93091	Power Save Configuration options missing in Settings
CSCse87259	Osage- Status Messages for 802.1X Authenticatio not as per Osage UI spec
CSCsd09479	softkeys disappear after blind directory transfer
CSCsd18550	TNP- keyboard I/O errors on reset
CSCsf12447	RTCP- Exiting Hoot & Holler cause phone to send bogus BYE packet
CSCsd70128	7931- Exception in OverviewModel during restart
CSCsf08142	Support G.722 56k and 48k in the Audio Server
CSCsf19717	TNP phone logs "Unable to get memory" message on console
CSCsf18819	pressing volume key then speaker button can lock up phone
CSCsg65954	G.722 K-Factor Table incorrect
CSCsd43768	Highlighted Call isn't displayed if 10th call ended leaving 9 held calls
CSCsf26570	7970/7961- dtmf burst is played with a double duration
CSCsf12118	Phone does not send un-register message to SRST on fallback to CCM

CSCsq38354	7931- Pressing Line button does not change Line focus
CSCsf05690	Onhook dialing produces delay in feedback sound with last digit
CSCsf05975	IP phone fails to do HTTP authentication
CSCse86158	7931- Overview not in home position at initial bootup
CSCsq21884	RTCP socket open error may cause audioserver to spin
CSCsd73061	under is only 20 chars instead of 64
CSCsf00759	Dynamic Trace level registration results in file create/delete operation
CSCsq55535	EAP-Request/MD5 to PC supplicant could not pass thru Gig phone
CSCse44215	Static Analysis Codebase Cleaning on Select Files
CSCse18921	7961 phones not processing CTI request to disable softkey
CSCse45888	TNP- dhcpRcv.c - uninitialized variable
CSCsd67273	7970- Phone lock up when message URL has max or 255 character
CSCse82997	IP Phone should re-DHCP immediately after DHCP NAK
CSCsd79071	7931- scroll up and down, sometimes a leftover icon appear next to label
CSCse80623	show inventory command returns no data
CSCse95050	RTCP- SDES packets are not being padded correctly
CSCse97625	Idle Prompt for SRST cannot be set back to the default value
CSCsd09502	Phone not sending DHCP traffic to pc port
CSCsd97505	Unable to dial from external dir list after cancel edit dial
CSCsd49711	LCD display does not always show status of 3 consecutive lines
CSCsf03133	7911G experiences loss of registration
CSCse19950	SIP phone show "Connected" in call preservation if user in/out line disp
CSCse55467	7961 with voice vlan resets if IPC is connected to 3rd vendor switch
CSCse47227	Static Analysis Codebase Cleaning on Select Files
CSCse26349	Ringing phone ICON keep showing up on the phone display without call
CSCsd68818	Skittles- Retain Dialplan from CCM while failing over to SRST
CSCsf03176	IP phone not direct HTTP request to proxy server w/ unresolved DNS name
CSCse22141	Phone does not have "End Option" field with DHCP Release message
CSCse54581	RTP Tx URI request should be rejected when a call is active
CSCsd07806	goped won't autoscroll to previous line/call in multiline scenarios
CSCsf96872	3rd gen phones running 8.0(4)SR1 unable to adjust ringer after a call
CSCsd64397	When uri is not responded by user, second uri post just hangs forever
CSCsd37539	Clean up debug options available / messages
CSCsd78959	Line DN label appear to be shifted a pixel or two to the left on Display
CSCse33310	Digit tone improperly continues until call connect
CSCsf19754	JPN hone freeze at Cisco Logo after reset due to Java OutOfMemory error.
CSCse50522	7961/70 fail to transfer a call with line 2 from Directory
CSCsd43749	TNP- Remove NULL term from hostname in DHCP request
CSCse77484	7971 displays "Ethernet Disconnected" briefly

CSCse95262	Phone core dump when terminating mulitple calls
CSCsd76840	phone not fallback to CCM and shows "Restarting...".
CSCse83946	Enumeration Pattern Code Update
CSCsd84325	Mute Button is enabled when Phone Speaker Button throws Error pass Limit
CSCsd70047	On turbo the overview is distorted when a new call is created and ended.
CSCse90988	Osage- Transaction Status does not update unless menu is re-entered
CSCse85549	TNP SIP phone uses wrong default TLS port number
CSCsc04450	Handsfree Receive Frequency Response does not meet the mask
CSCse64194	debugsh- set LOG_DEBUG trace level for sunvm.cnuw/ debug SIP/JVM command
CSCsd55099	Phone does not detect Invalid Load Server IP address for "A.B.C D"
CSCsd79565	Phone Ringsin Continuously,Need to power off/on to clear the call
CSCsd81691	7911 SLR is 5 dB softer than required, its ok in GL mode
CSCse37151	IPPM- Phone displays XML Parse Error when accessing Contact List
CSCse08120	7961 - PC cannot see data traffic if PC Voice VLAN Access is disabled
CSCse98992	TNP SIP phone can not handle long Unicode callid/linetext
CSCsd86740	7931- Clean up OverviewModel ACTIVATE_REQUEST event handler
CSCse51561	7970 Runs out of memory as phone when idle URL is used
CSCsd29434	7931- Phone looses softkeys when exit from IDLE URL screen
CSCse85554	Incorrect values in RX/TX_START_TIME and/or REPORT_TIME pegs
CSCsd44087	Soft factory reset does not clean files from /etc/sfr.tab
CSCse96263	RTCP- With RTCP disabled web StreamingStats Report Times are invalid
CSCsq12952	Include Kernel.core into the syslog files for debug purpose
CSCsd64178	Not able to use Dial Sofkey in Corporate Directory
CSCsd85364	TCP not sending all posted data after socket close
CSCsd09043	7911/41/61/70/71 - 2 concurrent XML posts result in Error 0 or Error 6
CSCse79085	devoplement build (TNP) script does not work
CSCsd49434	Dial Softkey should be disabled for corporate directory/PAB/FastDials
CSCsd83812	Turbo- DoS tool icmpsic crahses phone on Bugtrap 0x93
CSCsq42627	Unmount Error
CSCsd37846	HTTP sessions are not currently aged-out
CSCse99747	CreateStringMatchProperty does not update the allowedValues
CSCse83990	TNP - 7911 phone needs an 802.1X port lookup mechanism
CSCse24219	9 lines with call in Hold Reversion, phone stops ringing
CSCsb46877	provide for next generation static analysis for TNP
CSCse96188	RTCP- BYE packet has padding bit mistakenly set
CSCse30359	7941/7961/7970/7971 Aliasing in high band when using wideband headset
CSCsd69876	7931- LineFullDisplay detail is missing from the title
CSCsd76234	Call History Enhancements for Chumbawamba Phase 1
CSCsd78852	7970- reduce msg sizes being used in network daemon IPC

CSCse35569	Static Analysis Codebase Cleaning on Select Files
CSCsd52772	When calls are selected/unselected, sorting is done immediately
CSCse83972	TNP - 7971G-GE forwards 802.1X packets twice
CSCsg15183	Exit softkey stops UI when in Security Configuraiton/CTL File submenu
CSCse96540	7931- May have a Java Memory leak in disposeDynamicFeature
CSCse36773	Static Analysis Codebase Cleaning on Select Files
CSCsf01932	IP phone stuck at Cisco Logo screen when reset from CCM w/ sidecar
CSCsd81490	Can not login to phone during automation testing
CSCse15637	support persistent status line display on SIP phone in SRST mode
CSCse88493	Phone throws exception upon going off-hook
CSCsd04472	Dial URI w/ Active Call doesn't Invoke Call Options when no app in focus
CSCse53351	Static Analysis Codebase Cleaning on Select Files
CSCsd79080	7931 Titles in Line FullDisplay aren't left aligned at at the same place
CSCsf30327	Phone continues to ring after shared line picks up a transfered call
CSCsd81214	mipsacker not use CNU versioning for BN2 image
CSCsd78939	7931- Line number overlayed with ellipses ... while in active call
CSCsd52432	7970 SCCP requires Authorization when hitting **# to unlock the phone
CSCse47056	Static Analysis Codebase Cleaning on Select Files
CSCsd74992	Phone Service unavailability message corrupted
CSCse09491	UDI Time Zone not displaying string from phone config file
CSCsc04455	7931- Handsfree RLR does not meet the spec
CSCsd85222	Phone not showing "Duplicate IP Adress" in status line
CSCse63028	HOST Field Send IP Address Instead of Defined Hostname
CSCsf05922	7911 Phone speed and duplex settings not saved
CSCse51724	CP-7971 does not cache TFTP address if option 66 set TFTP server name.
CSCsd62215	TNP phone sends StationSubscriptionStatReqMessage at restart
CSCsc76316	Focus changes to the new ringing call before 10 secs..
CSCsf22484	Reset on sleep mode phone would not put it back to sleep mode
CSCsd52201	CiscoIPPhoneDirectory/DirectoryEntry/Name should be restricted to 32 cha
CSCse00488	TNP- check return value when writing dhcp.conf
CSCsf03236	Remote in use calls with no caller ID should display "To Unknown Number"
CSCsd56616	Sanity- Core produced for rtsp on restriciting incoming bandwidth/bitrat
CSCse32438	Fragile file cleanup and performance enhancements (Jasmine featurette)
CSCsd32478	7931- Tuk Tuk noise heard while using wideband codec for a call
CSCsc85514	7970 Phones have incorrect active display during shared line call
CSCse41742	SIP phone should reattempt download of softkey&dp on TFTP down/ timeout
CSCsd44691	For Cbarg "CM down,features disabled" message not displaying on 7970
CSCsd69706	7931- Headset icon not displayed when Headset LED is pressed
CSCsg24774	Expand Directory object name field to accept 64 characters

CSCse90950	7931- Softkeys disappear with 4 sofkey templates
CSCse81719	7971 should set Audio Preference to default values after Erase
CSCsf21394	Muffled voice on receive for some calls
CSCsf98469	cnu recover second look
CSCsb11808	7911- GroupPickUp does not work
CSCsg13871	Unknown name displayed if special characters are in display name
CSCse14839	7970-DHCP- Rejects DHCP request with option 15 from CNR
CSCsd43833	Display on shared-lines not-in-call is not consistent in cBarge scenario
CSCse93844	7931- Incorrect call appearance on shared trunk monitor calls.
CSCse84180	Call Focus shifts to Held call for consultative conference call leg
CSCse89302	TNP - Soft factory reset should clear 802.1X PAE info
CSCse67581	7931- Enable video support
CSCsd84321	Focus is on wrong call when line view is opened indirectly
CSCsd99303	Change the 7906 BN2 to use RELEASE keys for pilot build
CSCse82739	Turbo should not advertise G.722
CSCse16009	Dynamic features like BLF Speed dial and Privacy are not working
CSCse09914	Call fails when no dialplan and registered to SRST
CSCsd80603	Conference on Alerting with 8-0-2-4S load
CSCse78669	Update 7911 diagnostics to version 10.02.00.06
CSCsg06474	CNU kernel BugTrap 0x91 with V-E-R-Y specific conditions
CSCsd79795	TNP phone stuck in blank screen during upgrade to 8.0(3) load
CSCsf32985	third-gen phone 8.2(1) recover process is not displayed
CSCsd57619	dsp ingress frame timestamp not following RTP RFC3550
CSCsc21404	sleep() system call not POSIX compliant
CSCsd84327	AbbrDial key shouldnot be active when speakerbutton is disabled
CSCsf04520	Text Item Displays are not right justified in RTL locales
CSCsf09537	Phone should explicitly turn on display when reset/lost registration
CSCse72995	SIP phones should Ignore unknown softkey set names in softkey xml
CSCse08762	7931- Add icons to the DetailsFullDisplay
CSCsd70236	CIA-680 Support on 3rd gen phones
CSCse00577	revertPriority setting not used for 1st call after changing the setting
CSCse45417	Third-Gen phones running 8.0(3) do not hear multicast audio from RTPMRx
CSCsg38765	8.2 phone load causes robotic issue at customer site
CSCse18857	Dialplan is not supported when Failover to SRST
CSCsf25202	Highband noise reduction tuning
CSCsg10985	Bugtrap 0x91 phones (during fsck)
CSCse62574	unable to disable kpml on TNP phone registered to CME
CSCse95271	TNP- send DISCOVERs if no DHCP server can be found
CSCsf04633	IP phone reset with DOS attack

CSCsd75099	7941/61 LCD controller must be reset at startup time.
CSCsf26773	Arabic locale missed QRT on dest info
CSCsd65226	Empty Dial list is getting displayed on phone
CSCse57780	Static Analysis Codebase Cleaning on Select Files
CSCsd85188	Default router entry removed when dup ip present
CSCsf08177	Can not press line 36 on 7970 with 2 sidecars
CSCse29790	7931- Unable to answer call on 2nd line using phone handset
CSCsd80152	"On " prompt doesn't always work
CSCse48429	Static Analysis Codebase Cleaning on Select Files
CSCsd59892	TNP- "show inventory" CLI output not adhering to the specification
CSCse26257	redial sk is not active in onhook state
CSCse64290	getEndPointInfo reports MWI setting incorrectly
CSCse80382	vm -mem broken on Broadcomm platform (7941/61, 7970/71) 8-2-0-20
CSCsc51528	LCD display shows status of Lines 22-24 after phone boots up not 1-3
CSCsd57320	Turbo- DHCP recv socket error on bad address
CSCsf07282	7961GE stops receiving EAP-Req/ID during long duration reset test
CSCse43046	Static Analysis Codebase Cleaning on Select Files
CSCsc97023	7931- Doesn't show IDLE display on phone display after restart from CME
CSCse88507	TNP phone fails to display the switch info at its webpage
CSCsd40919	7970-PNG image file download unexpectedly shutdown the phone
CSCse89295	SYN ACK messages from phone not DSCP tagged
CSCsd81130	Jphone- Navigate problem under network statistics menu when debug mode
CSCse02587	make property retrieval from RMS store file effecient
CSCsc04453	Handsfree SLR does not meet the spec
CSCse56426	Static Analysis Codebase Cleaning on Select Files
CSCse01424	Add volume control for local and network tone
CSCsd85542	7931- Speed dial does not display called-id when another line offhook
CSCse98085	Selective graying out of AudioPref menu items incorrect on inline power
CSCsd91853	Placed calls are not multi-party and should not show a MP call history
CSCsd79623	Phone Continuously displays "Requesting...".
CSCsd78880	Softkey wrong after fallback from SRST
CSCse91631	7961 (and 7941,7970,7971) doesn't display Call park number after getting
CSCse50704	Static Analysis Codebase Cleaning on Select Files
CSCse53354	Static Analysis Codebase Cleaning on Select Files
CSCsd68366	7931-UI shows lines 22-24 when line button pressed with AppMenu Open
CSCse69979	Settings -> Device Configuration -> UI Configuration menu is missing
CSCsd91709	Call History Lists inaccessible after having max entries and deleting 1
CSCse01609	7931- Phone restart from CM duration test leads to Disk full
CSCse97273	Add SIP related changes to support G722 for ph0 of wide world

CSCsf96907	Missing Pixels on the left side of UI displays on Turbo phones
CSCse98510	phones should not advertise Voice VLAN on PC port
CSCse12436	JTest- SIPCCAdapter.java switch statement missing breaks
CSCsd71678	7931- Factory Reset Walk LED pattern is only 16
CSCsd97985	7971 phone reverts to old config after changes saved to netwk config
CSCse93985	7931- LEDs for lines above 8 do not illuminate
CSCse87188	debugsh should support RTCP trace
CSCse06889	Cfwdall fails to come back on CCM after fallback from SRST
CSCsd98825	7914 displays old version of remote-in-use icon
CSCse72058	Line LED not lighting up or delayed on incoming calls
CSCsf96938	Phone display not turned on when going into reverting state
CSCse87178	TNP SIP Phone resets after auto register due to default load info missin
CSCsf99285	PNG Broken- Phone fails HTTP GET if earlier HTTP request is not finished
CSCsd60107	Pushing RTPRx or RTPMRx URI to phone in a call enables mute
CSCsf01754	Call Statistics menu- Sender size is not a correct format
CSCsd13820	SIP phone UI Locks up and Keypresses ignored (still registered w/ CCM)
CSCse86764	UI locks up & phone cannot register
CSCsf13754	Timer Exception seen in TimeDateRequest
CSCsd92883	Clear softkey does not work in Status messages screen
CSCsf26575	Outgoing ringing and incoming ringing tones played at same time
CSCse28309	apply patch for Diab compiler from WindRiver
CSCsd96571	Add new tone messages to make traditional/stutter tones selectable
CSCsc98937	Phone accepting duplicate IP
CSCse44210	Static Analysis Codebase Cleaning on Select Files
CSCsf00501	7911, 7906,7931 & 7921 have poor voice quality with G711alaw codec
CSCsd78556	Out of Memory - Connection refused errors after duration testing
CSCsd51277	Turbo- 1st incoming call can't be answer if 2nd one be connected first
CSCsf14115	RTCP- RR/SR packet is missing some info when there is 2 report blocks
CSCsf00640	SIP gives different Error message than SCCP in Locations scenario
CSCsd59904	7931- IDLE URL Refresh timer doesn't work in 66DEV image
CSCsf15839	Shared line display & going offhook while in active call distort display
CSCse11178	Write to the TNETV105x PCNTRL "Access Control Reg" must be 16 bit
CSCsf09292	TNP- libcso.map from build should be saved
CSCse66794	New Features - Auto Call Select and More Key Timer
CSCsd22589	7931- Leave 1 pixel space w.r.t. App Menu/Headset/etc
CSCsd17448	Line reports as unregistered, but it's not, after failover
CSCse54754	Re-sync tone table if dsp host re-starts
CSCsf24260	Phone core dump while running the call features automation script
CSCsd85217	Phone not retrying the re-IP after dup IP

CSCse41381	7961/41 Speaker LED on even after pushing End key
CSCsc53412	SETTINGS softkey does not work if no DHCP server available during bootup
CSCsd99012	mount command exiting with status code 64
CSCse95317	KATE Input causes NPE and non-password data while using XML services
CSCsf98288	u7961/41/70 stuck at requesting after phones inbound web access disabled
CSCsg28219	SCCP phone does not register back to publisher after restart.
CSCse13185	Need an API to assign a local port to TLS connect
CSCsc76330	LineModel dispose call throwing a ClassCastException
CSCse44801	Static Analysis Codebase Cleaning on Select Files
CSCse41046	Dialer does not close correctly after Cancel or Idle Timer Expires
CSCsf32526	Need filter coefficients for headset, handset and speakerphone
CSCse48428	Static Analysis Codebase Cleaning on Select Files
CSCsd91823	Multi-Party Call History - Transfer case - Received call "from" details
CSCsf96424	Audio Server K-Factor table for G.722
CSCsa63664	CNU Flash Filesystem not recoverable if it fills up
CSCsd92798	certcnu.bin failure- GETCNU- CNU image update failure; code = 10
CSCse03001	Status of BLF SpeedDial does not get updated.
CSCse03136	need feature parity between sip and sccp phone for speed-dial
CSCsf01523	Endcall softkey doesn't work in Call Preservation
CSCsd96540	Answer and DnD Softkeys are not always displayed when a call is rcvd
CSCsf08522	softkey disappears on the phone after several calls are made
CSCsf04327	7970 precedence call waiting tone does not stop
CSCse76372	Issue with Pegs when the call is remotely held and on MOH
CSCsd59303	wrong filepath used after posting a TFTP file
CSCsf29404	Phone should send the 433 Anonymity Disallowed for anonymous calls
CSCse63732	Diagnostic is always reloaded into the primary slot
CSCse06992	Turbo- Speed dial entries not at designated position
CSCse62809	Calling/Called Info not correct for SIP TNP phones
CSCsd43847	Double call sort after ending selected call
CSCsg88504	ccmuser- add IIS monitor similar to ccmadmin, ccmcip
CSCsg81459	Can't update phones in cm4.2(3) when all parameters are field
CSCsg22098	can't update phones in cm4.2(3) - urlscan reject maxquery string exceed
CSCsd98221	Media Layer Does Not Correctly Establish MasterSlaveDetermination
CSCsg83588	Transfer to busy user causes Unity port hang
CSCse06780	MGCP BRI 3.1 Khz Support
CSCsg87647	Adding 8.2(1) features to CCM 3.3, 4.1, 4.2, 5.0
CSCsg53781	SW MTP/CRA RTP timestamp resets without SSRC changing
CSCsd79833	SIP Trunk w/o MTP to H.323 w/OFS results in no TCS and no T38
CSCsg55161	CFA failing.

CSCsd03617	AXL addLine and updateLine report wrong error
CSCsg58365	Callback fails / unreliable when Publisher is down.
CSCsg23692	CCM releases the call when it receives Status in call_received7 state
CSCdz25157	NewCall and EndCall should not be mandatory softkeys
CSCsg32819	BARS not updating CCM03xx DB name in Monitor Disk Space job on Restore
7985	
CSCse21503	Packets received on PC port are not forwarded in some configurations
CSCsd39465	7985 does not display animated icon w/ RTPRx
CSCse54965	Restart reason sometimes is not correct under Network status
CSCsd36788	Phone can rarely stop making calls after CCM failover/failback
CSCsc14484	Confrence List Remove feature does not work on CCM 5.0
CSCsd55735	Invalid dialed number when dialed from directory displays no information
CSCsd27788	Callback Notification window does not close after Dial is pressed
CSCsd39338	Phone sometimes does not fallback to the correct Standby CCM
CSCsd75862	Wrong display of softkey sets and callinfo on IPMA assistant phone
CSCsd71764	IPMA manager should not exit from IPMA service w/ 1 assistant
CSCse73518	Phone did not register with the Call Manager after a network power loss
CSCse06703	Phone unexpectedly reset during a long duration H.263 call
CSCsd89221	Some softkeys not work correctly with CiscoIPPhoneInput object
CSCsf32885	7985 phone not working with Mobile Connect service. (CMM/SNR)
CSCsd77139	7985 un-registers from the Call Manager after the switch speed changed
CSCsd90282	Network status should contain last restart reason
CSCse26188	Hoot & Holler service does not display Handset icon with RTP/Rx RTP/Tx
CSCsc84363	Visual call Pickup notification fails when line audio alert setting off
CSCse92536	7985- Ignore CDP V1 message for VLAN configuration purposes
CSCse26167	Equation type input can have unexpected delay when pressing numbers
CSCsd13306	Pressing a number in Ring Tone menu works differently than other phones
CSCsc68289	There is no Call Status information available via the web pages
CSCse00330	7985 appends devicename in HTTP request when searching directory users
CSCse55039	Changing volume during the Hoot & Holler service cause audio to be sent
CSCse55034	Hoot & Holler icon was not removed after exiting the service
CSCse01536	Background image after download is obscured by the image menu
CSCsd42341	7985 can not handle URL with 255 char.
CSCse27352	PC Voice VLAN disabled does not work with Admin VLAN
CSCse60244	IPPA phone service shows some unexpected error messages when logging in
CSCsg68763	Call accross ICTs may fail when hold or transfer
CSCsg68724	Call accross ICT trunks may fail when hold or transfer
CSCsg32517	CTI Ports/Route Points do not go in service after reset

CSCsf32240	Overlap Sending broken when using redial function while phone is onhook
CSCsg73165	Incorrect DNIS in the CDR when using speedial and Route Pattern Overlap
CSCsg53729	Error on Service Parameter on CCMAAdmin
CSCef58219	CallManager should handle T1-CAS incoming call after GW channel OOS
CSCsg60213	CallManager MGCP T1 CAS Channels Must Recover from Out of Service (OOS).
CSCsg68011	OpenSSL DoS vulnerabilites- CVE-2006-2937 & CVE-2006-2940
CSCsg26516	ccm.exe unexpectedly shutdown with c0000005(access violation) due to SIPHandler thread
CSCsc62073	Locations Out of Bandwidth causes unexpected Unity Failover
CSCsd35843	Aupair unexpected shutdown On 51st NCS Connection Request
CSCse63793	CCM reporting encodingStyle as ISO-8859-1 instead of an http URL
CSCsf07523	Update needed for N America DST changes in 2007

Resolved Caveats for 4.1(3)es72 - Base ES for 4.1(3)sr4d & sr4b

CSCse78153	RTMT does not work on winos 2000.4.3a or 4.3SR1
CSCsd98221	Media Layer Does Not Correctly Establish MasterSlaveDetermination
CSCse72798	Meet Me Conference is released when CallManager is down.
CSCse85155	Callmanager Fails To Remove First Call Leg During Blind Transfer
CSCse58998	CTI shall unregister ssmanager, then register ssmanager at failover time
CSCsc49709	update/add Phone do not allow userLocale/networkLocale for Cisco7920.
CSCse80961	CTIProvider is not closed when WebDialer is deactivated
CSCse01700	Jphone software changes to address Memorex enhancements in EDCS-505798
CSCse43433	Support RTCP featurette
CSCse84481	Add nightlight features
CSCse78257	MGCP GW reset due to message order changed
CSCse83645	CCM.exe process shows very high memory usage
CSCeq88830	callmanager generate same confernceID for h323 gateway call
CSCse48918	15 seconds delay when using speeddial for forwarding from AC
CSCsd18730	JTAPI modified calling party number overwrten at Route List
CSCse82801	SIP trunk stuck in a Shutting_Down state can not be reset
CSCse29071	beeps for CFwdAll confirmation and cancellation, 7941,7961,7971
CSCse66661	QSIG-ccm.exe unexpectedly shutdown by overrunning the display[32] buffer
CSCsd94511	CTI manager running high CPU with CTIERR_DEVICE_SHUTTING_DOWN errors
CSCse66775	listUserByName-Bad search filter error if no lastName expr given
CSCse36638	CCM tears down all calls on t1-cas trunk if one timeslot reports 5XX err
CSCsd53973	CtiQbeProviderUnexpected Shutdown after device unassociated with user
CSCse61109	CM sends wrong coding standard in Progress PI
CSCse30619	JTAPI-TransferEnd event delivered after station/line call cleared

CSCse32230	Desktop loses 3rd party call ctrl after consult xfer- personal call back
CSCse43154	DM table out of sync..SCCP handling of linkOOS
CSCse43391	DM table out of sync..Device manager handling of linkOOS
CSCsd30363	Maketypes needs run after Product CSV's added to branch
CSCse55217	Add 7921 support files (CSV, XML, GIF) to CCM
CSCse53300	ST-CCM service could not come up after upgrade
CSCse28092	CCM AC-Calls do not come out of Queue
CSCsc64303	CCM SIP Local Call Transfer encounter no audio with 3rd party PBX
CSCsc79421	UnknownCallerIdFlag is not checked for calling party number for mgcp
CSCsd87675	SIP trunk sends two different invites with the same branch ID
CSCse48041	T1-CAS MGCP to CM may fail inbound calls but work for outbound calls
CSCsb59858	Blank directory search from IPMA pages returns 0 users for AD or ND
CSCse33780	Removing a line from H.323 device causes CDBLException
CSCse39414	Non default device load popup incorrectly lists multiple 7914 loads
CSCse44026	CAR tool is not showing destination CMR in CDR> Search by User/Extension
CSCsc83171	First call to MGCP FXS port fails after CCM service restarts.
CSCse40889	Callmanager may get duplicate entries for same region pair
CSCse42819	Redial delayed while SDL tracing is off
CSCse43228	Calls to a MGCP PRI fail from a H323 device
CSCse44016	Blind xfer failure
CSCse09304	Call park number is not displayed after getting a new call
CSCse44352	Calls fail when CFall to a CTI RP redirects to another CTIRP.
CSCse01285	Agent logoff after xfer creates call on callclosed event.
CSCse28494	JTAPI caches invalid Device and Line Handles
CSCsb14724	always use prime line = true -> on hook dial not working
CSCse21694	Cdcc sends SsMoveInd to TransferManager, but ignored due to CSCsc67021
CSCse27147	huntlist hunt option changes do not take effect until reboot
CSCsd95583	Reset of MGCP Endpoints in CallManager causes failure, after 4.1(3)sr3a
CSCse12129	Incorrect Redirecting Reason set to DMS with iDivert to VM
CSCse28346	MGCP not passing reason code from PROGRESS to call control
CSCse31596	Device Package installation has dialog come up in silent mode
CSCse17132	Link 'View the User Guide for your phone' not available for 7961/7941
CSCsd96174	Distinctive ring not work when IP Phone has a active call.
CSCse28510	High CPU and Code Yellow on CM because of new call loop with vg248
CSCee93063	Callback fails / unreliable when Publisher is down
CSCsb25694	Calling party number contains number prefix when forwarded to PSTN
CSCsd17222	Call from PSTN (DMS-100) to Cisco CallManager failed due to NOTIFY msg.
CSCse23458	KeepAlive Events (3) To Provide TCP Port Number
CSCse21158	Always Route Member not enabled with AXL addAttendantConsoleHuntGroup

CSCse17114	7920 Phone Type reported as Unknown in TAPI
CSCse09209	TCP Port not closed after open during load test for H323 Calls
CSCse15368	MGCP->h323->iphone call dropped after 8 seconds of being on hold
CSCse18827	CCMUser should use FastAccess to get locale information
CSCse01285	Agent logoff after xfer creates call on callclosed event.
CSCsa80421	CM sends Progress message without PI causing PBX to drop the call
CSCsd58483	Resource Unavailable cause releases PSTN call via H.323 Gateway
CSCse05527	Wrong cause code when a call forwarded to Hunt Pilot not answered
CSCse13526	CallManager loses CSS for Line so can't route call
CSCse13632	7914 Non-default device load only displays 1 module
CSCeb74323	MeetMe conference leak causes reorder tone on initiating MeetMe
CSCsd79553	Callmanager won't play re-order tone for Cause 0x809D Facility rejected
CSCsd97462	Multiple calls with no ring for subsequent calls when a call drops
CSCsd99801	MonitorPartyTable leak causes continuous appearances of Code Yellow
CSCsd89514	Add code for RISDC to handle second DBL Exception
CSCsc93988	960 One button Login Failure with @ character in the password
CSCsc89249	CM Video-VCB Resource counts not changing for first video participant
CSCsd98033	CallManager should support RFC3398, or strip ;npdi
CSCeg43615	JTAPI Gateway receives RESOURCE_NOT_AVAILABLE error
CSCef12989	Route/Hunt list is not displaying the correct status.
CSCsd97519	Synching DBLEnums.asp and .js from share directory
CSCsd79863	CCMUser can't delete the service URL after unsubscribing the service
CSCse00499	Make 7906 (turboprop) appear in device defaults and device pulldown FCS
CSCse04367	7906/7911- Checkin user guide and update CSV files for online user guide
CSCsd45007	Name ChangeCisco Unified CallManager 4.2 - ES/SR Wrapper
CSCsd87878	QED (CSV and Display XML file) Changes for Phase 2 Ocuis 7985
CSCsd70236	CIA-680 Support on 3rd gen phones
CSCsd77284	CCMAdmin should not offer option of 72XX voice platform as a MGCP GW
CSCsd39649	Calls to BRI gateway from 2nd node fail after 1st node CCM is restarted
CSCsd80077	Decommissioned Server Not Removed
CSCsd55124	Intermittently failing to change CFA number by Netwise application
CSCsd88223	InsertCDR needs to better handle deadlock on calldetailrecord
CSCsd90384	Non default device load popup does not list load for 7914
CSCeg52684	CMR data not being loaded by CAR consistently - Call QoS shows NA
CSCsd86705	CAR needs to remove loader validation for directory number
CSCee69129	BAT does not allow entry of 2 line and 4 speed dial if SD are blank
CSCsa66174	Importing phones into BAT using a comma in the Alerting Name is invalid
CSCsd87772	ENU Coltrane3.0 Check In For English-US Locale
CSCsd49982	AC_J.out.log fills hard drive and 100% CPU for tcdsrv.exe

CSCsd72584	AC call routed to client remains in queue causing new calls to back up
CSCsd87924	Transfer fails when forwarded to CTI ports
CSCsd93062	fwdded calls over QSIG to other vendor voice mail go to open greeting
CSCsc29337	Empty CM Group or Device Pool Insert/Delete Induces CTFTP REBUILD_ALL
CSCsd84607	multiaccess to CCMAdmin page cause high memory usage of dllhost.
CSCsd92758	BAT needs to provide a throttle mechanism to control CPU usage
CSCeq17500	RIS need to handle empty resultset gracefully
CSCsd74769	CCM 4.1.3 sends StopMediaTransmission for incorrect MOH unicast stream
CSCsd63314	AdminUtility display a failure message when try to set IWAM_GUEST pwd
CSCsc16695	Product Specific Configuration Missing from 2821MGCP gateway config page
CSCsd17315	CTI tries to register notifications after app terminates unexpectedly
CSCsd65214	Phones,Gateways dont register when cnf cache SP is changed-ctftp
CSCsd72433	DN config page of 7941G-GE & 7961G-GE shows improper phone icons
CSCsd58388	7941G-GE & 7961G-GE phone Icons are not shown properly
CSCsd78224	Find & List Phones Page gives HTTP Error 500 after SR Install
CSCsb13556	H.323 Tandberg not getting MOH when on hold by SCCP Tandberg
CSCsd27237	Multiple calls with no ring for subsequent calls when a call drops
CSCsd56416	JTAPI error -1932787643 when Apps is answering a consult call
CSCsd61861	Call forward busy on remote node device fails
CSCsd67329	CM Video Bandwidth Unavailable shows for trunk calls with sufficient BW
CSCsd51518	CM Location Resync Bandwidth option doesn't resync video BW too
CSCsd45728	TFTP takes too long to act on the change from Caching to Non-Caching
CSCsd47035	AXL update of BusyTrigger tag fails
CSCsa99093	Number OfJTAPI Traces Is Limited To 100
CSCsd43857	JTAPI doesn't drop ExternalConnection
CSCsd61551	Qsig callback and MWI between clusters are failing
CSCsb93663	Auto Pickup causes incorrect connected name on requestor phone display
CSCsc71873	NumDevRegExceeded- Number of registered devices exceededPhones cant REG
CSCsc92724	Forward information is not displayed in a scenario in QSIG
CSCsd00135	Forward switch fails if forward reroute failed due to no route in orig
CSCsd04737	participant is not removed from participant list when request rejected
CSCsd16427	fwdded calls over QSIG to other vendor voice mail go to open greeting
CSCsd22818	Trailing # should be stripped from DivertingLegInfo after call routing
CSCsd23916	CCM reset due to memory access error in MGCP
CSCsd32150	Treat auto pickup as a direct call and display From xxx
CSCsd43646	Error in DeviceManager table leads to False Out Of Resources Condition
CSCsd54037	Notification Indicator Mandatory IE Missing in DMS NOTFIY message.
CSCsc24761	After sending ECS, CCM should send TCS after peer closes its channels
CSCsc57949	DivertingNr should be converted to RedirectingNumber

CSCsd03859	Max value for Forward Max Hop Count needs to be increased
CSCsc06953	Delayed cut-through on low bandwidth pipes with shared lines
CSCsc87316	ART failure adding user to admin group due to referral during ldap Add
CSCsa99905	CFNCExtCallingSearchSpace shared setting not getting reset to default
CSCsb07528	AXL listUserByName does not return user with blank First Name
CSCsb32989	CCM using Active Dir or Netscape Dir Svr AXL search returns no matches
CSCsb50294	AXL addPhone/updatePhone does not save MLPP Domain value
CSCsc49709	update/add Phone do not allow userLocale/networkLocale for Cisco7920.
CSCsd25421	ITA Display of Zero and CAPS O - 7960 Font Display
CSCeh02679	Dash/Underscore is an invalid char in User Group Base but not for DNS/AD
CSCsc49917	CCMAdmin page become hung, iexplore.exe runs at 100%
CSCsc21734	7911 Add support for Vieo
CSCsd21724	Placeholder CDETS for Turboprop Feature Commit
CSCsd40898	Enabling or disabling of CFA from IP Phone intermittently fails
CSCsb28215	7912 Park number is not displayed for a while
CSCsb87792	Join with on going dial call creates extra conf member
CSCsd28860	hold-state softkey set not updated on sccp phone in a scenario.
CSCsd43894	b channels may delay coming in service on MGCP gateway
CSCsc45181	MaxHoldDurationTimeout requires a restart of CCM service
CSCsc49886	RTMT reports LowCallManagerHeartBeatRate for all call processing nodes
CSCsa65681	CDR/CMR Export throws Error if selected date range do not have CDR/CMR's
CSCsb18851	Export CDR/CMR not working in CAR
CSCsc47886	Traffic Summary - Day of Month [Monthly] Report is consuming 100% CPU
CSCsd13544	Incorrect LINE_CALLINFO after lineAddtoConference
CSCsd36176	Call is not getting cleared (keep ringing)at all in Huntlist scenario.
CSCsd03212	CCM stops generating ring-back as it gets H245 LC open
CSCsb47643	Unable to communicate with DCD when SSL enabled
CSCsb68444	Some Serviceability Reports are not generated due to java exception
CSCsd37332	Cannot create new PAB entries from IP phone
CSCsd37356	Can not see the PAB Entry on Search on Phone for specific Nicknames
CSCsd21724	Placeholder CDETS for Turboprop Feature Commit
CSCsd11438	Call placed via 6608 T1-CAS failed when extra digit dialed.
CSCsc89583	Calls to CTI Route Point fail if CCM group is changed
CSCsd26196	MLA removes space character from OU name for AD LDAP access
CSCsd24291	CCMAdmin IPMA config with AD fails if directory query time out
CSCed90602	CMM Echo Cancel Coverage 8 and 16 ms should be removed
CSCsd01343	Back out CSCsb60395 change in ConnectionMediaManager
CSCsd16251	Incorrect 'srcinfo' in Admission Request from CCM, for forwarded calls
CSCsd20373	Optimizations for CIPT uses incorrect ConfigDB

CSCsc85141	RTMT generates directory connection and replication alarms
CSCsc49896	Call transfers over ICT between clusters ring fast busy of dead air.
CSCeg25365	E-mail information erased after PAB entry edited on phone
CSCeg65968	User unable to edit PAB entry if nickname crosses 26 character
CSCsc96583	Unable to allocate PAB entry to PFD service if nickname is >16 character
CSCsc32928	Fast dial from an ip phone 7960/7940 fails for 24 digit numbers
CSCsc95121	unable to add fxs port to a route group
CSCsd21207	Trunk Configuration Page displays productType is 77 below ctrl buttons
CSCsd19710	Incorrectly versioned CiscoCTL Client plugin checked in
CSCsc65738	No DevSpecific event notifications after losing connection with CTIMgr
CSCsd18255	MSSQL remains in Starting State
CSCsa70351	CFNA/CFB External not working for T1 CAS or BRI loopback calls
CSCsb15241	CCM send internal conference bridge number as the connected party number
CSCsb46008	Calling and called parties were swapped in CcSetupCompReq and CcSetupRes
CSCsd06096	No StationOutputStopTone When Onhook Speeddial Matches Overlap RP
CSCsd07174	H.323/ICT conf resource not released when rx empty terminalcapabilityset
CSCsc98627	CTI unexpectedly shutdown more then 16 party ad-hoc conf with CTI device/line monitoring
CSCsd08256	CTL client returns 'No valid server certificate found'
CSCsc50139	Transferred calls to ac pilot are stuck in queue
CSCsc78968	calls to the AC pilot are being rejected with available HG members
CSCsc79529	Call details orphaned in broadcast queue when transfered from Unity
CSCsc67021	Intermittent missing TransferEndEv for some calls
CSCsc70853	CCM unexpectedly shutdown w/ access violation in SoftkeySetMask--SetSoftkeySet
CSCsd02779	Calls to the ACPilot get stuck in queue until manually released
CSCsc51121	Call to Pilot Point from SIP trunk fail
CSCsb43753	Mistreating incoming TCS data capabilities as video capabilities
CSCsc07492	Skinny (G729)-CCM-MGCP calls fail intermittently
CSCsc92382	CM strips first digit of PRI DMS Original Called Party Number
CSCeg42700	Find/List Trunks-Search RP by % works like IsEmpty
CSCsc82255	Unable to login IPMA assistant console

Digital Access WS-X6608

CSCsb49202	6608 Incorrect marking DSCP value to 0
CSCsd36848	6608 shld not automatically clr connection when ICMP unreachable is rcvd
7914	
CSCsa71277	Implement 5.1 features
7906/7911	

CSCse38146	7906/7911 Check in 7906/11 f/w load to CCM
7920	
CSCsd91773	Coltrane 3.0 Firmware Check-In
7935/7936	
CSCsd97794	DTMF tone will not play for consecutive same digits with 7936
7935/7936	
CSCsb07424	Cannot use # or * as first entry while onhook
CSCsb10791	7936 vulnerable to ICMP attacks
CSCsb18666	7936 doesn't send HTTP Get with multi tier DNS names in Directory URL
CSCsb20131	Can't place a call from phone book when it receives a missed call
CSCsb20134	Phone cannot be reset to factory default when Admin passwd is not known
CSCsb20322	Remote party hears echo when 7936 used in glass conference room
CSCsb20525	7936 accepts invalid IP Address and Subnet mask
CSCsb20544	7936 accepts invalid Alternative TFTP Address
CSCsb20549	Access Admin Setup without entering the passcode
CSCsb21170	Web interface allows to change password with different characters
CSCsb24064	7936 Web Interface allows different characters in Phone Book
CSCsb26686	7936 Web interface doesn't prompt for password when phone is restarted.
CSCsb26695	7936 phone retains the meetme session even after the call manager fails
CSCsb30375	phone may not give Error tone when incorrect phone number dialed
CSCsb43148	7936 Editing phone Book doesn't have the asterisk in the required field
CSCsb44208	If call received while editing ring tone and publisher fails, 7936 hangs
CSCsb45210	7936 Web interface accepts alphabets in PING
CSCsb45340	Phone will not accept incoming call while waiting for Ping response
CSCsb45386	7936 Takes long time to register when PINGED with CCM failover
CSCsb58216	Info for Http Port parameter on 7936 web page doesn't show port range.
CSCsb63489	Polycom 7936 allows to change the Ringer settings in Ringing state
CSCsb63538	Phone book entry on the web display is not proper
CSCsb63570	7936 reboots when you configure Admin VLAN id while in active call
CSCsb64694	7936-Call Transfer number is not displaying in SRST mode
CSCsb65940	Park Information retained for a long time.
CSCsb65965	DN not displayed while placing the call on hold & initiating a new call
CSCsb66074	Call initiations fails from the phonebook with CFwdAll
CSCsb68317	Phone registers with Alt TFTP when Alt TFTP Address not specified.
CSCsb68740	Phone hangs when used Diagnostics with CCM failover
CSCsb70688	Mute turns off in this scenario in 7936 version 3-3-7-0

CSCsb94448	Second Call on shared line cannot be resumed or muted
CSCsb95056	7935 & 7936 Polycom phones lockup on failover, loss of call preservation
CSCsb98800	Display issue when Meet-Me number is 10 digit
CSCsc00529	Phone does not accept to change the passcode with valid characters
CSCsc02074	incorrect display on one of the phone in sharedline
CSCsc02085	Incorrect LED status on a phone in sharedline with call waiting enabled
CSCsc21577	7936 won't fallback to a TFTP server once registered to an SRST router
CSCsc22305	7936 Phone use odd RTP port numbers
CSCsc28637	7936 phone with phone load 3-3-8-0 does not work for FAC
CSCsc73221	7936 Outside dial tone sounds the same as inside dial tone
CSCsc88849	Call gets disconnected if we press hold & resume multiple times
CSCsd33539	7936 does not play tone 50 (Zip) when someone joins a conference
CSCsd38899	Phone display is incorrect when a bogus phone load is entered.
CSCsd41426	Phone doesn't ring when **8 is executed
CSCsd41429	Phone hangs during failback and failover with meetme
CSCsd42025	Phone displays Registering after CCM failover in a active call
CSCsd44837	Dial tone stops when phone receives a missed call
7940/7960	
CSCee36823	7960 phone does not clear status line during reset
CSCsa77085	pressing line button on ipphone doesn't switch between detail &overview
CSCsb26738	Posting Line34 URI enables Line30 on ip phone.
CSCsb95190	7960- Does not preserve the state of mute/spkr button in handset mode
CSCsb95223	7960 drops the incoming call when using the IPICS services.
CSCsc03900	7960 phone does not handle HTTP code 401 for push request
CSCsc07069	Phone- Authentication username/password takes only 31 characters
CSCsc11646	CiscoIPPhoneInput takes * and # when input is set to N
CSCsc13964	StreamingStatisticsX not backwards compatible
CSCsc14352	7960- Call being on hold is NOT sorted by Select function
CSCsc18929	7960- Doesn't update CDP cache when no voice vlan present in CDP message
CSCsc21946	7960 DSP Logging utility broken
CSCsc22618	7960 does not display via XSI Object Pass through
CSCsc27687	IP reassembly broken
CSCsc32693	IP phones become unregistered from both SRST and CM
CSCsc33230	7960/7940 phone stuck at CONFIG IP after a reset/power cycle
CSCsc37550	Phone load Upgrade to 7.2(3) causes RXshort errors on PC port
CSCsc40311	Phone drops untagged PC Traffic
CSCsc43593	HTTP 100 Continue from phone malformed
CSCsc45316	Remove use of linked directory in SCCP BA

CSCsc45445	7960 - XML Debug PUSH behaves erratically
CSCsc45748	Handle Current Call missing when dialing from Directory
CSCsc51551	Phone rejects menu responses from server- Fastdial, Corp Dir
CSCsc52668	Callback notif (Dial) & Park while already in an active call fails.
CSCsc53596	GARP enable/disable ignored
CSCsc54373	The phone unexpectedly shutdown when it receives invalid Response.ContentType in HTTP
CSCsc54415	Secure Phones does n't cancel tftp request while cancel key is pressed
CSCsc57815	7940/60 PC port 100M does not receive network traffic intermittently
CSCsc59606	7960/7940 Rcvr Lost Pkt reports as a negative no under impairment
CSCsc65264	Unable to dial the CB notified number during ringing state
CSCsc70168	No sidetone during first phone call following phone registration
CSCsc75013	Phone performs unneeded ARP when Garp enabled
CSCsc75035	Phone removes ARP entries too quickly
CSCsc75070	help for settings button not displayed when setting key is disabled.
CSCsc80813	DHCP enabled Phone resets with held call when alternateTFTP changed
CSCsc80998	Phone doesn't display held call in detail view when barged call ends
CSCsc89130	Prompts is Truncated to 20 Characters when using Greek Locale
CSCsc94714	Phone resets if we dial Half of the DN on-hook & remaining off-hook
CSCsd09389	Speed dial from Monitor DN is not working with 7.2.2
CSCsd31183	phone display Remote-In-Use menu when the other end resume the call
CSCsd40688	DIALED Number missing in CFA where the target phone is 7940/60 SCCP
CSCsd52418	Update 7960 built-in font to include new zero with a slash
CSCsd53605	7960/40 cannot register in authenticated mode CCM 4.1.X OS 2000.4.2
CSCsd54481	Phone resets during high bandwidth traffic to PC
CSCsd82762	Placed calls are recorded on all shared line phones
CSCsd98269	Missing SpeedDials on phone after upgrading the phoneload
CSCsd98799	7960 unexpectedly shutdown when more than 20 calls placed via stress script
CSCse26309	Placed call list under directory gets updated only for Connected calls
CSCse31121	7960- Unable to reset phone when other shared line is busy
CSCse34272	Phone strip dialed Number in Directory Placed call list for PSTN call
CSCef39491	Phone without DHCP cant recover Dup IP address
CSCsa811337	960/7940 characters by pressing '0' with li-ffr.4-1-3-JPN are funny.
CSCsa83092	help symbol missing in text press - key to cancel for english locale
CSCsb00617	7960 Settings -> RingType menu changes doesn't take effect
CSCsb05398	7910 DSCP values need to be consistent with current design guides
CSCsb09994	EM logout restarts the IP Phone.
CSCsb14540	Small MTU causes CVTA to H323 video call failure
CSCsb19225	7960/7914 Ringer type off by 4 lines.

CSCsb23005	Update dictionary file with SeaDragon new phrases
CSCsb25084	Phone Continuously displays Requesting RingList File
CSCsb25088	Phone UI Lines separating the DN disappear as it failover to subscriber
CSCsb27811	http///CGI/CallInfo does n't display all lines call Info.
CSCsb27827	ActiveSoftkeys eg redial, New Call are shown when publisher CCM is down.
CSCsb34498	In CallInfo the CalledPartyName field is not proper for Conf call
CSCsb34616	In http request for CallInfo/LineInfo the Prompt field is showing null
CSCsb36728	Line button does not answer call with 2 calls on hold already on line
CSCsb38923	DHCPReleaseMessage should be unicast to DHCPserver,not on broadcast IP.
CSCsb51299	7960 Phone doesn't display blank URL sign or URL without label on line
CSCsb61379	Volume control keys when calling a busy no affects ringer(ver8.0(0.16))
CSCsb65192	7960 Phone reset from settings with **##* while on call hold
CSCsb65243	7960 Phone loose RTP stream when restart from CM
CSCsb71606	7960 Pressing Line button twice ends calls on Phone in ringing state
CSCsb74608	BigApp does not kick back to LA on version mismatch in XMLDefault.cnf.xml
CSCsb76105	phone 7940/7960 should escape '#' symbol
CSCsb82801	7960 doesn't receive MOH or DHCP when Voice VLAN = Access VLAN
CSCsb85223	RED LAMP indication on 7914 for In Use Remotely does not work - 7.2(3)
CSCsb87693	7960 MWI functionality should be consistent with current phone behavior
CSCsb89192	7960 Phone volume not being set properly at RTPRx start
CSCsb93558	Menu object as IDL URL, menu item 1 selected when phone goes off-hook
CSCsc00351	MWI lamp glows continuously after a CB notification for the first set CB
CSCsc32693	IP phones become unregistered from both SRST and CM
CSCsc40311	Phone drops untagged PC Traffic
CSCsc54415	Secure Phones does n't cancel tftp request while cancel key is pressed
CSCsc57815	7940/60 PC port 100M does not receive network traffic intermittently
CSCsc65264	Unable to dial the CB notified number during ringing state
7941/7961- 7970/7971	
CSCeb52862	no value for some items on Device INformation page
CSCeb60682	Phone should display ... for very long Text or Number
CSCee18288	SSO Standby RP T/B atm_ha_decode_vc_update+0x23c for ATM PVC bundle
CSCef84566	Phone registered to a CM 3.3 shows only one line while call on hold
CSCeg40271	Received and missed calls show wrong calling party number
CSCsa76694	Time stamps on console messages and phone display is not the same
CSCsa82496	Deselected call in sorted call list appears with other selected calls
CSCsa86338	Turbo Gabage at the end of Network Statistic screen
CSCsa94528	Cancel softkey has delayed response when looking up a bogus DNS addr

CSCsb05445	Phone resets wmore volume of call are placed on sidecar lines
CSCsb05446	wbm failed to extract signature when display filter was used
CSCsb13507	Turbo Can not remove Doamin Name on phone
CSCsb13552	Phone does not remove the default router config
CSCsb13598	Increase max CPU usage timeout for JVM process
CSCsb17420	SIP TNP 1.1 image stress run freezes phone UI
CSCsb20391	Phones unable to Rx or Tx Multicast Services when Publisher fails.
CSCsb28457	Phone w/200 calls active single line reset w/calling phone reset
CSCsb33760	dhcp.conf could have invalid my name entry
CSCsb38513	Add consolle trace to indicatie the call is an encrypted call
CSCsb40300	Phone doesn't register when it is unable to resolve the CCM name
CSCsb41233	paging group display delayed on 7911 with CME
CSCsb42487	get SW port returned -1 error after downgrade to 6.0(2)SR1
CSCsb45684	Phone stops playing multicast after an unanswered call
CSCsb53046	local Ip/port value is cleared but others are kept for an ended cal
CSCsb54419	LED does not blinking red while the DCP is busy
CSCsb54991	7970/7971 Touch Screen issue IP Phone URL shows Delay
CSCsb56294	ogins with sys group permissions on release signed phones
CSCsb56414	timeZone tag errors
CSCsb56740	Background Image thumbnails not displayed in correct order
CSCsb57509	7961 Row of Pixels missing on Line View graphic
CSCsb58479	phone locks up when SEP dateTimeSetting is empty
CSCsb58706	phone locks up when SEP dateTemplate is MM/DD/YY
CSCsb58897	Phone display goes blank for consult transfer to busy monitor line
CSCsb59253	when Pickup softkey is pressed on onhook phone displays ???
CSCsb59719	Service URI cause phone to unexpectedly shutdown
CSCsb59801	need to press mute twice for an incoming intercom call
CSCsb60547	Assign a same IP port to RX and TX socket - casues 1 way audio
CSCsb60762	Phone doesn't play Zip/ZipZip Tones toward network
CSCsb62674	Phone Rcvr Lost Pkt reports as a negative no under impairment
CSCsb66459	SIP TNP DSP debug seen when pressing Settings, Directories, or Services
CSCsb67697	Reference getPegs() via IMedia interface instead of directly
CSCsb68597	Turbo Phone receives mcast pkts when port open forMcast transmit
CSCsb68914	Turbo Error Verifying Config Info after LSC install on secure phone
CSCsb68957	README-SGM-pdsources on DVD has SGM references
CSCsb70143	Phone Should handle gethostbyname failure and print appropriate Err Msgs
CSCsb71024	Phone not displaying all Placed call list when pressing up/down button
CSCsb72254	Corporate directory search fails if username contains special characters
CSCsb72626	wirelss client to client can not pass traffic

CSCsb73103	Service URL feature assigned in em profile does not work
CSCsb74470	Phone sends Duplicate DHCP Discover Message
CSCsb74796	Phone freeze after reset stress
CSCsb75176	Phone displays wrong msg when registration rejected for security reason
CSCsb75427	phone doesn't show up old admin vlan id in Current Admin. VLAN Id
CSCsb77075	Corporate Directory Search Fails When using Russian Locale
CSCsb80110	Add Title to Line View to identify which line the calls belong to
CSCsb81552	Having directory menu open causes Callback to not working properly
CSCsb85391	HTTP CGI ModeInfo query does not return if Services URL doesn't resolve
CSCsb85540	Ethernet Disconnected Mesasge does not appear when Ethernet unplugged
CSCsb86702	Turbo Missing status messages on Load Server parameter
CSCsb86739	No status message when TFTP service is down on load server
CSCsb87844	LineInfo web age query does n't show up Messagewaiting Indication.
CSCsb88186	Phone won't failback to a TFTP server once registered to an SRST router
CSCsb88420	HTTP req cancelled msg when hitting a softkey
CSCsb89173	Japanese locale (td-sip.jar) not loading on SIP phones.
CSCsb92890	Removing JVM from 7.0 on 8.0 CPK files (to avoid out of space errors)
CSCsb93225	Turbo status message No Default Router after changing DHCP=no to yes
CSCsb95198	Phone does not preserve the state of mute/spkr button in handset mode
CSCsb96018	Skittles phone does not complain with junk value in displayOnDuration
CSCsc01611	Making DSP standalone on phones- dsp.cnu reads dspfw.bin
CSCsc02390	select image Userpreference->Background image display invalid png icon
CSCsc03492	CDP unexpectedly shutdown from broadcasted CDP pkt, results in restart of all apps
CSCsc03743	Privacy lamp is not being displayed correctly on 7941 SCCP phone
CSCsc05666	Phone unable to come out of Service Menu using CANCEL softkey
CSCsc05743	Phone responds to CDP triggers from upstream port
CSCsc05821	phone does not play precedence CW tone
CSCsc08584	Calls drop during CME failback
CSCsc09627	Phone is stuck if Encrypted Config is on and supporting load is absent
CSCsc11411	phone doesn't come up with DHCP enable when Voice VLAN = Access VLAN
CSCsc12324	Incorrect response for unicast/invalid IP adress for RTPMTx i p URI
CSCsc12347	CiscoIPPhoneExecute ExecuteItem priority 1 is ignored in some cases.
CSCsc12412	Invalid Ip Address to be displayed while validating Null values.
CSCsc14759	Turbo lost audio w/ 100% broadcast traffic
CSCsc15474	Status Msg timestamps changed between 24hr/12hr formats on reset
CSCsc15515	CP-7970 firmware version 7.0(1) distorts background image color
CSCsc15953	Softkey changes from Connected Transfer state to On Hold state
CSCsc17872	Phone is loosing the querystring parameter on the refresh
CSCsc22511	Phone Multicast services not working

CSCsc23385	LSC Installed Status Messages is not displayed on phones
CSCsc24668	cBarge Target phone changes focus when other party cBarges
CSCsc28089	Phone doesn't dial from placed call list when edit dial & dial is pressed .
CSCsc28119	Phone Displays UI with no keys for a shared line scenario.
CSCsc28167	Phone CGI URLs never complete HTTP transaction
CSCsc28515	Services page text does not display properly
CSCsc29075	Idle phones never send SCCP TimeDateReq to sync clock
CSCsc31606	Pressing the '.' soft key in the edit menu doesn't force Kate String T/O
CSCsc36213	Clicking noise is heard in encrypted call when duplicating packets
CSCsc37932	Phone plays garbled audio for PA prompts
CSCsc38193	phone displays ??? as Codec in Call Statistics window
CSCsc38233	Call Stats window displays wrong info for Rcvr Lost Pkts/Discarded
CSCsc39093	IP Phones use random UDP source port for RTP media
CSCsc39189	Phones stop sending KA when backup TCP link down
CSCsc39509	call bubble does not disappear when there is no active call
CSCsc40627	High End Phones connect to CCM sub that is not present in the CTL file
CSCsc42766	Turbo fine-tune displaying errors of dspSendFrame _framePutEgressFrame
CSCsc43827	Turbo InsideDialTone could not be stopped after removing CFwdAll
CSCsc46740	UDI Support
CSCsc47224	Turbo Codenomicon HTTP test 39730 causes sunvm CPU Time Limit Exceeded
CSCsc48565	Add core file decoded core file to the serviceability webpage
CSCsc49721	SIP phone loads and CCM are out of sync for PC Voice VLAN Access
CSCsc53183	GARP enable/disable reversed
CSCsc55247	Property Errors - Settings Can Be Lost
CSCsc58105	phonerebooting when secondary CME inaccessible and keepalive is 10
CSCsc60901	Enhance the flush operation in the RecordStore
CSCsc61065	HTTP Client locks up upon consecutive posts to CGI Execute
CSCsc63124	No prompt/status in Detail call history record
CSCsc63201	Dial Softkey Enabled when no Active Audio Path or no CCM
CSCsc63333	Erase from Top-Level Settings Menu does delete sidecar contrast
CSCsc65503	SIP Phone does not do a TLS session reuse after network failure
CSCsc70929	RMS Store must be deleted in order for phone to boot correctly.
CSCsc72223	Phone stuck after erase under Settings menu
CSCsc76402	JPhone Overview displays incorrect topcall if some RIUs made private
CSCsc77900	GARP enabled native code returning incorrect value
CSCsc79774	Phone could not recover after DNS entry be corrected
CSCsc82236	Phone sends Invalid Message for SCCP v3 and v4
CSCsc91001	Phone Answer softkey not displayed for new incoming call
CSCsc92221	Remote In Use Icon/LED not shown when shared line is private

CSCsc97902	HTTP Authentication Does not Show Response
CSCsd02600	Able to Change Ring Volume Even when Setting Access set to Disable
CSCsd03510	TimeDateReq to sync clock causes KeepAlive to miss one interval.
CSCsd09478	7970/7971 InCorrect Date Format Shown Under Missed Calls
CSCsd11037	2 meg file limit cause double boot when upgrading to 8.0 load
CSCsd13838	JAVA/TNP Log/trace related changes
CSCsd13925	CNU syslog changes for 7.0.2.x branch
CSCsd13960	getportcfg check for errors on msgsnd()
CSCsd23065	Display distorts, when held calls goes from three to two
7985	
CSCsa63183	The phone does not honor the Connection Monitor Duration fallback value
CSCsa67626	Phone may malfunction if more than two lines configured.
CSCsa83715	Telnet xstatus command under DNS/Domain Name contains non-ascii letters
CSCsb10348	Need to add support for IP phone service
CSCsb11711	IPMA is not supported with 7985 video phone
CSCsb14183	Add screen saver to 7985
CSCsb28430	XML support
CSCsb30069	Three or more line appearance needed
CSCsb33761	Ocius should have a contrast and white balance configuration options
CSCsb35935	save button placement cause user to end call
CSCsb44385	Directories menu does not display for 15 seconds when URL is unavailable
CSCsb53412	Background image support is required
CSCsb82142	Phone unexpectedly shutdown when 100 calls active and remote side is lost
CSCsc43840	7985 does not play the MLPP preemption tone
CSCsc68264	Settings Erase softkey is displayed even when config is locked
CSCsd04800	7985 video endpoints do not support services.
CSCsd10522	Packets from the PC port are not being forwarded out SW port
CSCsd10817	7985 unexpectedly shutdown when attempting to originate a call from WebDialer
CSCsd13303	Phone does not ring at all if the selected ring tone is not available
CSCsd13311	Error message on missing ring tone is different than 7970
CSCsd15971	Phone never boots up when background image is changed
CSCsd15980	Phone does not detect changes to the CM background image list file
CSCsd16178	7985 does not do Authentication for CiscoIPEXecute
CSCsd16208	7985- HTTP redirect not work
CSCsd16304	7985- CiscpIPPhoneIconMenu oject parse error
CSCsd16346	7985- HTTP refresh not work
CSCsd16436	7985- two items missing from phone's web access page
CSCsd16455	7985 not display Authentication URL on Device Configuraiton menu

CSCsd16488	7985 should have Power Save Configuration menu
CSCsd17143	Device ID in CDP messages should all be in upper case
CSCsd17540	7985 takes too long to re-register when image load is not found
CSCsd17581	7985 not back to power save mode if restarted from CCM
CSCsd18477	Alpha Numeric fields use different key mappings than other phones
CSCsd18608	7985 not back to power save mode after a call coming in
CSCsd23329	7985- phase 2 image does not support asp URL pushed to the phone
CSCsd23577	7985 should exit Service app after login w/ ExtensionMobility
CSCsd23610	7985 (X) button toggles between Full Screen and Overlay modes
CSCsd24921	7985 only shows 6 lines w/ Privacy and Speedial configured
CSCsd24940	7985 does not display To conference at line button menu
CSCsd27876	Callback activation tone is not heard when using TFTP Server 2
CSCsd27957	7985 not registered to its CCMs
CSCsd28028	7985 not update call status icon at line button menu
CSCsd28063	Hanging up the phone does not work when failover occurs during call
CSCsd30858	7985 unexpectedly shutdown when Execute Object is pushed to phone with proxy config
CSCsd30881	7985 got authentication error
CSCsd32462	7985 can not list PAB entry
CSCsd32511	7985 displays white line at full screen
CSCsd32569	7985 does not send out video packets w/ IPMA configured
CSCsd33387	There is no Cancel softkey when requesting a phone service
CSCsd33391	Berbee services do not work on 7985
CSCsd33398	Softkeys in the Berbee phone service do not work properly
CSCsd33446	MyGroup IP service returns back John Chambers' group instead
CSCsd33740	7985 should exit from Setting menu by pressing Setting button
CSCsd35350	7985 Error message different when URL DNS name error
CSCsd35418	7985 unexpectedly shutdown when wake up from power save mode
CSCsd35493	7985 incorrect behavior when get HTTP Error 404
CSCsd37665	Camera Properties need a wider range of changes
CSCsd37671	When upgrading the software the status line is stuck
CSCsd37686	Left/Right arrows should change the monitor brightness values
CSCsd37827	7985 could not display FastDial page
CSCsd37894	7985 Update at service page does not work
CSCsd39374	Phone unexpectedly shutdown while looking at the eventlog during an active call
CSCsd39401	Video between 7985s momentarily blurs out
CSCsd39451	7985 unexpectedly shutdown while answering a call
CSCsd39479	Remote side video stops working when hold/resume rapidly pressed
CSCsd39483	7985 should close the listening chanel when service app is closed
CSCsd39512	Exit an IP phone service returns the user to the top of the service list

CSCsd40531	Phone takes DHCP option 150 in the wrong order
CSCsd40906	Conference call info status is displayed as the the 4 instead
CSCsd40933	Digits after first call state softkeys are messed up
CSCsd40943	Calls for status line is corrupted after pressing directories button
CSCsd40973	The From status line displays no number on an incoming call
CSCsd41029	Call Park doesn't display the number parked at
CSCsd42350	Phone should drop from full screen mode during an incoming call
CSCsd42559	7985 Push Execute failed with Internal Error
CSCsd43606	7985 unexpectedly shutdown w/ call on hold
CSCsd43641	7985 does not disable SSH after reset
CSCsd43673	985 fails over to SRST after ethernet cable replugged in
CSCsd43942	7985 does not change Camera properties back to default value
CSCsd43953	7985 should not display Erase key at CameraSettings menu
CSCsd45171	7985 plays wrong Ring Tone
CSCsd45274	7985 does not save selected Ring Tone if RingList.xml not available
CSCsd45299	HELP ID- Help for Camera Settings returns help for Monitor Brightness
CSCsd45305	HELP ID- Brightness Hue Saturation help returns main help topics instead
CSCsd45310	7985 set button template wrong w/ one button set as None
CSCsd45340	7985 unexpectedly shutdown when access Help Main menu
CSCsd45388	7985 fails to display Video Mute icon when incoming call answered
CSCsd45403	Video mute line status icon is lost after a hold/resume
CSCsd45455	Placed Calls Directory entries have a %s as part of the display
CSCsd45480	Background & Ring don't reset when Restore Default Settings is invokled
CSCsd45520	Downloaded Background & Ring list missing when TFTP Server 1 is down
CSCsd46521	7985 unexpectedly shutdown when Line key pressed on Help Menu
CSCsd46534	X button does not work in Service w/ Host Not Found Error
CSCsd46547	No Help Info for Transfer softkey
CSCsd46555	No Help Info for NewCall softkey
CSCsd46567	No Help Info for More softkey in onhook state
CSCsd46573	No Help info for Dial and Cancel softkeys in onhook dialing state
CSCsd46587	No Help Info for NewCall sofktkey in Remote-In-Use mode
CSCsd46626	Softkey sets mess up after access Help in Callback mode
CSCsd46682	No Help info for ImmDV and TrnVM softkey in ringin state
CSCsd46731	7985 should include Camera Setting info on View Setting menu
CSCsd46781	Forwarded to status message not display the DN
CSCsd46827	7985 displays ?1001 status message when in Setting menu
CSCsd46836	X New Missed Calls should not persist w/ new incoming call
CSCsd46878	7985 does not support Restricted Setting Access
CSCsd47797	Phone unexpectedly shutdown pressing the Search softkey on Corporate Directory

CSCsd47819	Next softkey does not work in Corporate Directory
CSCsd47837	Wrong softkeys when looking at an empty Missed Calls list
CSCsd47854	Cancel softkey has no impact while downloading Background images
CSCsd48243	7985 play ringer to handset for a second call
CSCsd48284	Softkeys disabled after change audio source w/ Handset off the crack
CSCsd49849	Forwarded Call Infomation Display not as configured
CSCsd51253	Softkey sets changed after pressing Line button
CSCsd51286	7985 should switch back to the first call after 2nd disconnected
CSCsd51297	7985 behavior inconsistant with 2nd incoming call
CSCsd51370	Wrong softkey sets for barged call
CSCsd51379	7985 displays Remote-In-Use icon after barge into a call
CSCsd51423	First ring tone in ring tone list is the letter a
CSCsd51431	Cannot easily answer incoming call while in Missed Calls Directory menu
CSCsd51520	7985 call status message mess up for shared line
CSCsd52685	7985 shared line Call Info display different from other phones
CSCsd52861	7985 should initiate a new call on shared line by selecting the line
CSCsd52920	7985 not show the CallInfo of shared line on line menu
CSCsd55461	Dial key not work on FastDial
CSCsd55800	7985 should always use first avail. line for Dial from Directory
CSCsd55840	7985 should allow number with 25 digits at PAB
CSCsd57392	7985 not fallback to primary CCM if the CCM restarted
CSCsd57590	7985 does not have Next Softkey at Berbee main menu
CSCsd58864	No Update softkey for graphicMenu and image
CSCsd58881	7985 not work with directory.asp
CSCsd58984	7985 fails to display No Park Number Available
CSCsd60201	PAB service URL does not work
CSCsd60263	ExtensionMobility ServiceURL button not work
CSCsd61815	IP Phone service - My Group does not work properly
CSCsd62988	7985 flash light not blinking for Callback
CSCsd66806	Denial of Service tcpsic script unexpectedly shutdown the 7985
CSCsd66815	Personal Address Book edit Name returns 400- Bad Request
CSCsd67263	7985 not display Softkeys with position more than 5
CSCsd67299	7985 could not display Directory object with maximum value
CSCsd67372	7985 unexpectedly shutdown when pressing Softkey-Next and Softkey-OK
CSCsd67388	Phone does not recognize SoftKeyItem/Position object
CSCsd67777	7985 gives parsing error with IP Phone Agent Service
CSCsd68180	7985 unexpectedly shutdown when running a image slide show IP service for 10 minutes
CSCsd69592	Fast Dial phone service should be allowed to Assign up to 32 digits
CSCsd69711	Call Information is not displayed after pressing Settings button twice

CSCsd69826	7985 gives incorrect Error Code for XML parsing error
CSCsd70248	Phone help does not work
CSCsd71568	7985 gives ParseError if IPMA realtime update stopped
CSCsd71601	7985 unexpectedly shutdown when press Exit at IPMA assistant service
CSCsd71637	7985 does not display Exit key w/ Parsing Error
CSCsd71666	Phone does not fallback off SRST router after call is terminated
CSCsd71722	7985 unexpectedly shutdown when attacked with some Denial of Service scripts
CSCsd71870	Phone displays a ? instead of line feed on directory listing output
CSCsd71891	Blackjack IP phone service returns error after 1st key press
CSCsd72608	IPPA service Agent Login screen password entry is displayed in the clear
CSCsd73087	Phone directs some http requests to the proxy url when it should not
CSCsd74457	PC Voice VLAN disabled does not work
CSCsd74525	Line button not work if not all line buttons are assigned
CSCsd75705	7985 should change focus to the active call after exit from Setting menu
CSCsd75844	No Help ID for IPMA related softkeys
CSCsd76814	Softkeys are confusing when in the Lines menu
CSCsd76844	Cannot hang up a call when the call comes from a shared line
CSCsd77165	IPPA service briefly displays some XML code during start or state change
CSCsd77299	7985 unexpectedly shutdown with broadcast traffic at Voice Vlan
CSCsd77341	HELP ID- Background Image help returns Help Topics instead
CSCsd78429	One way video or black screen or no video over VPN observed
CSCsd80181	7985 XML input - Uppercase & Lowercase input types allow invalid chars
CSCsd80200	7985 XML Input - Some Input types with password field flag show password
CSCsd80219	7985 XML Input - Equation type input doesn't allow symbols
CSCsd81179	7985 should exit from Service app by Exit key w/ EM login page
CSCsd81505	Could NOT hangup call on shared line after restart
CSCsd86218	7985 New HW does not suppress upstream Broadcast, multicast traffic
CSCsd87804	7985 video phone unexpectedly shutdown when it receives cisco gateway fax NSE
CSCsd87878	QED (CSV and Display XML file) Changes for Phase 2 Ocuis 7985
CSCsd89131	7985 not support softkeyitem as Key-KeyPad
CSCsd89189	Berbee IP phone service returns- unable to display service error
CSCsd90204	7985 should not clear Status object
CSCsd90249	7985 should not append its Devicename in HTTP Get message
CSCsd90264	Softkeys under the settings menu are misaligned
CSCsd90271	Phone status log should contain more information
CSCsd91636	One way video seen on call between 7985s
CSCsd93321	Ringng stops playing when the volume is adjusted during incoming call
CSCsd93335	Phone is using the callback tone as a ring tone on next call
CSCsd94628	7985 reboots if Option 150 is a String Data-Type

CSCsd96654	7985 XML Input - equals character (=) looks like a solid, heavy dash
CSCsd97997	Audio sources do not work on next call after a failover with call active
CSCsd98058	Cannot change audio output source when failover with active call occurs
CSCsd98112	Error message is truncated when invalid Admin VLAN is entered
CSCse00288	Localization needs to be turned off on the phone
CSCse01525	Softkeys are unavailable after pressing the Window button
CSCse01546	Help for Power Save Configuration returns help for Camera Settings
CSCse01554	Help within the Power Save Configuration returns Main Menu Help instead
CSCse01562	Help of SW Port Configuration returns help for PC Port Configuration
CSCse01679	Stock quote IP phone service unexpectedly shutdown the phone
CSCse09392	Domain name cannot be entered when phone doesn't have an IP address
CSCse09403	HELP ID- Power save configuration returns help for Display On
CSCse09409	Network Configuration Default softkey should be renamed to Erase
CSCse09415	User Preferences Default softkey should be only available when unlocked
CSCse09420	The popup window after pressing Default should be more specific
CSCse10745	7985 - Power save exits XML Service (and menus)
CSCse17156	Configuration parameters domain name and DNS servers lost after upgrade
CSCse22829	Phone rebooted when using Hoot & Holler with 2 phones in Shout mode
CSCse43169	Phone ignores DHCP option 150 when option 66 is present for TFTP server
CSCeh05771	Domain Name shows up as - ? when it is not populated by DHCP
CSCsa71240	Onhook dialing does not light Speaker LED in SRST mode
CSCsa94785	On help button ? page, Back softkey doesn't work
CSCsb07159	Requesting better administration tools
CSCsb11155	Video pixelation on calls made between Cisco VT Advantage and 7985
CSCsb18392	7985 Improper system message wording
CSCsb19181	There were no tones heard when using onhook dialing
CSCsb20900	No notification on phone when the remote end of a call is lost
CSCsb24490	Call focus switches off active call when shared line is used by others
CSCsb27570	Default router field periodically resets when phone is configured
CSCsb29880	7895 may report multiple Standby CCMs after fallback
CSCsb32824	Phone does not ignore lower valued Voice VLAN when multiple CDPs recvd
CSCsb38035	Phone may stop ringing when switching to a second incoming call
CSCsb38985	Headset mode sends output to the Speaker in SRST mode
CSCsb38994	Sometimes cannot answer 2nd call by switching lines in SRST mode
CSCsb39018	Phone sometimes does not direct audio to the handset in SRST mode
CSCsb39043	Call Forward icon still displays when fallback to SRST mode occurs
CSCsb39061	When using EditDial of a number the prompt should start at the beginning
CSCsb41380	Rarely the MWI light is on even when no messages are pending
CSCsb42444	Phone does not send periodic CNG packets during long silence breaks

CSCsb42481	Call Waiting Ring setting will only Flash the MWI lamp during 2nd call
CSCsb43461	Video may freeze at end of call or in self-view mode
CSCsb43516	Switch should ignore PC Voice VLAN Access when there is no voice VLAN
CSCsb43558	802.1p frames dropped on phone with Admin VLAN and PC voice VLAN disable
CSCsb44286	Phone gets stuck in CallManager Unavailable state
CSCsb44352	Test script causes a watchdog timer expiration
CSCsb46875	Packets to PC port are re-mapped with 802.1p when Voice VLAN is 802.1p
CSCsb47793	EditDial followed by lifting handset will not dial call
CSCsb49854	Phone may continue to display Self View rather than idle screen
CSCsb82176	Denial of Service mutant script cause the phone to reset
CSCsb88796	Sometimes phone cannot end call after a CCM fallback with call active
CSCsb88824	Web Access Enabled/Disabled need to be added to CCM and phone
CSCsb88839	Phone sometimes does not connect to correct backup CCM during fallback
CSCsb89095	Phone does not reset when lower numbered Native VLAN learned
CSCsb96016	Video mute state get out of sync after the phone is restarted
CSCsc00791	Phone sometimes shows wrong status msg/softkeys after CM service restart
CSCsc04464	Cannot browse under Directory, Up/D rocker stuck at the Missed Calls
CSCsc09982	Phone drops ~50% of IP multicast traffic from SW to PC port
CSCsc10082	7985 MWI Light misbehavior
CSCsc27761	7985g reboots after select softkey then hit the X key
CSCsc31705	7985 does not play precedence call waiting tone
CSCsc32408	7985 phone does not display call pickup visual alerts
CSCsc67447	7985 unexpectedly shutdown when running Codenomicon TCP protocol verification suite
CSCsc82605	7985 phone reboots when pressing the 'Directories' or '?' buttons
CSCsc84357	CCM4.2 - Cisco 7985 Phone softkeys disappear during Pickup Audio Alert
ATA18X	
CSCsb06073	ATA SCCP Incorrect Call Waiting behavior
CSCsb16422	Conference to ATA-Phone thru H323 & ATA-phone on same CME doesnt work
CSCsb23891	ATA flooding callmanager with SoftkeyeventNew call skinny messages
CSCsb25973	Problem transferring calls using ATA and CME
CSCsb41805	Update signaling ToS to be consistent with current design guides
CSCsb56308	ATA186 configuration web page should state clicking rather than click
CSCsb60054	ATA SCCP sent AVT message when sent DTMF to SCCP endpoint
CSCsb63368	No Secondary dialtone played by ATA SCCP
CSCsc47937	ATA186 excessive TCP ACK delay after receiving SKINNY message
CSCsc50269	ATA SCCP sends excessive StationSendTimeDateReq

Resolved Caveats for 4.1(3)es40 - Base ES for 4.1(3)sr3c, sr3b, & sr3a

CSCsb25699	Max CDR Records exceeded if SQL Agent service is not ready during init
CSCsc83528	MGCP-Need configurable timer waiting for FXS onhook when call ends
CSCsc26241	CTI manager running high CPU with CTIERR_SHUTTING_DOWN errors
CSCsc49668	CiiscoatUserProfile and ciscoatUserProfileString not updated
CSCsc63262	Missing disconnect for conf parent in alerting/drop scenario
CSCsc68542	Firewall support for attendant console in skate
CSCsc49358	Remove Redundant FORWARD Trace Events in CCM SDI Trace
CSCsc51393	Unanswered call to Huntlist is cleared with incorrect cause code
CSCsc56058	Race Condition Occurs in CCM that Causes Call to Get Dropped
CSCsc62658	Support of DDI trailing
CSCsb15170	CM need support for new phones in devicelistx.asp file
CSCsc71593	Tunneled protocol not available for H225 gatekeeper controlled trunk
CSCsc67507	CTL client returns 'No valid server certificate found' inserting etoken
CSCsb95225	ES/SR Installation needs corresponding code for CSCsb44801 resolution
CSCsc80738	stopservices needs error handling update
CSCsc81725	Enlarge splashscreen in ES/SR installaton
CSCsc81747	Need new sections for file copy ops
CSCsc81756	Update SQL script handling
CSCsc82417	Enhance error handling reporting and dialogs
CSCsc82071	End of installation Dialog Changes needed for Device Package
CSCsb44801	Sub installation failed because no user tables for CCM database on Sub
CSCsb68978	CCM 4.1.3 sr1 sending Mal-formed DNS request
CSCsc50451	PRI Sends Cause Code 0 On Drop Party From Conference
CSCsc50466	H.323 Sends Cause Code 0 On Drop Party From Conference
CSCsc70044	E164 Mask change notification issue for DN's with wild characters
CSCdy83914	CCM does not update analog port status for analog GW (need rej msg)
CSCsc51531	CAR report CDR Search by Gateway displays incorrect records
CSCsb52379	Implement group listening.
CSCsc68821	Changes in clearcase not properly built into ES
CSCsc80762	Stopservices to display services being stopped.
CSCsb90459	CVTA Failed call to MGCP BRI gateway - bearer cap 0x8080A5
CSCsc00795	CCM MGCPbrid device didn't handle CcSelectFacilityReq message properly
CSCsc34583	CCM Initialization Digit Analysis State Takes 4+ Minutes To Complete
CSCsc56718	CCM doesn't sent stop alerting tone
CSCsb90104	CallBack does not work after modifying the CallManager Group
CSCsc56058	Race Condition Occurs in CCM that Causes Call to Get Dropped
CSCsc67973	CTIManager unexpectedly shutdown with Access Voilation

CSCsb59662	raven Voice Quality Problems using SIP based VoIP
CSCsc57488	AXL response containing junk characters.
CSCsc13263	Cisco TFTP perfmon counters can not be viewed through perfmon
CSCsc13290	Slavonic Languages Delta on the localized dictionaries
CSCsc40205	JTAPI Client causes issues with ICM Jtapi Gateway
CSCsc56032	PlatformException sent to Apps erroneously when call is xfer'ed/dropped
CSCsc61201	JTAPI is not sending CiscoAddressCreatedEv
CSCsa85674	WebDialer takes line with lowest DN on user device profile
CSCsc68285	PCM change breaks 4.2 and lower builds.
CSCsb94314	Need tag for 6608-MTP/CFB in ccm xml
CSCsb90176	Callback seizes to function after a while
CSCsc01046	log service stopped event in SDL traces
CSCsc62075	Call Manager restart setting up media for MGCP call
CSCsc37302	Locations Bandwidth Leak
CSCsb70900	CCM Can not form the TO packet that is required by LCS
CSCsc59478	ES34 causes global directory pages to break
CSCsa85731	AdminUtility does not write out a log file
CSCsb00410	AdminUtility should control password changes for the IWAM_Guest account
CSCsb08117	AdminUtility is not stopping services
CSCsb25938	enhance adminutil to validate usernames
CSCsb25942	enhance adminutil to be compatible across Cisco CallManager versions
CSCsb25945	enhance adminutil to perform additional operating system checks
CSCsb25959	enhance adminutil to reset dcom permissions
CSCsb13785	Translated Rerouting Text not shown on phone
CSCsb16326	Sending Complete Setup Msg to overlap Route Pattern fails
CSCsb16361	MTP Orphaned Stream w/H.323 Call On Hold - Incorrect CI
CSCsb17813	Call fails to connect after dialing FAC code in a scenario
CSCsb27954	There is no StartMedia Transmission to the IP phone when it re-opens
CSCsb46742	Bandwidth leakage allocation in CCM
CSCsb91901	Hunt group was not utilizing the T1 CAS circuits on a Gway until reset.
CSCsc11294	ccm.exe terminates unexpectedly after trunk reset w/ DNS server offline
CSCsc22655	Softkeys greyed out for a barged call that is barged again
CSCsc46535	Need Inbound Redirecting Number IE over QSIG PRI for interoperability
CSCsb34908	T38H323-H323 fax across CCM nodes not supported
CSCsb59144	Preserve active H323 GW call during quiet clear
CSCsb39067	CTI Route Point is using the configured DNas Redirect
CSCsc20850	Voice Mail Port Wizard fails with DBL Exception
CSCsb33983	updatePhone - invalid Max Call and Busy Trigger causes line disassoc
CSCsc01046	log service stopped event in SDL traces

CSCsc20057	Disable Nonregistered SCCP Keepalives default value should be False
CSCsc20116	DialingForestDumpEnabled service param should warn of CCM terminations
CSCsc27282	BAT Phone validation fails with comma in Display or Alerting Name
CSCsc40315	Deleting Unassigned DN with BAT causes deletion of configured devices
CSCsb84724	CCMAdmin Password Validation should be proper once enabling MLA !!
CSCeb77828	Region name fields should allow 30 character in regionconfig.asp
CSCsc15508	Changing partition name not implemented until CSS is changed
CSCsc26838	Route Filters can not be selected when Max List Box Items is exceeded
CSCsa99604	CCM Inter-Cluster Trunk Wait for Far End H.245 Terminal option
CSCsc48675	Inbound Redirecting Number IE Delivery should be selectable for QSig
CSCsc49372	No validation done if beginning DN is empty in VM Port wizard
CSCsc03592	TAPS should be made compatible with CRS 4.0
CSCsb62285	VG224 configured for shared line on Callmanager fails
CSCsa81564	devices attempting to register prior to CCM being up
CSCsb77467	Unable to complete the conference
CSCsc38714	CTIManager out of service making PhoneLine to go into incorrect state
CSCsb22201	Cisco IP Voice Media Streaming App using SW CFBs stops unexpectedly.
CSCsc39616	updateGatewayEndpoint fails after insert 24 ports
CSCeg54015	Error comes on clicking Update on Autogenerated Device Profile
CSCsc03637	Remote scripting error on web page if updated after long idle time.
CSCsc43604	Blank popup message after session timeout popup
CSCsc43818	7.0(2)SR1 image for the 7941/7961 checkin to 3.3, 4.0 and 4.1CCM release
CSCsc43876	7970/71 7.0(2)SR1 image check in
CSCsb83277	Add online doc. name to 7911 SCCP loads
CSCsb15343	Stdndr Feature 7960 sftky profile fail on 7940 CallBack equipped phone
CSCsc42186	Update/Make 7911 ready for FCS and prepare Skate SR build
CSCsb72498	AgenaInterface leak when remotely join party
CSCsb99442	Last party in the meet-me conf closes if other parties has Tx failure
CSCsc33663	ccm.exe unexpectedly shutdown when printing Media_PayloadList[capsInB[5].payloadCapabil
CSCsc20451	CCM Initialization-Forward Phase In SsInit Takes 34 Minutes To Complete
CSCsc37571	race condition in CTI failover/failback
CSCsc09589	CallManager forwards conferenced call to default VM Profile
CSCsc34686	CCM Init/RuntimeDETAILED DBL Trace For FORWARD Phase Is Too Verbose
CSCef75361	CCMAdmin Read Only User Can Escalate Privileges
CSCsb12765	Unauthorized Alteration of CCMAdmin Administrator Privileges
CSCsb88649	CCMAdmin Read Only User Can Escalate Privileges
CSCsc26275	CCMAdmin Read Only User Can Escalate Privileges
CSCsb86047	MeetMe needs to have additional tracing to track leaks in conf use

CSCsc30455	CTIMnager unexpectedly shutdown access violation
CSCsc15310	Dialed Number Analyzer fails after NZT Daylights Savings Time Start
CSCee26934	invalid GSM EFR audioUnitSize should not cause CCM not to send TCS
CSCsc08308	H.323 Faststart call fails after getting 2 ORCAck from IOS gateway MTP
CSCsc14193	CM sends ARQ with nonzero bw for callback via GK controlled ICT
CSCsc17394	CFwdALL may fail to clear for Shared DN
CSCsb89190	ASTISAPI.DLL Memory Leak Upon CMLAUserPermission--setUserID() Failure
CSCsb42763	Call Pickup fails on Hunt List
CSCsc18581	Application menu items should not be in all CAPS
CSCsb99593	CAR version 4.1(0.34) cannot retrieve data passed certain dates
CSCsc06751	Moving cLock forward cause JTAPI Exception and Provider going OOS
CSCec50080	App Event log Warning not always generated when CM service stopped
CSCsb05242	CCM sends sendTCS to device registered in h323 gw mode
CSCsb80835	Call forward on QSIG reroute fails
CSCsc13589	Aupair Sustained CPU Spike - ghSendQueueSem Deleted On CCM Change
CSCsb84764	remove loggingDisplay option for 7941...7961G-GE phones from CCM/Windows
CSCsa89839	RUS-JTAPI files shows garbage in the preference window
CSCsb40708	JTAPI deadlocks when trying to deliver event at same time agent logs out
CSCsb42308	Invalid DisconnectedEvent in conference release
CSCsb72542	Cisco JTAPI does not work with IBM JVM 1.4.2
CSCsb87731	Address on CTIPort is out of service if registered after adding observer
CSCsb97841	InvalidStateExceptionImpl when jgw attempt to send call to CTI manager
CSCsb27001	Support new phone cert in CAPF
CSCsb75848	ToneOnHold played when user drops from external call
CSCsb88712	CallManager unexpectedly shutdown (access Voilation) in Cdcc
CSCsb98884	CCM 4.1(3)sr1 - SIP trunk Diversion info lost
CSCsc08515	QSIG Loops on CallForwardAll to OffNet DN
CSCsc10659	Callmanager propogates disconnect cause 0x9F
CSCsb84027	Logging Display and Load Server features do not appear for the 7970/7971
CSCsa72046	Adding DN get stuck in Verifying state
CSCsb48346	Attendant Console fails to redirect Queued calls to Huntgroup
CSCsb34023	Attendant Console gets an error message Failed to make new call
CSCsb74383	AC outbound call does not use primary line
CSCsb36910	OrininalPartyName and LRPName coming blank in inter-cluster unpark
CSCsb46224	LineTransferEndedEvent Missing because of CallProcessing Issues
CSCsb50366	DSP Keepalive Timeout for MOH Multicast
CSCsb60395	Memory leak in AgenaInterface
CSCsb95724	ccm.exe unexpectedly shutdown (access voilation) with CcSetupCompReq
CSCsb92313	add service parameter for progress->disconnect translation

CSCsc02681	CTI does not query database as part of ProviderOpen
CSCsb32984	VPT receives corrupted HTTP header in AXL response
CSCsa67964	SIP Default Telephony Event Payload Type Range ends at 120 not 127
CSCsb85579	Call Manager 4.0(2a) SR2b unexpectedly shutdown when masking called pattern
CSCsb88871	Q931 field does not contain release cause for Annex M1 calls
CSCef47866	CMI service does not restart when it loses DB connection
CSCsb45865	Stuck call
CSCsb61425	BAT insert fails if phone description contains comma
CSCsb88304	Unable to update MLA's User Group Base.
CSCsb97915	Route Group page takes too long to display available devices
CSCsb63302	Diverting to specified directory number isn't working
CSCsb76677	Stored procedure was not replaced correctly on Sr1 Installation
6608	
CSCsb85691	CallManager may incorrectly put a 6608 CAS port OOS
CSCsb85909	6608-Glare conditions on T1 CAS is not cleared appropriately
6608 E1/T1	
CSCsc14019	Calls through 6608 T1 CAS trunks are not preserved
CSCsc64672	T1-CAS E&M ports on a 6608 card unregistering during stress test
CSCsc80674	Periodic T1-CAS E&M channel out-of-service during 6608 stress test
6624	
CSCsa74278	change configuration link is not opening for 6608 & 6624 GWs.
7911	
CSCsc82623	Checkin 7911 f/w loads to create Device Packs for FCS
7902/7905/7912	
CSCsb09545	7912 fails due to malicious VLAN tagging
CSCsb47309	7912 does not play UK dial tone
CSCsb55707	7905/12 phones lose Service button after EM update
CSCsb72625	phone - 7912 phone reboots after receiving 3 IMs quickly
CSCsb84484	Only a 7912 shared number phone work when configured max-dn dual-line
CSCsb86641	No dial tone after the 7905 and 7912 SCCP failover to SRST
CSCsb89284	7912G-A phones cause PC's behind them not to retain an IP Address
CSCsc04738	Long delay for PC to obtain network connectivity when used with 7912G-A
CSCsc28280	7912/05 should always Reset unless an rtp stream is active
CSCsc47335	CCCM 5.0 & 7905/12 does not show external number on top line of display

CSCsc47463	7912 SCCP sends excessive StationSendTimeDateReq in idle mode
CSCsc50849	7912/05 excessive TCP ACK delay after receiving SKINNY message
CSCsc50888	7912/05 RTPMTx sets TTL of sent multicast packets to 1
CSCsc51693	TimeDate req. msg. storm from at midnight
7920	
CSCsa90127	Extension Mobility does not work with Services URL Button on 7920
CSCsa93659	7920 Doesn't Support Vibrate URI
CSCsb08922	Need a menu to display configured regulatory domain
CSCsb08923	Need a menu to display current transmit power
CSCsb11420	7920 Does Not Support CCA Versions of QBSS
CSCsb13680	7920 can spontaneously re-register to CM in idle with INF-MIB error
CSCsb16154	7920 Can Associate to a Lower Priority Profile When Set to Auto Profile
CSCsb29735	Upgrade to 2.0 will cause phone lock password corruption
CSCsb38067	CCM 5.0 Centralized TFTP compatibility enhancement
CSCsb38210	Port 17185/udp is open on 7920 phone
CSCsb40013	7920 RTPMTx sets TTL of sent multicast packets to 1
CSCsb46797	7920 call-forward noan on second active call results in phone hanging
CSCsb48681	7920 can corrupt the CCKM Timestamp
CSCsb48687	Invalid XML object sizes can cause the 7920 to reboot
CSCsb48693	Idle URL can cause the 7920 to lock up
CSCsb60866	7920 will roam off a strong signal AP to a weaker one
CSCsb61677	7920 should continue streaming RTP packets when on Mute
CSCsb61711	7920 can fail to ACK G711 packets during a call
CSCsb72898	7920 Can Roam More Frequently With 12.3(7)JA AP Image
CSCsb77564	7920 Can Stop Scanning Although Still Associated
CSCsb83303	7920 send 802.11 Auth suddenly and it causes choppy audio
CSCsb85711	Channels in Active List are not flushed after 3 missed CM Keepalives
CSCsb99759	Emergin's alert tone volume needs to be limited when on-call
CSCsc00129	CP-7920 is not responding to AP packets
CSCsc00147	MWI tone can be very loud to user if CP-7290 re registers
CSCsc00238	Need to roam when QBSS max threshold is met
CSCsc72304	7920 MR2.0.1 firmware upgrade
7935	
CSCsc58699	CP-7935 generates choppy audio when in a conference call
7936	
CSCsc20570	7936 Transmit Jitter Extremely Sporadic - 2 Second Cycle

7941/61	
CSCsb83788	The Exit softkey is not working on the Callback screen.
CSCsc03743	Privacy lamp is not being displayed correctly on the phone.
CSCsc04301	Add fault-tolerance to file system.
CSCsc14168	checkin 7.0(2) firmware for 7941/7961 phones into CCM/Windows
7970/71	
CSCsc14196	7.0(2) firmware for 7970/71

Resolved Caveats for 4.1(3)es25 (Base for 4.1(3)sr2)

CSCsb73699	High cpu with ccm, cti and gatekeeper configured
CSCsb91325	CCM faulters on backhaul messages to 6608 for T1 CAS hookflash transfer
CSCsb08010	Put PerfmonQueryAllCounter ASTIsapi Url back to 4.1.3.sr.1
CSCsb88131	Enable Database Related SYMBOL and MAP Files During ES/SR Build
CSCsb38840	Delay on DN lookup in CCMAAdmin with large number of CallPickup Groups
CSCsb87824	Route Group Configuration screen does not show Available Devices
CSCsb08073	CM SDLListeningPort service parameter should not allow a value of 0
CSCsb56053	CCM CCMG for inter Cluster Trunks does not limit GK registrations
CSCsb16635	Established Flood causes high CPU usage or unexpectedly shutdown ccm process
CSCsb40307	Can't save IPMA manager's config if divert target contains number zero
CSCea53907	CallManager-improve handling of idle TCP connections
CSCsa86197	TCP connections not managed aggressively
CSCsb64161	TCP connections not managed aggressively
CSCsa82548	CAR 4.1(X) CDR search getting Database access denied
CSCsb49430	MGCP calls fail after failover
CSCeq50815	AVVID ICT media exchange timeout on CTI redirected call
CSCsa64436	LDAP Access Error while searching for users in CAR (clone of CSCsa60661)
CSCsa68286	Wave driver thread leak
CSCsb05396	One-way audio with CiscoTSP
CSCsb50071	Callback doesn't work after CTI Manager failover
CSCsb57558	PC logging option is not available for makaha
CSCsb65027	CCM AXL API support for voice mail pilot and profile
CSCsb70126	Invalid PSS1 info may cause ccm hang
CSCsb49627	Incorrect DNIS using speeddial and Route Pattern configured for overlap
CSCsb53977	CNFA on hunt group pilot point doesn't work for transfered calls.
CSCsb62669	CM doesn't wait for more digits if partial digits are rcvd for RP/XP
CSCsb64065	CCM rejects incoming T1 CAS calls intermittently due to race condition

CSCuk55138	1 way speech path call from CME FWD to operator transfer to ip phone
CSCsa69040	Add 7985 QED support CCM versions 4.X and 5.X
CSCsb58653	7911 QED changes to support alt scripts and load server
CSCsb27851	Endcall Received After Second Transfer Causes Disconnect
CSCsb36782	New Call Failed To Be Pickup Using Handset
CSCsb57014	Auto pickup call does not show forward info after connect
CSCsb58843	RQNT before CAS DT/oc interrupted DT/sup
CSCsa97017	IpVmsApp on Subscriber pegs to 100% CPU
CSCsb56736	Checkin ip7961.pdf ver3 into3.3.5.eng.spec, 4.0.2.eng.spec, 4.1.2.eng...
CSCsb33400	CallManager terminates unexpectedly, RaiseException
CSCsb31613	TFTP Does Not Build All Configuration Files
CSCeg39344	Subscription Pull Takes Almost 6 Hours To Complete
CSCsb28268	Wrong call details on shared line console
CSCsb31441	Unwanted error pop up on console with shared lines..
CSCsb36220	The line state is broken when using dialrules.XML
CSCsb48804	Enable visibility of Makaha types in dev packs 3.3.5.eng.spec, 4.0.2. ..
CSCsa73714	Inband info not heard by IP phone when ISDN DISC+PI received after SETUP
CSCsb18809	Inband announcement not heard when calling busy or unallocated numbers
CSCsb40124	Secondary line set to flash only will only blink the icon and not lamp
CSCef70826	Need to bump the SDL version number due to changes in CSCef64304
CSCsb05135	7961/7941 font should be more readable - suggest making tallerCSCef28642
CSCeg51337	Device Association Page distorted & JScript Err after a bad search
CSCsb46052	MLPP config not available for 3845 MGCP gateway
CSCsa98719	On 7970 Display-on-Time shows default value after setting it to blank
CSCsa77103	Station stay at CONNECTED state after call release
CSCsa95603	Media Component Race Condition Leads To MRM And Process Leaks
CSCsa67314	Primary CMI does not send KeepAlives to Voicemail
CSCsa64684	Change Notify stops working due to bug in TcpLib
CSCeg39579	Second TCS from H.323 Tandberg is not handled properly by CCM
CSCsa55834	dtmf not sent on t1 cas If call is not in connect state
CSCsa82150	Ericsson MD110 PBX CCBS/NR CallBack Interoperability issue
CSCsa81035	Standard Phone FG does not Allow Changes to EM Select User Profile
CSCsa82141	MLA generates error when configuring partition for DN
CSCsa66428	Install Migration for AIM-VOICE-30(332) to AIM-VOICE-30-SLOT-0 (412)fail
CSCsa70825	InsertCDR.exe taking 1.5 GB of Memory
CSCsa92229	CCM Srvc Unexpectedly Restrts during a fax operation usin H.323 gateway
CSCsa86039	CCM SIP call failed when the INVITE message has a phone-context tag
CSCeg38879	Pilot point busy if member sets CFWall back to Pilot Point
CSCsa62728	Agent stuck in talking after Outbound Option call

CSCsa69159	4.0(2) wrong line status returned by jtapi
CSCsa80418	selectRouteThread and EventThread are blocked for 15sec.
CSCsa83476	Cisco Jtapi stops sending events after address is manipulated byCCMAdmin
CSCsa93610	CATUrgent need to get JTAPI build to Catalan theater with revisions
CSCsa90858	TurboError Extracting File using latest tc-sccp.jar file
CSCeq62448	AC client showing wrong line status
CSCeq35909	Device Pool not getting updated for 7912 and 7905 phone.
CSCsa70883	CallManager terminates unexpectedly, RaiseException
CSCsa87857	InsertCDR service stops populating CDR database from flat files
CSCsa84493	Implement JAVA side and QED CM interface
CSCsa84032	Catalan fail to launch due to wrong language code in localelistings.prop
CSCsa83874	Idivert Key upon being pressed get temp fail
CSCsa76784	LowAvailableVirtualMemory alert triggers when 70% or more memory free
CSCsa82061	Unable to manage Personal Address book via CCMUSER page
CSCsa61342	DevPack does not install the locale files
CSCsa80820	No alarm when maximum devices per provider is exceeded
CSCsa80822	No alarm when maximum devices per node is exceeded
CSCsa82121	Deleting a transcoder disables transcoding for the whole cluster
CSCsa81171	CCM doesn't clear the h225 call properly when PSTN hangs up
CSCsa79453	CDR value is not correct when using Auto Call Pickup
CSCsa79287	Comment Column In CallDetailRecord Table Does Not Support 2048 Chars
CSCsa81028	Enable fclosethread or start CCM w/ thread corrupts SDI index to -1/0
CSCsa66381	Wave driver incrementing RTP sequence #s during silence
CSCsa69896	Additional languages for CM4.1(3)
CSCsa75271	Marker Bit not set in the first RTP packet after silence.
CSCeq15756	Change notification stopped working after route filter change
CSCeq19146	CFA stops working after CCM has been running under load
CSCeq75144	IP phone re-registers after set or unset of call forwarding
CSCsa66331	Add QED support for 7911
CSCeq65803	AC displays err message during preemption on an attendant phone
CSCsa74250	Pop message when pressed save on the Attendant console GUI
CSCsa76356	Attendant Console shows Unknown Error at Basic Settings
CSCeq05792	Polycom ViewStation Call disconnects
CSCeq47889	CC returns unmodifiedCGPN same as CGPN. Issues with states of agents
CSCeq75148	High number of voice packets/frame in outbound fast start
CSCeq77257	DMS-100 spec does not recognize ISDN Q.931/Q.850 Disc Cause Code 53
CSCeq80606	Incorrect cause code is returned when the line is not registered
CSCsa63770	Always use prime line is not working with 7.1.2 phone load
CSCsa64690	Messages button works intermitently

CSCsa65757	AS-8 gateway stops supporting SMDI after upgrading to CM 4.02a
CSCsa66224	Call Pickup fails intermittently
CSCsa68351	CCM prepened the prefix to Cgpn for CLIR calls via H.323 GW.
CSCsa70684	CM Deducting twice the Audio BW and returning only half when call comple
CSCsa71292	CCM doesn't instruct 6624 to generate outside dia ltone
CSCsa71443	h323 faststart to MGCP calls fail when h323 has active caps enabled
CSCsa72075	unexpected shutdown in MeetMeConference when accessing NULL pl/spl lists
CSCsa72667	CTI Change needed to accomodate CCM Change required for Prime Line
CSCsa73461	RBT is not heard on the PSTN side while call routing to an agent
CSCsa73468	ForwardManager does not remove map table (mPartyToActiveCallIndexMap)
CSCsa73821	MWI requests fail when originating device goes onhook quickly
CSCsa73460	CTINewCallAcceptTimer expires during lineRedirect causes timing issue
CSCsa80583	TCD is requesting redirect to an available hunt group member, calls fail
CSCsa79229	CallManager terminates unexpectedly during IP Phone registration
CSCeg04867	RTMT installs outdated/duplicate/unsupported JRE 1.4.1_01
CSCeg72925	TFTP not serving requests, stuck with 200 requests in progress
CSCsa63212	CNF stops sending CTFTP changes.
CSCeh07555	7961 device pack doesnt conatin proper device name on device default
CSCeg78586	Unable to access Database also Publisher out of Disk Space
CSCsa74704	AXL Allows Creation of Duplicate Route Patterns
CSCeh02155	ADCM Tools will not function w/multiple clusters in same AD domain
CSCsa75741	Directory throwing exception when manager DN does not exist in iPlanetDirUser, UserManager
CSCsa69809	Call Activity Report incorrect reporting on PRI count in service
CSCef64451	java.exe consumes 100% CPU leading to CallManager restart
CSCeg64058	Validation not done for Auto-registration Information
CSCsa76726	Unannounced products show up in various admin pages
CSCeg41270	Garbage characters on JTAPI Preferences launched on Japanese PC
CSCeg57486	Misleading message in JTPrefs console window.
CSCeg69679	Need a reason/cause for the CallCtlConnFailedEv to indicate MLPP
CSCeh06938	Unexpected CallCtlTermConnTalkingEv after disconnected
CSCeg65779	Error on phone page in DNA
CSCef60562	Patch Install says file replaced successfully whether done or not
CSCef62839	Msg if we wish not to view log should be consistent for install/unin
CSCeg05021	SR doesnt Init Database on replication failure detected scenario
CSCeg76037	Device Default is updated when uninstalling ES/SR
CSCef92024	Wrong Upgrade Message when upgrading to SR01-rc02
CSCef92093	Unwanted msg leading to err pops up while upgrading to 4.0(2a)SR01
CSCef94368	Misleading CCm Ver Msg if Patch installed on a Non-CCM Server

CSCef95676	SR Patch Ver check lists From as old SR and not new MR and misleads
CSCeg20517	Remove the extra are-you-sure from the ES/SR installs
CSCeg24009	Uninstall Confirmation dialog should mention version reverting to
CSCsa75224	Support needed for Ext Device Package execution during ES/SR install
CSCsa75625	Need to dump a list of running processes during installation.
CSCsa83128	CCM 4.0(2a) - DCD terminates during quiesce operation for backup.
CSCsb33698	AXL missing a few key handlers
CSCsb30317	Attendant Console does not retain window focus
CSCsa77185	Need to add Service parameter Always play outside dial tone
CSCsb08581	Enhancement to Modify APDU ext num for outgoing Qsig MWI on/off messages
CSCeg56410	Call Forward to Multiple Busy Users gets no busy tone
CSCeh06782	Pressing the Transfer softkey on a selected call deselects the call
CSCsa65878	Annex M.1 trunks need to optionally ignore tunelled content
CSCsa75901	Call Join Request fails
CSCsb18747	When Auto Call Pickup IP Phone does not display For.
CSCsb26605	First character of Caller ID is stripped in Japanese environment
CSCsb32103	CCM constant registrationRequests to GK if no TTL in registrationConfirm
CSCuk55454	No ringback tone when calling from CME to Qsig PBX via CCM
CSCsb01329	CTI Route Points remain registered after CTI application shutdown
CSCsa89823	CTI unexpectedly shutdown when device is removed from control list
CSCsb30766	Unnessecary changenotification sent to DeviceLineMgr causes CPU load
CSCsa60661	LDAP Access Error while searching for users in CAR (cloned CSCsa64436)
CSCef72456	CM hangs on blank screen upon reload with USB mcast MOH audio src
CSCsa83306	Error -1 [Internal Error] Unknown user on 7940 when adding Fast Dial
CSCeg55074	1700 GWs FXO ports are allowed to be configured for diff signaling.
CSCsa65740	ONLINE HELP Ring tone help screen needs to replace Alert with Ring
CSCsa66535	ONLINE HELP Device Configuration help need updated with new submenus
CSCsa66557	ONLINE HELP Help info for editing IP address needs additional steps
CSCsa66579	ONLINE HELP Erase softkey help under Settings needs more information
CSCsa76658	ONLINE HELP Help for Network Settings DNS Server 1 returns error
CSCsa83588	ONLINE HELP Default softkey under some User Preferences returns no help
CSCsa85476	No Help content for the softkey OPickUp.
CSCed94835	Greyed ERASE softkey is actually enabled
CSCee90845	Caller ID gone from shared line after a barge
CSCeg25405	> in 7940/60 i-button help text
CSCsa65880	sidecar lamp shows red for barge/cbarged calls
CSCsa68706	7960/40 Device Info page does not follow Message Waiting Lamp Policy
CSCsa69490	Display settings on Phone should be changed for Restricted Display
CSCsa73129	7960 can load a Ringlist.xml with more than 50 entries

CSCsa73355	Remove conditional code
CSCsa73918	IPPS authentication credentials, % sign not URL encoded
CSCsa73988	PC can't ping 7960 phone with dot1p configured
CSCsa60938	fclose thread flag should be set to true by default to avoid cpu spike
CSCef71610	CM disconnects call when phone goes off hook
CSCeg37721	CM Cas trunk in cm shows registered without NMHDV in ios router
CSCeg55229	illegal line errors in CCM log?
CSCeh39139	CallManager terminates unexpectedly,need to handle exception in dbprocs
CSCsa91198	CCM sends 2 StartMediaTransmi Msgs without a StopMediaTransmi between in
CSCsb12448	7960-7914 does not ring on incoming call if there is active call on 7914
CSCsb13798	Not receiving NOTIFY, Called Party Number is not displayed properly. ICT
CSCsb30975	CallControl Should look at all the Fac IE's in the CfDataInd signal
CSCsb31602	ReleaseComplete CRV High Order Bit Not Flipped
CSCsb09013	Admin page does not open after installation of SR1 Rc02
CSCsb14584	Unable to have a NON-QSIG ICT in a mixed routelist
CSCsb20477	CCM unexpectedly shutdown intermittently on changing the CCM server's timezone
CSCeg27056	Can not add more than 39 Devices in Media Resource Group
CSCsb02270	Unable to delete IPMA assistant in Catalan locale
CSCsa76660	Video capability for Communicator has to be added
CSCsa87252	support for EM2-HDA-4FXO in CCM
CSCef71775	CallManager ARQs for wrong E.164 address when calling H.323 client
CSCsb21995	AXL AddRegion does not support Default Codec With Other Regions
CSCsa64336	AXL return unknown error for updatePhone after IP service got deleted
CSCsa70674	StationUpdateCapability from VTA doesn't list all codecs in CCM Trace
CSCsa80318	Flow control is not symmetric if one video location is unlimited

Resolved Caveats for 4.1(3)es06 - Base ES for 4.1(3)sr1

CSCsa75117	Maketypes needs run after Product CSV's added to branch
CSCsa67496	Change default value for Disable Non-Registered SCCP Keepalives to False
CSCeg32248	TSP access violation with CCM 4.0
CSCef01691	802.1x auth state remains after PC disconnect
CSCef34334	Incorrect status msg when no ctl on phone and modified ctl dwnld
CSCef67145	7960/40 does not support QueryStringParam as documented in SDK
CSCeg27729	IPSvcSupported xml fields size are 1 less than max
CSCeg27734	IPsvcNew http headers support as per SDK 4.0(1)
CSCeg41715	Lock icon overlaps to page title text
CSCeg45665	Mid-call video starts when active call is in mute state
CSCeg50933	Phone shows encrypted call with CM 3.3

CSCeg59026	Security Configuration menu name should be separate from title
CSCeg60220	Clear softkey doesnt clear interface stats on HTTP page
CSCeg67817	Autodial fails on choosing hold option for the current call
CSCeg76026	Not able to scroll down to see help pages displayed by i button
CSCeg81361	7940/60 phone should use HTTP 1.1 for URL with IP address
CSCeg81455	Auto line select enabled prevent use of softkeys on 1st line
CSCeg90188	7960 stuck in booting process when press service before phone alive
CSCeh01099	7960/7940Voice Quality Degradation With Echo Back To Remote Party
CSCeh07336	Shared line call doesnt display toggling between lines correctly
CSCsa61784	Support calloc caller PC broke LA built.
CSCsa65899	Phone connects to secure SRST if bad config
CSCsa66918	Clouseau debug infrastructure implementation in 7960 sccp phones.
CSCsa69233	Retain old BA while LA upgrade
CSCsa71367	Disable the display debug tracing by default on 7960 phones
CSCed39346	Update copyright year on mid-range IP Phone boot display
CSCsa68462	After a preserved calls is terminated, the phone is stuck
CSCsa90217	Key rollover with Hold and EndCall Softkeys causes wrong action
CSCsa97383	7940/60 stuck in Configuring CM List state
6608	
CSCeg06661	6608 Fa Relay debugs in D00404 firmware need to be same as D00403
CSCeg31788	6608 inbound call mistaken for hookflash
CSCsa60692	ICMP Hard error handling
CSCsa63950	Dicktracy Remove unnecessary DSP and MLPP related messages.
CSCsa64458	6608 Dicktracy Reduce trunk flash timer from 700ms to 400ms.
CSCsa88299	Burst of static during ringback and connect on calls through 6608
6608/6624	
CSCsa63396	Integrate 4.3.25 DSP firmware for 6608
6624	
CSCef01551	6624 FXS port is unavalable for 2 mins after disabling and enabling
CSCef62209	updation on 6624 does not reflect on port configuration page.
CSCin80851	FAC tone played continuously on using non default network locale
7905/7912	
CSCeg27958	TFTP Client Busy Retry Behavior
CSCeg51314	7912 doesnt display correct Softkeys when using MCDN feature
CSCeg77784	IP Phone 7905 not responding to http commands

CSCeg87585	7912 cant ring immediately when receiving a call after fallback
CSCeh01236	MWI will be turned off by incoming call
CSCeh05420	7905/12 display English prompt at Services page
CSCeh06814	7912 ignores StationClearPriNotifyMessage from CME
CSCsa63741	Authentication delay between IP Phone 7905 and CM 5.0 is to long
CSCsa67687	Issues with processing of DNS packets
CSCsa71521	7912 RTP URI push during call requires user to cycle hook twice to end
CSCsa72417	7912 dies when configuring Graphics via TFTP on CCM 4.1
CSCsa74660	During cross upgrade, power off/on the phone & the phone never come up
CSCsa78892	Found dtmf digits fail when calling into Meeting Place IVR.
7920	
CSCeg33605	BSSID is all Zeros in Reassociation Packets
CSCeg40244	Site Survey Detail Shows the Same Info for All APs Sometimes
CSCeh03999	7920 Does Not Answer IGMP Query
CSCeh06553	7920 Could Get Into Continuous Roaming Loop When CU Is High
CSCsa61019	7920 May Get 1 Way Audio Without ARP-Caching
CSCsa61075	7920 Will Sometimes Show RSSI = 1
CSCsa74624	Packets are Sent at 1mbps rate Off Call When 7920 Uses a Non-Auto Rate
CSCsa75133	7920 Advertises All Rates Are Supported When Non-Auto Rate Is Configured
CSCsa77405	Get association timeouts sometimes with Aruba APs
7940/60	
CSCef22347	Video stream not terminated when CM is down Bsphere 2628
CSCef39695	NetworkConfigurationX tag names do not match Network Config UI
CSCef79801	Help for side car buttons throw an error
CSCeg27729	IPSvcssupported xml fields size are 1 less than max
CSCeg41715	Lock icon overlaps to page title text
CSCeg46352	Idle URLRefresh page does not recover after a packet loss
CSCeg55180	Phone accepts invalid/Reserved/Multicast IP address
CSCeg60195	invalid display by ip phone on key pad uris push
CSCeg64136	phone not updating volume changes during call preservation state
CSCeg67958	Handle current call not displayed on dialing from directories
CSCeg76034	pressing first line speed dial causes second line to go offhook.
CSCeg82422	No PORT_UP event on 7940 if PCport on Phone changed frm 10Mbps-100Mb
CSCeg90312	phone sends tftp request to ip address 0.0.0.0
CSCeh01187	Phone does not retains Volume Settings changes
CSCsa60315	7960/40 phone will not fail back to primary
CSCsa63893	Change in behavior of resuming the call that is onhold on IP Phone,7.1.2

CSCsa69644	speaker button won't work with sidecar
CSCsa67239	7940/7960 display HTTP error[11] when pressing Services/Directory button
CSCsa90217	Key rollover with Hold and EndCall Softkeys causes wrong action
7970/7971	
CSCec09013	Some items of Streaming Statistics from 7970 inconsistent w/ 7960s
CSCec70969	Headset status indicator incorrect after 7970 reboot
CSCee56313	7970 incorrect LineType for some line buttons
CSCee88177	7970 not auto answer with headset after restart w/ headset light on
CSCee92103	7970 not put active call in focus after incoming call disconnected
CSCef24496	Phone restart with lower line rate of multicast/broadcast traffic
CSCef28727	7970 fails to reregister after temporary WAN failure
CSCef31899	Ringer volume and other parameters are not configured after DSP reset
CSCef48700	Sidetone on handset after reset
CSCef54947	7970 ICMP hard errors behavior changes
CSCef61608	7970 does not pick up the line when configured share line
CSCef75668	Extra ring heard when answering call after adjusting volume
CSCef83454	7970 RTPRx/RTPMRx URI syntax error allowed
CSCef89557	Possible deadlock situation in msg queue software
CSCef90046	Phone stuck at Configuring IP after prolonged CCM disconnect/recon
CSCef94516	7970 drops host in DNS queries with subdomains
CSCeg01679	Skate Security config menu opt 5 and 6 display wrong softkeys
CSCeg01729	7970 RTPRx/RTPMRx URI opens invalid port by default
CSCeg02413	Phone lockupCSCeg04380
CSCeg04380	7970 gethostbyname() does not return multiple IP addresses
CSCeg08171	Mute signal heard on network
CSCeg08210	When resetting the phone (***#) PC loses network connectivity
CSCeg08513	phone freezes during reboot with mqThread problem
CSCeg08536	7970 phone failover to SRST takes more than 6 minutes
CSCeg09136	Last digit not displayed when dialing from keypad
CSCeg11907	JavaException using Navigate Keypad when call on hold
CSCeg14178	Phone continue to stay with Requesting msg, cancel key has no effect
CSCeg15510	Java exception when 7970 configed with sidecar but none attached
CSCeg16228	7970 Phone hangs on changing existing speed dial from phone (CME)
CSCeg18394	7970 unexpectedly shutdown when access protected URL 2nd time
CSCeg18397	Onhook Dialing will not accept * or # as first digit
CSCeg19277	Core dump of Sunvm.cnu when web-access is disabled & then enabled
CSCeg19644	Attempt to load diagnostic image file causes CNU reset
CSCeg20602	Onhook Dialing is available when the phone is not registered

CSCeg20801	7971 Multicast traffic dest to PC dropped by switch in phone.
CSCeg21679	RTPTx Stop not being executed
CSCeg23307	7971 Unplugging and plug the ethernet cable, loses VLAN id
CSCeg23928	Incorrect time for New Zealand time zone (GMT+12)
CSCeg24131	7970 drops keys if pressed too fast
CSCeg24150	EM logged off profile keeps CFA icon
CSCeg24646	Update handling of init.conf authentication settings
CSCeg26725	SA Dereferencing pointer to freed memory in Core/CNU/NetSys/udp.c
CSCeg26730	SA expression must be a modifiable lvalue in Core/Apps/cmds/ttrace/
CSCeg27936	SA Freeing pointer to already freed memory in Core/Apps/daemons/DHC
CSCeg28923	Broken autosensing on type-2 cabling (BU-3494)
CSCeg32572	Makaha power request numbers are wrong
CSCeg33915	ListenerManager allows for multiple listener
CSCeg34288	Memory leak when press keys in predial
CSCeg34303	Memory leak on startup in Call History property
CSCeg35901	7971 phone not upgrading load, using device defaults.
CSCeg36423	Phone reloads from nmap connect scan
CSCeg36441	Stream.c flood reloads phone
CSCeg36667	Failover fail on 7971 phone with CM 3.3.4(SR2)
CSCeg37001	CVTA with 7970 messes up audio caps
CSCeg37674	Phone stuck at Updating Software
CSCeg37733	7970 - does not report Dest Unreach on sendto()
CSCeg37736	Ethernet Disconnected message interferes with display (BU-3572)
CSCeg38291	EndCall softkey doesn't work when CM down and other end had hit Hold
CSCeg38922	7971 Low power backlight needs to be 14
CSCeg39262	7970 - only retries 4 times after leaseT1 expires
CSCeg39679	7970 hangs at config IP after reset
CSCeg40217	Unexpected DHCP Renew after Release operation
CSCeg42114	Shared System Threads create debugging problems
CSCeg42910	Cut through on speaker phone take approx one sec
CSCeg42980	Line button becomes useless after try dialing from call history
CSCeg44232	Timer object should allow ITimerListeners to disable timerCancelled
CSCeg45241	7970 phone does not close the sockets automatically
CSCeg45714	Mid-call video starts when active call is on mute
CSCeg46269	7970 registering with CM when a active call is in place
CSCeg47854	7971 phone reset after hold/resume duration
CSCeg49303	Phone freeze after the extension mobility duration test was run
CSCeg50192	7970 hangs intermittently while attempting EM login/logout
CSCeg50697	XML parse error when text object with 4000 chars of text is sent

CSCeg53154	Multiple restart from CM causes phone to freeze up
CSCeg55288	http push may stop working
CSCeg55617	Console shows CONSOLE TOO SLOW! Skipping 0 log files!
CSCeg56405	Trace does not include key press information
CSCeg56835	7971 Phone ignore vvlan information from switch port
CSCeg57746	CVTA does not receive information on calls active when PC plugged in
CSCeg58032	Phone stuck after erase operation
CSCeg58939	7971 does not comply with 802.3af power specification
CSCeg60165	Phone can lose VLAN id with broadcast storms in the network
CSCeg60175	PC attached to Phone loses network after multiple phone reload
CSCeg61314	7971 phone re-boots when SYNC_RCVD state sttack was run
CSCeg62838	Enable 802.3x flow control
CSCeg68331	7970 plays loud comfortable noise when using G.729 codec
CSCeg72231	Can not accept calls when call history is empty and in focus
CSCeg74764	7970 change between daylight and standard time 1 hour too early
CSCeg76679	Ringer stops working if press speaker right after adjust ring volume
CSCeg78507	Phone restarts exposes memory leak in the CallAgent module
CSCeg81433	Call Info gone but voice path remains after brief Ethernet disconnect
CSCeg86356	Phone does not take Service URL w/ no label
CSCeg86368	7971 w/ PC connected not operate in low power mode using ieee inline
CSCeg87739	7970 does not display missed call info after waking the display
CSCeg88344	Phone stuck under simClient duration test
CSCeg88372	7970 not alllow user to set IP Address Release as No
CSCeg88383	7970 should display IP address released
CSCeg88682	7970 missing date on console logs, status messages & debug display
CSCeg89894	7970 Autodial postponds to dialed # if display name contaions #s
CSCeh02213	UI issue services tab not coming to foreground in push scenario
CSCeh03588	7971 continuously resets if dot1x configured on switch interface
CSCin79793	Services Changing volume while RTPRx - softkey gets stuck at Save
CSCsa60306	shownet command in cnush gives wrong output
CSCsa61795	7971 accepts untagged packets while on a voice VLAN
CSCsa63639	AbbrDial softkey appears on 7970 phone in CM3.x
CSCsa65915	HTTP Push requests has successful response, but UI does not display XML
CSCsa67507	7970 does not properly reset causing sessions hung in LAST_ACK on CCM
CSCsa69149	7971 PC port does not show what is configured
CSCsa69209	CP-7970 Fails to Boot up if 'switchport voice vlan dot1p' is configured
CSCsa69667	Bad voice on 7971 phone with 10% broadcast traffic
CSCsa69676	Broadcast traffic throttling rate very low w/ load 69 on 7971 phone
CSCsa69678	7971 phone only allows 10M (1%) broadcast traffic send to PC

CSCsa69770	Phone does not pass thru all multicast traffic to PC
CSCsa72049	7971 switch port stops transmitting frames causing phone to unregister
CSCsa74481	Network Statistics does not display Port 1 or Port 2 status information
CSCsa74877	7971 - PPU workaround does not set forced link speed correctly
CSCsa74882	7971 - change CDP from a mgmt packet to a mcast packet in ATU
CSCsa75445	7971 - enable VLAN 1 and VLAN 0
CSCsa77101	Phone unexpectedly shutdown with in half an hour ,when XML boundary objects script was
CSCsa77673	Phone unexpectedly shutdown for 200 calls per device case
CSCsa88581	7970 won't boot w/ inline power

File Versions included in 4.1(3)SR8a

File Name	Version
AdministrativeReportingTool.exe	4.1(0.48)
ASTIsapi.dll	3.3.2.0
Aupair.exe	4.1.3.20019
AuthFilt.dll	4.0.0.0
BulkAdministrationTool.exe	5.1(4f)
CallBackService.exe	4.1.3.20043
ccm.exe	4.1.3.22844
CcmServRtmtPlugin.exe	4.00.0002
CiscoAttendantConsoleClient.exe	1.4.1.17
CiscoCTLClient.exe	2.1 (222)
CiscoJTAPIClient.exe	2.1(3.30)
CiscoMessagingInterface.exe	4.1.3.10026
CiscoTSP.exe	4.1(1.4)ES13
CPidMgr.exe	3.0.0.0
ctftp.exe	4.1.3.20844
CtftpChangeNotify.dll	4.1.3.10054
CTIManager.exe	4.1.3.23844
DBConvert.dll	4.1.0.11
DBL.dll	4.1.3.20009
DBLRT.dll	4.1.3.20008
DBLX.dll	4.1.3.10034
DNASetup.exe	4.1(3)ES
InsertCDR.exe	4.1.3.20018
IPMAAssistantConsole.exe	14.0.0.162

Ipvmsapp.exe	4.0.0.20
IpVms.sys	4.0.0.25
MADirectory.dll	1.0.0.1
MediaAppPerfMon.dll	
QRTFileMgr.exe	4.1.3.10080
RisDC.exe	4.1.3.10057
RISX.dll	3.3.0.2
SnmpCcmImpl.dll	4.1.1.2
SOAPISAPI.dll	4.1.3.10083
SSAPIDLL.DLL	4.1.3.10025
tcdsrv.exe	1.4.1.13
ToolforAutoRegisteredPhonesSupport.exe	5.1(4b)
UpdateLoadInfo.exe	4.1.0.11
UserPermissions.dll	4.0.0.0

Firmware Versions included in 4.1(3)SR8a

4.1(3) Devpack 83	
7914 14-Button Line Expansion Module	S00105000300
Analog Access WS-X6624 Load	A00204000013
ATA18X	ATA030203SCCP051201A
Conference Bridge WS-X6608	C00104000003
Digital Access WS-X6608 Load	D00404000032
IP Phone 7902g	CP7902080002SCCP060817A
IP Phone 7905g	CP7905080003SCCP070409A
IP Phone 7906	SCCP11.8-4-1SR2S
IP Phone 7910	P00405000700
IP Phone 7911	SCCP11.8-4-1SR2S
IP Phone 7912g	CP7912080003SCCP070409A
IP Phone 7920	cmterm_7920.4.0-03-02
IP Phone 7921	D00404000031
IP Phone 7921G	CP7921G-1.2.1
IP Phone 7935	P00503021900
IP Phone 7936	cmterm_7936.3-3-16-0
IP Phone 7937	apps37sccp.1-2-1-0
IP Phone 7940/7960	P00308000900
IP Phone 7941/7961	SCCP41.8-4-1SR2S
IP Phone 7942/7962	SCCP42.8-4-1SR2S
IP Phone 7945/7965	SCCP45.8-4-1SR2S

IP Phone 7970/7971	SCCP70.8-4-1SR2S
IP Phone 7975	SCCP75.8-4-1SR2S
IP Phone 7985	cmterm_7985.4-1-6-0
Media Termination Point WS-X6608	M00104000006

Determining the Software Version

You can determine the version of Cisco Unified CallManager software that is running on your server by accessing Cisco Unified CallManager Administration and then clicking **Details**.

The following information displays:

- Cisco Unified CallManager System version
- Cisco Unified CallManager Administration version
- Cisco Unified CallManager Installation ID
- Database information

Compatibility Matrix and Supported Upgrades

You can find the minimum versions with which Cisco Unified CallManager release 4.1(3) has been tested and which previous release of Cisco Unified CallManager has upgrade support by accessing the following URL: http://www.cisco.com/en/US/docs/voice_ip_comm/cucm/compat/ccmcompmatr.html

Note: Be aware that the release of Cisco IP telephony products does not always coincide with Cisco Unified CallManager releases. If a product is not compatible with Cisco Unified CallManager, you must wait until a compatible version of that product becomes available before you can upgrade to this release of Cisco Unified CallManager. For the most current compatibility combinations and defects, refer to the documentation that is distributed with the Cisco IP telephony products.

Locale Installer for Cisco Unified CallManager

For optimal performance, be sure that you use the Cisco IP Telephony Locale Installer that is specific to the version of Cisco Unified CallManager that you use. Be aware that all phrases may not display in the desired locale when you upgrade to a different version of Cisco Unified CallManager. Refer to the readme file that is posted with the Cisco IP Telephony Locale Installer software on the following URL for the complete list of supported languages:

<http://www.cisco.com/kobayashi/sw-center/telephony/callmgr/locale-installer.shtml>

Each release of Cisco Unified CallManager may support a different number of locales. The full suite of Locale Installers that work with each applicable version of Cisco Unified CallManager can be found on <http://www.cisco.com> about 8-10 weeks after the English version becomes available. You can download the Locale Installers for all languages that are supported with Cisco Unified CallManager from the following location: <http://www.cisco.com/kobayashi/sw-center/telephony/callmgr/locale-installer.shtml>

Note: When using locales, Cisco recommends that you wait until the locale installer that specifically supports the version of Cisco Unified CallManager that you use becomes available before you upgrade your system. Because some incompatibilities may exist between releases, be sure to only use the locale installer that specifically supports your version of Cisco Unified CallManager.

Related Documentation

For additional information about Cisco Unified CallManager, refer to the following documentation:

Release Notes for Cisco Unified CallManager Release 4.1(3)

Refer to the following URL for maintenance release notes that are relevant to this release of Cisco Unified CallManager: http://www.cisco.com/univercd/cc/td/doc/product/voice/c_callmg/4_1/rel_note/index.htm

Cisco Unified CallManager Document Guide

Refer to the following URL for a list of documents that are related to Cisco *Unified* CallManager release 4.1(3): http://www.cisco.com/en/US/docs/voice_ip_comm/cucm/docguide/4_1/dg413.html

To access the documentation suite for voice products, navigate to the following URL:

<http://www.cisco.com/univercd/cc/td/doc/product/voice/>

To access the latest software upgrades and related documentation for Cisco Unified CallManager, navigate to the following URL and then choose the applicable version:

<http://www.cisco.com/kobayashi/sw-center/sw-voice.shtml>

Obtaining Documentation, Obtaining Support, and Security Guidelines

For information on obtaining documentation, obtaining support, providing documentation feedback, security guidelines, and also recommended aliases and general Cisco documents, see the monthly What's New in Cisco Product Documentation, which also lists all new and revised Cisco technical documentation, at: <http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Cisco.com

You can access the most current Cisco documentation at this URL:

<http://www.cisco.com/univercd/home/home.htm>

You can access the Cisco website at this URL:

<http://www.cisco.com/>

You can access international Cisco websites at this URL:

http://www.cisco.com/public/countries_languages.shtml

Documentation DVD

Cisco documentation and additional literature are available in a Documentation DVD package, which may have shipped with your product. The Documentation DVD is updated regularly and may be more current than printed documentation. The Documentation DVD package is available as a single unit.

Registered Cisco.com users (Cisco direct customers) can order a Cisco Documentation DVD (product number DOC-DOCDVD=) from the Ordering tool or Cisco Marketplace.

Cisco Ordering tool:

<http://www.cisco.com/en/US/partner/ordering/>

Cisco Marketplace:

<http://www.cisco.com/go/marketplace/>

Ordering Documentation

You can find instructions for ordering documentation at this URL:

http://www.cisco.com/en/US/docs/general/illus_process/PDI/pdi.htm

You can order Cisco documentation in these ways:

Registered Cisco.com users (Cisco direct customers) can order Cisco product documentation from the Ordering tool: <http://www.cisco.com/en/US/partner/ordering/index.shtml>

Nonregistered Cisco.com users can order documentation through a local account representative by calling Cisco Systems Corporate Headquarters (California, USA) at 408 526-7208 or, elsewhere in North America, by calling 1 800 553-NETS (6387).

Obtaining Additional Publications and Information

Information about Cisco products, technologies, and network solutions is available from various online and printed sources.

Cisco Marketplace provides a variety of Cisco books, reference guides, and logo merchandise. Visit Cisco Marketplace, the company store, at this URL:

<http://www.cisco.com/cgi-bin/marketplace/welcome.pl>

Cisco Press publishes a wide range of general networking, training and certification titles. Both new and experienced users will benefit from these publications. For current Cisco Press titles and other information, go to Cisco Press at this URL: <http://www.ciscopress.com/>

Internet Protocol Journal is a quarterly journal published by Cisco Systems for engineering professionals involved in designing, developing, and operating public and private internets and intranets. You can access the Internet Protocol Journal at this URL <http://www.cisco.com/ipj>

World-class networking training is available from Cisco. You can view current offerings at this URL: <http://www.cisco.com/web/learning/index.html>

Documentation Feedback

You can send comments about technical documentation to bug-doc@cisco.com.

You can submit comments by using the response card (if present) behind the front cover of your document or by writing to the following address:

Cisco Systems
Attn: Customer Document Ordering
170 West Tasman Drive
San Jose, CA 95134-9883

We appreciate your comments.

Cisco Product Security Overview

Cisco provides a free online Security Vulnerability Policy portal at this URL:
http://www.cisco.com/en/US/products/products_security_vulnerability_policy.html

From this site, you can perform these tasks:

- Report security vulnerabilities in Cisco products.
- Obtain assistance with security incidents that involve Cisco products.
- Register to receive security information from Cisco.

A current list of security advisories and notices for Cisco products is available at this URL:
<http://www.cisco.com/go/psirt>

If you prefer to see advisories and notices as they are updated in real time, you can access a Product Security Incident Response Team Really Simple Syndication (PSIRT RSS) feed from this URL:
http://www.cisco.com/en/US/products/products_psirt_rss_feed.html

Reporting Security Problems in Cisco Products

Cisco is committed to delivering secure products. We test our products internally before we release them, and we strive to correct all vulnerabilities quickly. If you think that you might have identified a vulnerability in a Cisco product, contact PSIRT:

Emergencies security-alert@cisco.com

Nonemergencies psirt@cisco.com

We encourage you to use Pretty Good Privacy (PGP) or a compatible product to encrypt any sensitive information that you send to Cisco. PSIRT can work from encrypted information that is compatible with PGP versions 2.x through 8.x. Never use a revoked or an expired encryption key. The correct public key to use in your correspondence with PSIRT is the one that has the most recent creation date in this public key server list:

<http://pgp.mit.edu:11371/pks/lookup?search=psirt%40cisco.com&op=index&exact=on>

In an emergency, you can also reach PSIRT by telephone:

1 877 228-7302

1 408 525-6532

Obtaining Technical Assistance

For all customers, partners, resellers, and distributors who hold valid Cisco service contracts, Cisco Technical Support provides 24-hour-a-day, award-winning technical assistance. The Cisco Technical Support Website on Cisco.com features extensive online support resources. In addition, Cisco Technical Assistance Center (TAC) engineers provide telephone support. If you do not hold a valid Cisco service contract, contact your reseller.

Cisco Technical Support Website

The Cisco Technical Support Website provides online documents and tools for troubleshooting and resolving technical issues with Cisco products and technologies. The website is available 24 hours a day, 365 days a year, at this URL:

<http://www.cisco.com/techsupport>

Access to all tools on the Cisco Technical Support Website requires a Cisco.com user ID and password. If you have a valid service contract but do not have a user ID or password, you can register at this URL:

<http://tools.cisco.com/RPF/register/register.do>

Use the Cisco Product Identification (CPI) tool to locate your product serial number before submitting a web or phone request for service. You can access the CPI tool from the Cisco Technical Support Website by clicking the Tools & Resources link under Documentation & Tools. Choose Cisco Product Identification Tool from the Alphabetical Index drop-down list, or click the Cisco Product Identification Tool link under Alerts & RMAs. The CPI tool offers three search options: by product ID or model name; by tree view; or for certain products, by copying and pasting show command output. Search results show an illustration of your product with the serial number label location highlighted. Locate the serial number label on your product and record the information before placing a service call.

Submitting a Service Request

Using the online TAC Service Request Tool is the fastest way to open S3 and S4 service requests. (S3 and S4 service requests are those in which your network is minimally impaired or for which you require product information.) After you describe your situation, the TAC Service Request Tool provides recommended solutions. If your issue is not resolved using the recommended resources, your service request is assigned to a Cisco TAC engineer. The TAC Service Request Tool is located at this URL:

<http://www.cisco.com/techsupport/servicerequest>

For S1 or S2 service requests or if you do not have Internet access, contact the Cisco TAC by telephone. (S1 or S2 service requests are those in which your production network is down or severely degraded.) Cisco TAC engineers are assigned immediately to S1 and S2 service requests to help keep your business operations running smoothly.

To open a service request by telephone, use one of the following numbers:

Asia-Pacific: +61 2 8446 7411 (Australia: 1 800 805 227)

EMEA: +32 2 704 55 55

USA: 1 800 553-2447

For a complete list of Cisco TAC contacts, go to this URL:

<http://www.cisco.com/techsupport/contacts>

Definitions of Service Request Severity

To ensure that all service requests are reported in a standard format, Cisco has established severity definitions.

Severity 1 (S1) Your network is down, or there is a critical impact to your business operations. You and Cisco will commit all necessary resources around the clock to resolve the situation.

Severity 2 (S2) Operation of an existing network is severely degraded, or significant aspects of your business operation are negatively affected by inadequate performance of Cisco products. You and Cisco will commit full-time resources during normal business hours to resolve the situation.

Severity 3 (S3) Operational performance of your network is impaired, but most business operations remain functional. You and Cisco will commit resources during normal business hours to restore service to satisfactory levels.

Severity 4 (S4) You require information or assistance with Cisco product capabilities, installation, or configuration. There is little or no effect on your business operations.

CCVP, the Cisco Logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, *Packet*, PIX, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries. All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0612R)

© 2008 Cisco Systems, Inc. All rights reserved.