

HPE 3PAR OS 3.2.1 MU2 Patch 36 Release Notes

This release notes document is for Patch 36 and intended for HPE 3PAR Operating System Software 3.2.1.200 (MU2)+P13.

Part Number: QL226-99149 Published: May 2016

Edition: 1

© Copyright 2016 Hewlett Packard Enterprise Development LP

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Acknowledgments

Intel®, Itanium®, Pentium®, Intel Inside®, and the Intel Inside logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Microsoft® and Windows® are trademarks of the Microsoft group of companies.

Adobe® and Acrobat® are trademarks of Adobe Systems Incorporated.

Java and Oracle are registered trademarks of Oracle and/or its affiliates.

UNIX® is a registered trademark of The Open Group.

Documentation

For the latest version of this document, go to www.hpe.com/info/enterprise/docs.

Contents

1	Purpose	4
	Guidance	
	Prerequisites	4
	Details	
	Warnings, cautions and notes	4
	Affected components	4
	Modifications	4
	Verification	5

1 Purpose

HPE 3PAR OS 3.2.1 MU2 P36 provides improved error handling for physical disk (PD) failures and improvements to servicemag.

Guidance

This patch is intended for 3PAR OS 3.2.1 MU2 and should be installed as-needed based on the modifications included in the patch. All supported hardware platforms are susceptible to the issues corrected in this patch.

Prerequisites

• **SP**: 4.3.0.GA-24 plus the latest SP patch (if any)

• **OS**: OS-3.2.1.200-MU2 + P13

Details

 Affected packages: tpd-kernelpatch, tpd-libcli, tpd-libgalaxy, tpd-libhitachi, tpd-libstec-mach-8, tpd-libtextconv, tpd-sysmgr, tpd-utils, tpd-prerevert

Obsoletes: OS-3.2.1.200-P16

Build version: 3.2.1.408

Revertible: Yes

Warnings, cautions and notes

NOTE:

- Applying this patch to the 3PAR OS might restart the affected OS components. With these
 restarts, events and alerts might be generated and this is an expected behavior. The system
 continues to serve data, but existing CLI or SSMC sessions might be interrupted.
- Hewlett Packard Enterprise recommends installing patches in the same sequence as they
 are released, unless instructed otherwise.
- When displaying the showversion command output from the SP, the CLI Client version is fixed in the SP code, and might differ from the output displayed from any other system.

Affected components

Component	Version
System Manager	3.2.1.408 (P36)
TPD Kernel Patch	3.2.1.408 (P36)

Modifications

This patch includes the following modifications to 3PAR OS 3.2.1 MU2:

- Servicemag now prevents LD allocation and chunklet movement on the serviced physical disks.
- The lifetime counts of uncorrectable errors is now monitored. When it exceeds preset limits, an event is generated and the drive is evacuated so it can be replaced.

Verification

The installation of Patch 36 can be verified from an interactive CLI session. Issue the CLI command showversion -a -b to verify that Patch 36 is listed.