



Hewlett Packard Hewlett Packard Enterprise Support Center Enterprise

Drivers & software

HPE StoreEver MSL6480 Tape Library Firmware

Type:	Firmware
Version:	6.30(16 May 2023)
Upgrade Requirement:	Recommended
Operating System(s):	OS Independent

Description

HPE StoreEver MSL6480 Tape Library firmware. This firmware can be installed from the Remote Management Interface (RMI). For instructions, see the release notes or the HPE StoreEver MSL6480 Tape Library User and Service Guide.

Release Notes

End User License Agreements:

HPE Software License Agreement v1

(<https://downloads.hpe.com/pub/softlib2/software1/doc/p1796552785/v113125/eula-en.html>)

Important:

HPE GPG Signature Verification

The .sig file on this page can be used with GPG to validate and verify the digital signature of the .frm firmware file on this page.

GPG Signature Verification Procedure:

Verify the signature by running 'gpg --verify ' Name.of.Sig.File'

Note: The HPE Public Key, hpePublicKey2048_key1.pub (fingerprint: 26C2B797), is required to support signature verification and is available from the HPE Software Delivery Repository (SDR)

(<https://downloads.linux.hpe.com/SDR/keys.html>)

(<https://downloads.linux.hpe.com/SDR/keys.html>). Download the HPE Public key and import the key using "gpg --import hpePublicKey2048_key1.pub" command before running the verification command.

HPE StoreEver MSL6480 Tape Library Version 6.30 Firmware

Release Notes

Abstract

This document provides information about enhancements and fixes to the firmware for the HPE StoreEver MSL6480 Tape Library.

Part Number: 20-STVM6630-RN-ED1

Published: June 2021

Edition: 2

© Copyright 2021 Hewlett Packard Enterprise Development LP

Notices

The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from Hewlett Packard Enterprise required for possession, use, or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Links to third-party websites take you outside the Hewlett Packard Enterprise website. Hewlett Packard Enterprise has no control over and is not responsible for information outside the Hewlett Packard Enterprise website.

Acknowledgments

Intel[®], Itanium[®], Optane[™], Pentium[®], Xeon[®], Intel Inside[®], and the Intel Inside logo are trademarks of Intel Corporation or its subsidiaries.

AMD and the AMD EPYC[™] and combinations thereof are trademarks of Advanced Micro Devices, Inc. Microsoft[®] and Windows[®] are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Adobe[®] and Acrobat[®] are trademarks of Adobe Systems Incorporated.

Java[®] and Oracle[®] are registered trademarks of Oracle and/or its affiliates.

UNIX[®] is a registered trademark of The Open Group.

All third-party marks are property of their respective owners.

Description

This release includes updated firmware for the HPE StoreEver MSL6480 Tape Library. This firmware can be updated from the library remote management interface (RMI) or operator control panel (OCP).

Library firmware version

6.30

Update recommendation

Update Recommendation: Recommended.

Supersedes information

Supersedes: All previous firmware versions.

Product models

This release applies to all HPE StoreEver MSL6480 Tape Libraries.

Languages

Languages supported for this release:

- English
- Japanese for the library RMI

Compatibility notes

This version of MSL6480 firmware is compatible with:

- HPE Library and Tape Tools (L&TT) standalone version 6.0 and newer
- Command View for Tape Libraries (Command View TL) version 6.0.74 and newer
- TapeAssure Advanced (license installed and used with Command View TL 6.0.74 and newer)
- Data Verification (license installed and used with Command View TL 6.0.74 and newer)

Bar code label length

The industry standard length of bar code labels is eight total characters, including the media ID. Because of this, Hewlett Packard Enterprise tape libraries and associated application software (such as Command View TL, and other backup applications) are extensively tested by Hewlett Packard Enterprise using eight character bar code labels. Although the MSL6480 can read labels with more than eight characters, some applications might not operate correctly with these labels. For compatibility with other libraries and with applications, Hewlett Packard Enterprise highly recommends using eight character bar code labels when possible.

MSL Encryption Kit token backup file format change

Firmware version 4.30 changed the MSL Encryption Kit token backup file format and file extension. Hewlett Packard Enterprise recommends creating a token backup file after loading 4.30 or later firmware. The new token backup file format is compatible with other MSL tape libraries.

When changing firmware

Because each firmware revision contains new features, some configuration settings are not retained when earlier firmware versions are loaded. Hewlett Packard Enterprise recommends against downgrading firmware unless instructed to do so by a support engineer. Always verify configuration settings after installing firmware.

Enhancements

The following enhancements are included in this firmware version:

- Updated Python to version 2.7.16
- Updated OpenLDAP to 2.4.49
- Updated PHP to 7.3.14
- Updated bind9 dig to 9.11.10
- Updated sqlite to 3.29.0
- Updated lighttpd to 1.4.54
- Updated Agent++ to 4.2.0
- Updated SNMP++ to 3.3.13
- Added "Firmware Type" to drive status page on RMI
- Enhanced web security settings
- Enhanced several error messages to give more detail

- Improvements to CVTL integration
- Enhanced logging
- Improved IPv6 compatibility
- Improved LDAP configuration
- Improved Japanese language support
- Added Password Policy to allow setting minimum number of days before password can be changed

Fixes

- Updated OpenSSL to 1.1.1j with fixes for CVE-2019-1547, CVE-2019-1549, and CVE-2019-1563, CVE-2020-1967, CVE-202103449, CVE-2021-3450
- Fixed an issue with KMIP operating over IPv6
- Fixed an issue where tickets were not generated for missing top or bottom covers

Known issues and workarounds

- **Issue:** Pulling on the magazine handle while the library is unlocking the magazine can damage the library.

Workaround: When opening a magazine, wait until the OCP or RMI says that the magazine is unlocked before attempting to remove it.

- **Issue:** Command View for Tape Libraries (Command View TL) Data Verification tests yield “Test Incomplete” status after one of the following occurs:
 - Modifying the DVP partition
 - Adding, removing, or replacing a tape drive
 - Rebooting the library or drives, or taking a drive off line

Workaround: Stop and restart the Command View TL DV service.

1. Stop the Command View TL DV service.

- a. In Command View TL, open the Library page.
- b. Select the library that is configured for Data Verification.
- c. From the library screen, select Data Verification.
- d. Click Stop for the library to stop the DV service.

2. Use Command View TL or the library RMI or OCP to remove any media from drives assigned to the DVP partition.

3. In the Command View TL Data Verification screen for the library with Data Verification configured, start the DV service.

The DV service will rescan the slots and drives assigned to the DVP partition and restart the DV service.

- **Issue:** When using the Edge compatibility mode on some Internet Explorer 11 versions, the RMI logs out after starting a drive or library firmware update.

Workarounds:

- Log back in to the RMI and let the firmware upgrade complete. When updating drive firmware, you can log in immediately. When updating library firmware, you can log in when the library has completed initialization.
- Use a different browser when upgrading firmware from the RMI.

Installation instructions

RMI installation instructions

Procedure

1. Log in to the RMI as the administrator user.
2. From the Maintenance > Firmware Upgrades > System Firmware screen, browse to the location of the library firmware file and then click Upload.

OCP installation instructions

Procedure

1. Copy the firmware file to a USB flash drive.
2. Log in to the OCP as the administrator user.
3. Insert the USB flash drive into the USB port on the front of the library.
4. Navigate to the Maintenance > Firmware Upgrade > System Firmware screen, and then follow the prompts to complete the firmware upgrade.

Related information

The latest documentation is available in the Storage section of the Support Center

<https://www.hpe.com/support> (<https://www.hpe.com/support>).

To find documents for this product:

1. Type **MSL6480** in the search bar.
 2. Choose the MSL6480 from the product list.
 3. Select the Documents tab.
 4. Type the last part of the document name, for example Getting Started in the search box.
- HPE StoreEver MSL6480 Tape Library Getting Started Guide
 - HPE StoreEver MSL6480 Tape Library User and Service Guide
 - HPE StoreEver MSL6480 Tape Library Command Line Interface Guide
 - HPE StoreEver MSL Tape Libraries Encryption Key Server Configuration Guide
 - HPE StoreEverTape Libraries Failover User Guide

Websites

General websites

Single Point of Connectivity Knowledge (SPOCK) Storage compatibility matrix

<https://www.hpe.com/storage/spock> (<https://www.hpe.com/storage/spock>)

Storage white papers and analyst reports

<https://www.hpe.com/storage/whitepapers> (<https://www.hpe.com/storage/whitepapers>)

For additional websites, see [Support and other resources](#).

Support and other resources

Accessing Hewlett Packard Enterprise Support

- For live assistance, go to the Contact Hewlett Packard Enterprise Worldwide website:
<https://www.hpe.com/info/assistance> (<https://www.hpe.com/info/assistance>)
- To access documentation and support services, go to the Hewlett Packard Enterprise Support Center website:
<https://www.hpe.com/support/hpesc> (<https://www.hpe.com/support/hpesc>)

Information to collect

- Technical support registration number (if applicable)

- Product name, model or version, and serial number
- Operating system name and version
- Firmware version
- Error messages
- Product-specific reports and logs
- Add-on products or components
- Third-party products or components

Accessing updates

- Some software products provide a mechanism for accessing software updates through the product interface. Review your product documentation to identify the recommended software update method.
- To download product updates:
Hewlett Packard Enterprise Support Center
<https://www.hpe.com/support/hpesc> (<https://www.hpe.com/support/hpesc>)
Hewlett Packard Enterprise Support Center: Software downloads
<https://www.hpe.com/support/downloads> (<https://www.hpe.com/support/downloads>)
My HPE Software Center
<https://www.hpe.com/software/hpesoftwarecenter>
(<https://www.hpe.com/software/hpesoftwarecenter>)
- To subscribe to eNewsletters and alerts:
<https://www.hpe.com/support/e-updates> (<https://www.hpe.com/support/e-updates>)
- To view and update your entitlements, and to link your contracts and warranties with your profile, go to the Hewlett Packard Enterprise Support Center More Information on Access to Support Materials page:
<https://www.hpe.com/support/AccessToSupportMaterials>
(<https://www.hpe.com/support/AccessToSupportMaterials>)

IMPORTANT:

Access to some updates might require product entitlement when accessed through the Hewlett Packard Enterprise Support Center. You must have an HPE Passport set up with relevant entitlements.

Remote support

Remote support is available with supported devices as part of your warranty or contractual support agreement. It provides intelligent event diagnosis, and automatic, secure submission of hardware event notifications to Hewlett Packard Enterprise, which initiates a fast and accurate resolution based on the service level of your product. Hewlett Packard Enterprise strongly recommends that you register your device for remote support.

If your product includes additional remote support details, use search to locate that information.

HPE Get Connected

<https://www.hpe.com/services/getconnected> (<https://www.hpe.com/services/getconnected>)

HPE Pointnext Tech Care

<https://www.hpe.com/services/techcare> (<https://www.hpe.com/services/techcare>)

HPE Datacenter Care

<https://www.hpe.com/services/datacentercare> (<https://www.hpe.com/services/datacentercare>)

Warranty information

To view the warranty information for your product, see the links provided below:

HPE ProLiant and IA-32 Servers and Options

<https://www.hpe.com/support/ProLiantServers-Warranties>
(<https://www.hpe.com/support/ProLiantServers-Warranties>)

HPE Enterprise and Cloudline Servers

<https://www.hpe.com/support/EnterpriseServers-Warranties>
(<https://www.hpe.com/support/EnterpriseServers-Warranties>)

HPE Storage Products

<https://www.hpe.com/support/Storage-Warranties> (<https://www.hpe.com/support/Storage-Warranties>)

HPE Networking Products

<https://www.hpe.com/support/Networking-Warranties> (<https://www.hpe.com/support/Networking-Warranties>)

Regulatory information

To view the regulatory information for your product, view the Safety and Compliance Information for Server, Storage, Power, Networking, and Rack Products, available at the Hewlett Packard Enterprise Support Center:

<https://www.hpe.com/support/Safety-Compliance-EnterpriseProducts>
(<https://www.hpe.com/support/Safety-Compliance-EnterpriseProducts>)

Additional regulatory information

Hewlett Packard Enterprise is committed to providing our customers with information about the chemical substances in our products as needed to comply with legal requirements such as REACH (Regulation EC No 1907/2006 of the European Parliament and the Council). A chemical information report for this product can be found at:

<https://www.hpe.com/info/reach> (<https://www.hpe.com/info/reach>)

For Hewlett Packard Enterprise product environmental and safety information and compliance data, including RoHS and REACH, see:

<https://www.hpe.com/info/ecodata> (<https://www.hpe.com/info/ecodata>)

For Hewlett Packard Enterprise environmental information, including company programs, product recycling, and energy efficiency, see:

<https://www.hpe.com/info/environment> (<https://www.hpe.com/info/environment>)

Documentation feedback

Hewlett Packard Enterprise is committed to providing documentation that meets your needs. To help us improve the documentation, use the Feedback button and icons (located at the bottom of an opened document) on the Hewlett Packard Enterprise Support Center portal (<https://www.hpe.com/support/hpesc>) (<https://www.hpe.com/support/hpesc>) to send any errors, suggestions, or comments. All document information is captured by the process.

Revision History

Version

6.70(7 Nov 2025)

Version

6.60(9 Sep 2024)

Version

6.40(16 May 2023)

Version

6.30(16 May 2023)

Legal Disclaimer :Products sold prior to the November 1, 2015 separation of Hewlett-Packard Company into Hewlett Packard Enterprise Company and HP Inc. may have older product names and model numbers that differ from current models.