

Prepared (Subject resp) XMRDMFI Dmitry Filyushin		No. 19/1543-ANA 901 37 Uen		
Approved (Document resp) BDGSGHDD [Hans Fernqvist]	Checked	Date 2018-05-07	Rev C	Reference

SS7 CAF Call Control Replaced

Contents

1	Overview	2
1.1	Description	2
2	Procedure	2

Prepared (Subject resp) XMRDMFI Dmitry Filyushin		No. 19/1543-ANA 901 37 Uen		
Approved (Document resp) BDGSGHDD [Hans Fernqvist]	Checked	Date 2018-05-07	Rev C	Reference

1 Overview

Note: This alarm is deprecated.

1.1 Description

The notification is issued when a call control has been replaced with a new bind request, for example a new user ID is being used.

Major type	193
Minor type	1586564180
MO Class	N/A
Specific Problem	SS7 CAF Call Control Replaced
Severity	SEVERITY_MINOR
Additional Text	Call Control Replaced

The possible causes are as follows:

- A new user application bound to ISUP module.

2 Procedure

This notification does not need any remedial actions. To find out new user ID check the SS7 CAF trace file. The alarm parameters include the old call control and the new call control. Additional information about SS7 CAF trace file can be found in SS7 CAF Troubleshooting Guide.