

Prepared (Subject resp) XNATTOL Nataliya Tolokontseva		No. 4/1543-ANA 901 37 Uen		
Approved (Document resp)	Checked	Date 2016-09-22	Rev B	Reference

SS7 CAF Remote Processor Outage

Contents

1	Overview	2
1.1	Description	2
2	Procedure	2

Prepared (Subject resp) XNATTOL Nataliya Tolokontseva		No. 4/1543-ANA 901 37 Uen		
Approved (Document resp)	Checked	Date 2016-09-22	Rev B	Reference

1 Overview

1.1 Description

The alarm is issued when the Remote Processor is unavailable.

Major type	193
Minor type	1586564104
MO Class	N/A
Specific Problem	Remote Processor Outage
Severity	SEVERITY_WARNING
Notification class ID	193.24209.1541
Required SS7 Stack alarm mask	5 (MTPL3)
Additional Text	Remote Processor Outage

The possible causes are as follows:

- The remote end of the signaling link became temporarily unavailable.

2 Procedure

If this alarm occurs frequently, the load on the links should be reduced by either adding additional links or by changing the routing priorities. Additional information about how to change configuration of links can be found in Signaling Manager User Guide.

If the alarm is not cleared follow instructions in SS7 CAF Troubleshooting Guide.