

CIC Restarted

Cloud Execution Environment

OPERATING INSTRUCTIONS

Copyright

© Ericsson AB 2016–2018. All rights reserved. No part of this document may be reproduced in any form without the written permission of the copyright owner.

Disclaimer

The contents of this document are subject to revision without notice due to continued progress in methodology, design and manufacturing. Ericsson shall have no liability for any error or damage of any kind resulting from the use of this document.

Trademark List

All trademarks mentioned herein are the property of their respective owners. These are shown in the document Trademark Information.



Contents

1	Introduction	1
1.1	Alert Description	1
1.2	Prerequisites	2
2	Procedure	3
2.1	Actions	3



CIC Restarted



1 Introduction

This instruction concerns the handling of an alert that does not require intervention.

1.1 Alert Description

The CIC Restarted alert is issued by the Managed Object (MO) CIC.

The alert is issued if one of the following conditions apply:

- The periodic supervision algorithm detects that one of the virtual Cloud Infrastructure Controllers (vCICs) has failed the availability test three consecutive times, and following that, it passes the test and becomes available again within five minutes.
- Or a previously unknown vCIC passes the availability test for the first time.

The severity of the alert is WARNING.

The following is the consequence for the node if the alert is not solved:

- If two vCICs become unavailable, the third vCIC is not operational.

The alert attributes are listed in Table 1.

Table 1 Alert Attributes

Attribute Name	Attribute Value
Major Type	193
Minor Type	2031701
Managed Object Class	CIC
Managed Object Instance	Region=<name_of_the_region>, CeeFunction=1, CtrlDomain=1, CIC=<name_of_the_vCIC_host>
Specific Problem	CIC Restarted
Event Type	other (1)
Probable Cause	m3100Indeterminate(0)
Additional Text	N/A
Severity	WARNING (6)



1.2 Prerequisites

This section provides information on the documents, tools, and conditions that apply to the procedure.

1.2.1 Documents

Not applicable.

1.2.2 Tools

No tools are required.

1.2.3 Conditions

Before starting this procedure, ensure that the alert was not issued due to ongoing planned maintenance.

If the alert was issued due to ongoing planned maintenance, no further actions are required.



2 Procedure

This section describes the procedure to follow when this alert is received.

2.1 Actions

When this alert is issued, the vCIC has already recovered. Normally, no further actions are necessary. In this case, exit this procedure.

If the alert is issued for the same vCIC frequently, perform the following:

1. Collect troubleshooting data as described in the [Data Collection Guideline](#).
2. Consult the next level of maintenance support.
Further actions are outside the scope of this instruction.
3. The job is completed.