



Motorola Solutions, Inc.

MOTOTRBO® SLR 5000 Repeater

Professional Commercial Radios
(PCR) & Accessories

Date: 4/9/2016

R01.02.00 Release Codeplug Update

MOTOTRBO SLR 5000 Repeater

Table of Contents

Overview 3

Definitions..... 3

What’s new in the Release..... 4

Product Versions 4

Known issues in product release 4

Closed issues in product release 4

Overview

"Product Versions" provides a list of related MOTOTRBO product software revision levels used to test system performance for the MOTOTRBO® SLR 5000 Repeater.

"Known Issues in Product Release" details the known MOTOTRBO SLR 5000 product issues which remain outstanding at the time of this release of software to the field.

Known product issues are divided into two categories:

- New issues opened against new functionality in this release
- Latent issues (product issues also existing in earlier releases)

Please refer to the "Known issues in product release" section of this document for details on the open issues as of this release.

"Resolved Issues in Product Release" details the known MOTOTRBO SLR 5000 product issues which have been resolved in this release of software to the field.

Definitions

A known issue is a problem that is currently unresolved (open).

A closed or resolved issue is a problem that has been repaired and no longer should occur in the product after upgrading to the new product version.

The risk and workaround aspects are included in the release note description for overall assessment of the problem.

What's new in the Release

SLR 5000 Repeater Firmware

Description: This release updates the SLR 5000 UHF repeater codeplug to improve the receiver performance under specific conditions. These improvements are limited to the following conditions: operation between 463.5MHz-465MHz and in extreme cold (-30C to -10C). Under these conditions without the updates, customers may experience audio degradation.

Models Impacted:

Region	Model Supported
NA	SLR 5700

* Only UHF1 models are affected.

Product Versions

Listed below are the MOTOTRBO elements, with a reference to the released version of software, used to validate the product operation.

MOTOTRBO Product	Version Supported in Release
SLR 5000 Repeater Firmware	R01.02.00
SLR 5000 Repeater Codeplug	R01.01.10

Items highlighted in BLUE indicate new release.

Known issues in product release

None

Closed issues in product release

NA