



# **MOTOTRBO® System Release Notes**

## **Professional Commercial Radios (PCR) & Accessories**

**Version: M2021.01.04**

**Date: September 17, 2021**

**North America Region**

## **Contents**

Product Versions

Resolved issues in product release

## Product Versions

Listed below are all MOTOTRBO Product types with a reference to the released version of software:

Notes: From M2020.01 onwards, only products (i.e. MOTOTRBO radios, repeaters and CMSS) which are either in warranty or under a service contract are entitled to software update.

Software Update Management (SUM) was introduced with the R2.10 system release and provides products with built-in intelligence to determine if they are eligible to accept a software update. Products on prior releases must therefore be upgraded to an R2.10 system release and be eligible to accept a software update before they can be upgraded to M2020.01 onwards.

Cancelled products that are still under a service contract at time of cancellation will be entitled to the software update in line with the Motorola Solutions Software Support Policy. Following cancellation only critical bug fixes will be tested for these products.

MOTOTRBO Product	Version Supported in Release
Repeater -SLR 1000, SLR 5700, SLR 8000	<b>R20.21.01.08</b>

## Resolved Issues In Product Release

Resolved issues are the known product problems that were reported in product releases, but have now been fixed or closed.

Defect ID	Release Introduced	Product	Headline
ENG_INFRA_PCR-11257	M2021.01.03	All SLR family repeaters	Repeater Web service default password issue