

MOTOTRBO™ System Release Notes Professional Commercial Radios (PCR)

Version: M2024.01.01

Contents

What's new in the Release

Product versions

Overview

Definitions

Known issues in product release

Resolved issues in product release

Cybersecurity

Important notes

New Upgrade Package Zip Format

Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2024 Motorola Solutions, Inc. All rights reserved.

What's new in the Release

Radio new features

There are no new radio features introduced with this release.

For specific CP100d and MOTOTRBO R7 radio revisions this is a "Motorola Factory Only" Release. For that reason, CP100d and MOTOTRBO R7 radio recovery package only is being made available, and there is no upgrade package for CP100d and MOTOTRBO R7 radios in the field.

The MOTOTRBO R2 upgrade package is only being made available to resolve issues in the field, and there are no new radio features. Please refer to the "Resolved Issues in Product Release" section.

Infrastructure/System new features

CMSS upgrade to RHEL 8.8 EUS

In order to keep up to date with recent operating system fixes, security enhancements and new features, the CMSS OS is being upgraded to Red Hat Enterprise Linux (RHEL) version 8.8 EUS.

Product Versions

Listed below are all MOTOTRBO Product types with a reference to the released version of software:

Notes: From M2020.01 onwards, only products (i.e. MOTOTRBO radios, repeaters and CMSS) which are either in warranty or under a service contract are entitled to software update.

Software Update Management (SUM) was introduced with the R2.10 system release and provides products with built-in intelligence to determine if they are eligible to accept a software update. Products on prior releases must therefore be upgraded to an R2.10 system release and be eligible to accept a software update before they can be upgraded to M2020.01 onwards.

Canceled products that are still under a service contract at time of cancellation will be entitled to the software update in line with the Motorola Solutions Software Support Policy. Following cancellation only critical bug fixes will be tested for these products.

MOTOTRBO Product	Version Supported in Release			
Subscriber – MOTOTRBO R2 Subscriber – MOTOTRBO R7 Subscriber – MOTOTRBO - CP100d Subscriber – MOTOTRBO - XPR 4000/6000 Series	R02.24.01.3002(NEW - Recovery Only) R02.24.01.1003 (NEW - Recovery only) R01.24.01.3000 (NEW) Canceled.			
Option Board - MOTOTRBO 2.0 (incl SL Series) Option Board - MOTOTRBO - XPR 4000/6000 Series	Canceled. Canceled.			
Repeater - XPR 8380 / XPR 8400 Repeater - MTR 3000 Repeater - SLR 1000, SLR 5000, SLR 8000	R20.24.01.03 R20.24.01.03 R20.24.01.03			
XRC 9000 / 9100 Controller	R02.100.05.1036_1695			
XRT 9000 / 9100 Gateway	R02.100.05.1036_1695			
XRI 9100 Interconnect	R02.100.05.1030			

Network Manager (merged with XRC / XRI packages)	R02.100.05.1030			
Network Manager Connection Tool	R02.100.05.1030			
XRT Configuration Tool	R02.100.05.1030			
CPCPS	Canceled.			
Paradise MPT1327 GOB CPS (not supported on Rajang series)	R02.00.05			
CPS 2.0	2.146.122.0			
Radio Management	2.146.122.0			
RadioCentral Client	2.146.123.0			
CPS	CPS V16.0 Build 828			
Tuner	V24.1 Build 2			
RDAC	V24.1 Build 2 (NEW)			
AirTracer	V11.0 Build 39			
Device Discovery and Mobility Service (DDMS)	R24.01.0005			
Multi Channel Device Driver (MCDD)	Canceled			
MNIS Data Gateway	R24.01.0023			
MNIS Status Agent	R22.03.01			
MOTOTRBO Motopatch	Canceled			
Capacity Max ESU Launchpad	DESU_LP-R17.18.10.56-02.rhel.iso			
Capacity Max System Server Installer Software Image	PC435S0El000202010.iso (NEW)			
MNIS Voice and Radio Command (VRC) Gateway	PCR-MNIS_24.01.01.00-12 (NEW)			
Capacity Max ESU	ESU-PCR_24.01.25.02-44 (NEW)			
Capacity Max Trunk Controller	Cmxtc-pcr_20.24.01.10-42 (NEW)			
Capacity Max System Advisor	UEM-PCR_24.01.01.36-00 (NEW)			
System Design Tools	Version 06.09			
Sensor Management Tool	R01.00.01			

3rd Party Applications	Version Supported in Release		
GW3-TRBO	2.17.3.73		
Avtec VP Gate	5.3.0.41		
Avtec Scout Console/Scout Manager	5.3.0.54		
Avtec VPGate Advanced Radio Support w/Encryption	5.3.0.16		
Avtec Data Management Services - Scout Central Distributor	5.3.0.20		
SmartPTT PLUS	SmartPTT-PLUS-9.14.0.62		
TRBOnet PLUS	TRBOnet Plus 6.2.1.7429		
ConSEL PLUS	ConSEL PLUS v7r69.3		

ETSI DMR Specification	Version Supported in Release
TS 102 361-1: the DMR air interface protocol	v2.6.1

Motorola Solutions confidential - do not redistribute - PartnerEmpower member, customer, and prospective customer use only.

Page 4

TS 102 361-2: the DMR voice and generic services and facilities	v2.5.1
TS 102 361-3: the DMR data protocol	v1.3.1
TS 102 361-4: the DMR trunking protocol	v1.7.1 ~ 1.12.1

- 1. The feature sets supported in the release are compliant with the versions of ETSI DMR standard specifications listed above. Though in DMR Tier 3 there have been some things changed to existing features that are not backwards compatible, Capacity Max complies to the newer versions so may not always work with other manufacturer's infrastructure on older versions.
- 2. The Capacity Max System Advisor (SA) client is not accessible for the System View, Grid View and Alarm Details view if the Java version 8u211 or newer is used on the PC where SA client resides in. Downgrading the Java to any version between and including 8u181 and 8u201 will work fine.
- 3. USB 3.0 port is not supported for the repeater upgrade. With R2.8.0 and newer repeater release, the recommendation is to use USB 2.0 port on the PC or connect repeater via USB 2.0 hub when upgrading the repeater via USB.
- 4. For CMSS (Capacity Max System Server),
 - a. Access to the MSI MyView portal to download MOTOTRBO M2024.01.01 Capacity Max System Server SW Upgrade as software iso image
- 5. For the PC used for CMSS upgrade only from M2022.01 and M2022.03 to M2024.01 or M2024.01.01 (note: upgrading from 2023.01 to M2024.01 or M2024.01.01 does not require ESU-LP)
 - a. If ESU-LP is required, order (1) T8486A, MOTOTRBO Capacity Max System Server SW Update Launch Pad which contains the ESU LP software files on a DVD.
 - b. Alternatively, for customers with access to the MSI MyView portal, you can order (1) T8483B, MOTOTRBO Capacity Max System Server SW Update Launch Pad where you will receive an e-mail with a unique link to access/download the ESU LP application files from the MyView portal. The T8483B will require an e-mail address at time of order.
 - c. Please refer to the section "Capacity Max System Upgrade from M2022.01, M2022.03, M2023.01 or M2024.01 to M2024.01.01" of Capacity Max System Release Upgrade Guide for additional details. It is available on the Learning Experience Portal (LXP).
 - d. NOTICE: The DVD (T8486A) can take 2-3 weeks for delivery while the downloadable file via the MyView portal (T8483B) is generally available within a week. Please plan ahead and take the delivery times into consideration before scheduling your upgrade
 - e. The ESU Launchpad About page describes the target CMSS versions that it supports to ensure the appropriate ESU Launchpad version is ordered along with the CMSS upgrade installation files.

Overview

This section details the known MOTOTRBO product issues which remain outstanding at the time of this release of software to the field.

Known product issues are divided into two categories:

- Known issues contained within the current release
- Resolved Issues that have now been fixed within the current release

Definitions

A known issue is a problem that is currently unresolved (open). The risk and workaround aspects are included in the release note description (Known Issues) for overall assessment of the problem.

A closed or resolved issue is one that has been repaired and no longer should occur in the product after upgrading to the new product version.

Known Issues in Product Release

Infrastructure Impact

Issue Number: **UEM-7280 / MTN-0063-24**System/Products: Capacity Max/System Advisor

Description: After upgrading Java to 8u411 (released on 16 April) on Windows,

System View and Grid View in SA client are not working. Blank page is

displayed instead of System View

Workaround: For issue avoidance if any of previous releases of Java is installed,

then do not install the latest one (8u411). If Java 8u411 is installed for recovery, uninstall it using the Control Panel. For further details please refer to MTN-0063-24 Capacity Max System Advisor System View and

Grid View are not opening on Java 1.8.411

Issue Number: **UEM-7269**

System/Products: Capacity Max/System Advisor

Description: System Advisor java app is not starting properly with some errors

visible in console log

Workaround: Try starting SA again

Resolved Issues in Product Release

Resolved issues are the known product problems that were reported in product releases, but have now been fixed or closed. Following are the issue tracking number and issue descriptions that have been resolved in this release.

Device Impact

Issue Number: **PCR_SUB-46286 / INC0000304706**

System/Product: MOTOTRBO R2

Description: Under very rare circumstances after turning the radio off, it may not be

possible to turn the radio back on.

For further details please refer to MTN-0071-24

Holdings, LLC and are used under license. All other trademarks are the property of their respective owners. ©2024 Motorola Solutions, Inc. All rights reserved.

Cybersecurity

Motorola Solutions, Inc. (MSI) has delivered a PCR MOTOTRBO 2024.01 release. MSI development and operations teams continually make security updates as needed based on evaluated threats, determine protective measures, create response capabilities, and promote compliance. MSI interacts with and participates in several US and international security organizations, such as U.S. Department of Homeland Security's National Cybersecurity & Communications Integration Center (NCCIC), National Institute of Standards and Technology (NIST), The 3rd Generation Partnership Project (3GPP), Telecommunications Industry Association (TIA), European Telecommunications Standards Institute (ETSI), Digital Mobile Radio (DMR) Security standardization, and others. Standards from the aforementioned organizations can map to security controls in international standards such as Information System Standards (ISO / IEC 27001).

The PCR MOTOTRBO 2024.01 system release includes enhancements to security based on the National Vulnerability Database and industry standards:

- Ongoing vulnerability management remediation based on network scanning security tools
- Ongoing Software Lifecycle Management improvements (3rd party software)

In addition to ongoing releases for security updates, MSI has a Bug Submission Program for external entities to disclose to MSI possible security vulnerabilities or issues. Motorola Solutions encourages researchers to use the PGP key when sending sensitive information via email. Please send all security vulnerability reports to security@motorolasolutions.com.

Open Source Software Legal Notice

This media, software or hardware ("Product") obtained from Motorola Solutions, Inc. ("Motorola Solutions") may include Motorola Solutions' Software, Third Party Software (defined below), and/or Open Source Software (defined below).

The object code or source code (collectively, the "Software") included with the Product is the exclusive property of Motorola Solutions or its licensors, and any use is subject to the terms and conditions of one or more agreements in force between the purchaser of the Motorola Solutions Product or licensee of the Motorola Solutions Software and Motorola Solutions. SOFTWARE IS PROTECTED BY U.S. COPYRIGHT LAWS AND INTERNATIONAL LAWS AND TREATIES. UNAUTHORIZED COPYING, DISTRIBUTION OR OTHER USE OF THIS PRODUCT IS STRICTLY PROHIBITED. ANY DISTRIBUTION OR USE NOT SPECIFICALLY APPROVED BY MOTOROLA SOLUTIONS IS STRICTLY PROHIBITED.

Motorola Solutions' Software is subject to the commercial terms and conditions entered into with Motorola Solutions, any other use is strictly prohibited. Commercial Software licensed for redistribution by Motorola Solutions ("Third Party Software") is subject to the terms and conditions in force between Motorola Solutions and the licensor of the Third party Software. The terms and conditions governing the usage of Third Party Software may be part of the agreement entered into by the purchaser of the Product with Motorola Solutions or separate Third Party Software license agreement(s) included with the Product.

Software provided by Motorola Solutions which is covered by a publicly available license governed solely under Copyright law, whereas the complete terms and obligations of such license attach to a licensee solely through the act of copying, using and/or distribution of the licensed Software, such

Page 7

obligations often include one or more of attribution obligations, source code distribution obligations, copyleft obligations, and intellectual property encumbrances is referred to herein as "Open Source Software". The use of any Open Source Software is subject to the licenses, terms and conditions of the commercial agreement in force between the purchaser of the Product and Motorola Solutions as well as the terms and conditions of the corresponding license of each Open Source Software package. If there is a conflict between the terms and conditions of any commercial agreement and the terms and conditions of the Open Source Software license, the applicable Open Source Software license will take precedence. Copies of the licenses for the included Open Source Software as well as their attributions, acknowledgements, and software information details, are listed below. Motorola Solutions is required to reproduce the software licenses, acknowledgements and copyright notices as provided by the authors and owners, thus, all such information is provided in its native language form, without modification or translation.

Use of any Software is subject to acceptance of the corresponding terms associated with the Software and by using the Software you agree you have reviewed the terms and agreed to be bound by said terms.

To obtain a copy of the source code for the Open Source Software with source code distribution obligations, you may send a formal request in writing to:

Motorola Solutions, Inc.
Open Source Software Management
2000 Progress Parkway
Schaumburg, IL 60196 USA.

In your request, please include the Motorola Solutions Product name and version, along with the Open Source Software specifics, such as the Open Source Software name and version.

The source code for the Open Source Software included by Motorola Solutions may be residing on the product's installation media provided with the Product or on supplemental Product media. Please reference and review the entire Motorola Solutions Open Source Software "Legal Notices" and any corresponding "End User License Agreement" provided with the Product or the commercial agreement under which the Product was purchased for details on the availability, location and method for obtaining source code. Further, depending on the license terms of the specific Open Source Software, source code may not be provided. Please reference and review the entire Motorola Solutions Open Source Software "Legal Notices" and "End User License Agreement" to identify which Open Source Software packages have source code provided or available.


MOTOROLA, MOTOROLA SOLUTIONS and the Stylized M Logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license. All other trademarks are the property of Motorola Solutions, Inc. or their respective owners. All rights reserved.

RM Access Control Feature Note

Important note for customers who DO NOT need to use RM Access Control:

After upgrading an existing RM deployment to version 2.134.77.0 or later, there are some necessary steps to take to ensure normal operation, otherwise, users may not have access to the security keys and Radio View operations that they had prior to the upgrade.


1. After performing the upgrade the user should open the RM Server Utility App on the machine that hosts the RM Server.



From the User Authorization tab, with the Roles radio button selected, delete any unnecessary roles that may have been created prior to the upgrade, leaving only the RM Administrator and RM Client User roles.



3. For users that do not wish to use the Access Control features at this time, select the Users radio button and ensure that each user that will be accessing RM remotely has both RM Administrator and RM Client User roles assigned to them.




4. This completes the necessary steps for users that do not wish to use the Access Control features. The RM Server Utility can be closed at this point. Users should be able to use the RM Configuration Client to connect to the RM Server and perform normal operations.

New Upgrade Package Zip Format

Starting from M2022.03, MSI will start to release the MOTOTRBO firmware upgrade package in zip format. Below are the instructions on how to install the firmware upgrade package.

- 1. Create a new folder of your choice in the C:\drive. We will use "Packages" as an example.
- 2. Download zip file to C:\Packages
- 3. Extract All



5. Run the .exe file

program files	10/11/2022 1:45 PM	File folder	
	10/1/2014 11:41 AM	Configuration sett	22 KB
MOTOTRBO 2.0 R0222021000_222213 Portable Update Packages.msi	8/30/2022 11:09 AM	Windows Installer	663 KB
MOTOTRBO_2.0_R0222021000_222213_Portable_NA.exe	8/30/2022 11:09 AM	Application	1,269 KB
Setup.ini	8/30/2022 11:09 AM	Configuration sett	6 KB

6. To save space, the folder can be deleted after successful installation