

# **IMPRES Field Programmer SW V1.12 (Charger V4.2 / Display V1.7 / Prgrm V1.1) Customer Release Notes**

**For any questions, please contact Customer Resources at 1-800-927-2744.**

## **I. Enhancements**

Motorola Solutions has made enhancements to the software used in IMPRES vehicular chargers from V4.1 to V4.2 to improve robustness of charger to battery communications to minimize the possibility of battery data corruption in the APX TIA batteries during momentary disconnect of the charger contacts. **NOTE: This change does not apply to APX Multi Unit Desktop Chargers (NNTN7064 – NNTN7077 & 7086), APX Single Unit Chargers (NNTN7079 – NNTN7085, 7261) or APX Dual Unit Desktop chargers (NNTN7584, NNTN7585, NNTN7586 & NNTN7593)**

## **II. Corrections**

None.

## **III. Known Issues**

None.

## **IV. FAQ's**

1. What's the difference between V4.1 and V4.2?  
**Software V4.2 improved robustness of charger to battery communications for Vehicular Chargers.**
2. How do I upgrade the software in my charger?  
**You can refer to the IMPRES Field Programmer User Manual for the detailed steps.**
3. How do I find the software version in my charger?  
**The software version programmed in the charger at the time of manufacture can be found printed on the label at the bottom of the charger. See pictures below for reference:**




Figure 1: XTS Multi-Unit charger



Figure 2: XTS Single Unit charger