

MLC 8000 Software Synchronization Notes:

The MLC 8000 product functionality is enabled by having 2 pieces of software; the firmware in the device itself, and the programming software (Configuration Tool or CT). There is a need to marry these 2 pieces of code for a given system release to keep certified combinations in synch.

Please make sure to utilize the correct combination of host code and CT to prevent any undesired effects.

As of July 2017, the most current combinations are as follows:

System Release 7.16 – July 2016 (added transmitter steering and Windows 10 compatibility)

Firmware: R06.00.30

Configuration Tool: R01.07.20

System Release 7.15 – January 2015

Firmware: R05.00.13

Configuration Tool: R01.06.11

MLC Box Release – July 2014 (added 64-port capability)

Firmware: R04.00.34

Configuration Tool: R01.05.26

System Release 7.14 – January 2014

Firmware: R03.00.13

Configuration Tool: R01.04.16

System Release 7.13 – October 2013 (added continuous voting)

Firmware: R02.00.42

Configuration Tool: R01.03.26

System Release 7.12 – April 2012

Firmware: R01.00.70

Configuration Tool: R01.02.50