

RPB50_INTERFACE

```

MOTOROLA Radio Service Software                      12 Dec 90
Radius M214                                           12:29
Version R07.00.00
-----
Model:    D04LRA7PA5AK                               Coded Squelch
Serial:   778RPTRX02                                UHF
Software: 009                                         2 W
-----
CHANGE/VIEW:RADIO WIDE:CONN CON                     SCREEN PRINT UTILITY
-----

                ACCESSORY CONNECTOR CONFIGURATION
                -----
INTERNAL ACCESSORY: NONE EXTERNAL ACCESSORY:          REMOTE    CUSTOM: YES

  PIN      FUNCTION      DATA      DEBOUNCE    ACTIVE
  NUMBER   # DESCRIPTION DIRECTION          LEVEL
  4         01 NULL      OUTPUT         NO         LOW
  6         00 NULL      INPUT          NO         LOW
  8         05 PL/DPL & CSQ Det  OUTPUT         NO         LOW
  9         00 NULL      INPUT          NO         LOW
  12        07 CSQ Detect  OUTPUT         NO         LOW
  14        10 I/O Mic Off Hook INPUT          YES        HIGH

POWER-UP DELAY: 4.301 SEC

```

"RECEIVER" RADIO

```

MOTOROLA Radio Service Software                      12 Dec 90
Radius M214                                           12:29
Version R07.00.00
-----
Model:    D44LRA7PA5AK                               Coded Squelch
Serial:   778FNUI750                                UHF
Software: 009                                         35 W
-----
CHANGE/VIEW:RADIO WIDE:CONN CON                     SCREEN PRINT UTILITY
-----

                ACCESSORY CONNECTOR CONFIGURATION
                -----
INTERNAL ACCESSORY: NONE EXTERNAL ACCESSORY:          REMOTE    CUSTOM: YES

  PIN      FUNCTION      DATA      DEBOUNCE    ACTIVE
  NUMBER   # DESCRIPTION DIRECTION          LEVEL
  4         01 NULL      OUTPUT         NO         LOW
  6         06 Tx PL Inhibit  INPUT          NO         LOW
  8         00 NULL      INPUT          NO         LOW
  9         00 NULL      INPUT          NO         LOW
  12        01 NULL      OUTPUT         NO         LOW
  14        10 I/O Mic Off Hook INPUT          YES        HIGH

POWER-UP DELAY: 4.301 SEC

```

"TRANSMITTER" RADIO