



KS-19717 TAPE PRINTER OPERATING PROCEDURES

1. GENERAL

1.001 This addendum supplements Section 030-342-301, Issue 3. The added pages must be inserted in the section in accordance with the filing instructions above.

1.002 This addendum is issued to add trouble-shooting information in Table C and to make minor

corrections. This addendum does not affect the Equipment Test List.

5. TROUBLE-SHOOTING

The following change applies to Part 5 of the section:

Table C—revised

Attachments:

Page 1 dated April 1973, revised
Page 2 dated April 1973, reissued
Page 7 dated April 1973, revised
Page 8 dated April 1973, revised