

197- AND 198-TYPE SWITCH BANKS PIECE-PART DATA AND REPLACEMENT PROCEDURES

1. GENERAL

1.001 This addendum supplements Section 030-705-806, Issue 10. Place this pink sheet ahead of Page 1 of this section.

1.002 This addendum is issued for the following reasons:

1. To correct the part number of the 1/4-inch 12-Point double-end box wrench
2. To change the part number of the 555A wrench.

This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 4, 3.01 under TOOLS, change the 514A 1/4-inch 12-Point double-end box wrench to 541A 1/4-inch 12-Point double-end box wrench.

2.002 On Page 4, 3.01 under TOOLS, change the 555A 3/16-inch Hex single-end socket wrench to 476A 3/16-inch Hex offset socket wrench.

2.003 On Page 6, 3.09, change the 555A wrench to 476A wrench.

2.004 On Page 7, 3.16, change the 555A wrench to 476A wrench.

2.005 On Page 12, 3.38, change the 555A wrench to 476A wrench.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement