

RECORDER

KS-19326 L1

PIECE-PART DATA AND REPLACEMENT PROCEDURES

1. GENERAL

1.001 This addendum supplements Section 034-358-801, Issue 2. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is reissued to revise instructions for obtaining replacement parts (1.04).

1.003 Issue 1 of this addendum was issued for the following reasons:

- (a) To revise instructions for obtaining service and parts from the manufacturer (1.05)
- (b) To delete a redundant item from List of Recommended Spare Parts (2.03)
- (c) To correct a reference on Fig. 17.

2. CHANGES TO SECTION

ISSUE 1 CHANGES

2.001 On Page 1, change 1.05 to read as follows.

1.05 When parts or service is required, the user should contact the Regional Quality Management

Engineer in accordance with standard engineering complaint procedures in Section 010-700-010.

2.002 On Page 3, (2.03), delete last item in list as follows:

760-1715 Roller Shaft 2

2.003 On Page 18, Fig. 17, reference in upper right corner to read: (See Fig. 18).

ISSUE 2 CHANGES

2.004 On Page 1, change 1.05 to read as follows:

1.05 Piece parts and subassemblies should be ordered from:

CONRAC Corporation
32 Fairfield Place
West Caldwell, New Jersey 07006
Contact: Mr. W. E. Gaffney
Phone: 201-575-8000 Ext. 203
Refer to Contract No. G95270B
If night service is required, call Area Code 201-575-8165.

Give complete information on what is needed.

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement