

OPERATORS CHAIRS

METAL TYPE

REPLACEMENT PARTS, REPLACEMENT PROCEDURES, AND MINOR REPAIRS

1. GENERAL

1.001 This addendum supplements Section 065-100-802, Issue 13. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued to add a replacement procedure for the spindle cover. This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 11, paragraph 5.03, change the first two sentences to read as follows: The

only piece parts to be replaced in the field are the seats, backrests, floor glides, and spindle covers. See Fig. 7 and 10 for piece-part information.

2.002 On Page 13 following (f) add the following:

5.08 To replace the spindle cover (Fig. 10), disassemble the chair as outlined in 5.07(a) through (d), replace the defective spindle cover with a new KS-20751, Detail 39, and reassemble the chair per 5.07(f).

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement