

PACIFIC TEL.  
NUMERICAL INDEX – DIVISION 069  
MISCELLANEOUS METHODS

1. GENERAL

1.01 This appendix supplements the A.T.&T. Numerical Index and lists:

All Pacific Co. issued practices.

Long Lines practices Standard for use in the Pacific Co.

A.T.&T. practices NOT STANDARD for Pacific Co. use. (See A.T.&T. index for issue number.)

1.02 A bullet (●) indicates an item that has been added or changed since the previous issue of the index.

1.03 A square (□) indicates a cancelled item.

	Section	Issue	Subject
• App. 1	069-000-000PT	N	Numerical Index
Add.	069-110-811LL	A	Wiring and Cable – Reinforcement of Cable Forms
App. 1	069-120-801PT	B	Distributing Frame Cross-Connections – General
App. 2	069-120-801PT	A	Distributing Frame Cross-Connections Using Intercepting Connectors
App. 1	069-120-811PT	A	Bradley Insulation Strippers – Description And Use
	069-120-901PT	A	Party Line Grouping Block – Connections
	069-130-811		NOT STANDARD
	069-130-811PT	B	Method of Connecting Wires to Split Terminals

	Section	Issue	Subject
#□	069-190-902PT	A	Series Circuits – Distributing Frame Cross Connections
	069-199-900PT	A	Inspection – Locating And Clearing AC Unbalances
App. 1	069-310-801PT	A	Salvaging and Disposing of Precious Metal Contact Material
Add.	069-310-802PT	A	Relays (Non-Wire Spring Type), 197-Type Switches, Crossbar Switches, And KS-13835 (AMA) Reader – Replacing Contacts
	069-392-901PT	A	Reconditioning Central Office And PBX Equipment Damaged by Water
	069-393-901PT	A	Distributing Frames – Cleaning
App. 1	069-501-801PT	A	197- And 198-Type Switches And Associated Banks, Commutators, And Wipers – Cleaning Requirements And Procedures – Abrasive Cleaning Using CMC Microscrub

#Information now contained in Section 002-582-903PT.