

EQUIPMENT TEST LIST

B.S.P.	I S S	TEST OR REQT.	EQUIPMENT AND WORK DESCRIPTION	CLASS	FREQ.	JOB NO.
169-713-301	2		RECTIFIERS KS-19212 L3 AND L4			
(Page 4)		4.02	Float and Charge Voltage Adjustments	MW	12M	
		4.03	Voltage Rise for Constant Current Adjustment	MW	12M	
		4.04	Current-Limiting Circuit Checks	MW	12M	
		4.05	Fuse Alarm Tests	MW	12M	
		4.06	AR1 and AR2 Ammeter Relay Settings for Plant Signaling	MW	12M	
		4.07	SCR Check	MW	6M	
169-713-312	2		RECTIFIERS KS-19212 L11 AND L12			
(Page 4)		4.02	Check Fuse	MW	6M	
		4.03	Check SCRs	MW	6M	
		4.04	Current Limit Circuit Checks	MW	12M	
169-715-501	1		RECTIFIER KS-19213 TYPE SWITCH, FUSE ASSEMBLY, AND BUS BARS TESTS AND INSPECTIONS			
(Page 4)		3.01	CHG or BAT DISC Switch Inspection	MW	6M	
		3.02	CHG or BAT DISC Switch Electrical and Thermal Test	MW	12M	
		3.03	CHG or BAT DISC Switch Cleaning and Lubrication Procedure	MW	12M	
169-723-301	3		RECTIFIERS KS-19215 L3 AND L4			
(Page 6)		4.02	Check High and Low Current-Limiting Circuit	MW	12M	
169-730-301	1		RECTIFIERS KS-19790 L11 AND L12			
(Page 3)		4.08	Check Shutdown by Blown DC OUTPUT ALM and OUTPUT CAPACITOR (F1 ALM and F2 ALM) FUSES	MW	12M	
169-709-301	2		RECTIFIERS KS-19211 L2 AND L7			
(Page 3)		4.02	Clean Ventilating Passages	MW	3M	
		4.03	Contactors and Relay Check	MW	12M	
		4.04	Voltage-Limiting Circuit Check	MW	12M	
		4.05	Current-Limiting Circuit Check	MW	12M	
		4.06	Minimum Load Signal Check	MW	12M	
		4.07	Maximum Load Signal Checks	MW	12M	
169-717-301	2		RECTIFIERS KS-19213 L5 and L9			
(Page 5)		4.01	Clean Ventilating Passages	MW	3M	
		4.03	Fuse Alarm Check	MW	12M	
		4.04	Power Failure Alarm Check	MW	W	
		4.05	Float Voltage Check	MW	M	

